

ELD2-RS Series DC Servo Drive

User Manual





Foreword

Thank you for purchasing Leadshine ELD2-RS series DC Servo drives. This manual will provide information on the ELD2-RS series servo products regarding product safety & specifications, installations & wiring, tuning & problem diagnostics.

Please contact us at tech@leadshine.com if you need further technical support.

Incorrect operation may cause unexpected accident, please read this manual carefully before using product.

- ♦ We reserve the right to modify equipment and documentation without prior notice.
- ♦ We won't undertake any responsibility with any customer's modification of product and the warranty of product will be canceled at the same time.

Safety Precautions

Please read the safety instructions carefully before using the products and pay attention to the safety signs.

Danger	Might incur death or serious injury			
Caution	Might cause injury to operating personals or damage to equipment			
Warning	Might cause damage to equipment			
<u></u>	Hot surface. Do not touch			
	Protective Earth			

Safety instructions



- ✓ The design of the product is not to be used in mechanical system which may incur health hazard.
- ✓ Users should be aware of the product safety precautions during design and installations of the equipment to prevent any unwanted accident.

Upon receiving



- The use of damaged or faulty product(s) is prohibited.
- Please refer to item checklist. If the labels don't match, please do not install.



Transportation



- ✓ Please provide storage and transportation under protected conditions.
- ✓ Do not stack the products too high up to prevent toppling.
- ✓ The product should be packaged properly during transportation,
- ✓ Do not hold the product by the cable, motor shaft or encoder while transporting it.
- ✓ The product should be protected from external forces and shock.

Installation



Servo drive and Motor:

- ✓ Do not install around combustibles to prevent fire hazard.
- ✓ Avoid vibration and impact.
- ✓ Do not install products that are damaged or incomplete.

Servo drive:

- ✓ Please install in electrical cabinet with sufficient protection from outside elements.
- ✓ Reserve sufficient gap as per the installation guide.
- ✓ Make sure to have good heat sinking.
- ✓ Avoid dust, corrosive gas, conductive object or fluid and combustibles.

Servo Motor:

- ✓ Make sure installation is tight to prevent it from loosening.
- ✓ Prevent fluid from leaking into motor and encoder.
- ✓ Protect motor from impact to avoid damaging encoder.
- ✓ Motor shaft should not bear the load beyond the limits as specified.

Wiring



- Participate installation personals should have sufficient training in product installation safety.
- ✓ Please power off and wait for 10 minutes to make sure a full discharge of electricity.
- ✓ Servo drive and motor must be connected to ground.
- ✓ Connect the cables only after servo drive motor installed correctly
- ✓ Make sure the wires are properly managed and insulation layer is not torn to prevent electrocution.



- Wiring must be correctly connected to prevent damage to product(s)
- ✓ Servo motor U, V, W terminal should be connected correctly and NOT connected directly to an AC power supply.
- ✓ Capacitor, inductor or filter shouldn't be installed between servo motor and servo drive.
- ✓ Connecting wires or any non-heat resistant components should be put near to heat sink of the servo drive or motor.
- ✓ The flyback diode which is connected in parallel to output signal DC relay must not be connected in reverse.



Tuning and running



- ✓ Make sure the wirings of servo drive and servo motor are installed and fixed properly before powering on.
- ✓ On the first time tuning of the product, it is recommended to run unloaded until all the parameter settings are confirmed to prevent any damage to the product or machine.

Usage



- ✓ Please install an emergency stop button on machine to stop operation immediately if there is an accident.
- ✓ Please make sure machine is stopped before clearing an alarm.
- ✓ Servo drive must be matched with specified motor.
- ✓ Frequent restart of the servo system might incur damage to the product.
- ✓ Servo drive and motor will be hot to touch shortly after power off. Please be careful.
- ✓ Modification(s) to servo system is prohibited.

Error Handling



- ✓ Please wait for 5 minutes after powering off for the electricity to be fully discharged before uninstalling the cables.
- ✓ Participate maintenance personals should have sufficient training in maintenance and operation of this product series.



- ✓ Please handle the error before clearing an alarm.
- ✓ Keep away from machine after a restart upon alarm. Mechanical axis might suddenly move. Such hazard should be prevented during the utilization of the product.

Model Selection



- Rated torque of the servo motor should be higher than continuous designated torque when fully loaded.
- ✓ Load inertia ratio of the motor should be lower or equals to recommended value for specified models
- ✓ Servo drive must be matched with specified motor.



Warranty Information

Available for

Leadshine overseas warranty only covers Leadshine DC servo products that are obtained through Leadshine certified sales channel outside of China.

Warranty claim

- All Leadshine DC servo products (Servo drives and motors) overseas enjoy **18-month** warranty period.
- Due to unforeseen circumstances in different sales regions around the globe, we recommend users to seek technical support from directed sales channel as any warranty claim or repair services may be required.
- Please be informed that any maintenance/repair work that is outside of the warranty claim conditions might incur some charges and to be confirmed before product(s) is being sent in.
- The duration required for maintenance work to be done is to be confirmed after initial check-up but we reserve the right to prolong the repair duration if needed.
- Discontinued products within warranty period will be replaced with a product of similar specifications.

Steps to warranty claim

- 1. Visit Leadshine global site www.leadshine.com to look for local certified sales channel.
- 2. Contact designated sales channel to check if any fee might incur. May include repair fee, spare part cost or shipping cost.

Circumstances where warranty claim is not available

- Damage/Loss due to occurrence of natural or man-made disaster such as fire, flood or earthquake.
- Installation or wiring error
- If there is any modification done to the product
- Warranty label on products is torn or not existing
- Not a product bought from Leadshine certified global network of retailers/distributors.

Before warranty claim

- Please backup device parameters before any repair work/warranty claim. Leadshine and Leadshine certified retailers/distributors will not be held responsibilities for any data loss.
- If available, please send product back in original packaging or make sure it is well packaged to prevent any damage to the product during shipping.

Leadshine Technology Co.,Ltd. and its certified sales channel reserved the final right of the interpretation of the warranty information.



TABLE OF CONTENT

CHAPTER 1 INTRODUCTION	9
1.1 Product Introduction	9
1.2 Model Number Structure	10
1.2.1 Servo Drive	10
1.2.2 Servo Motor	10
1.3 Servo Drive Technical Specifications	11
1.4 Servo Drive Ports and Connectors	12
1.5 Motor Ports and Connectors	13
CHAPTER 2 INSTALLATION & WIRING	14
2.1 Servo Drive Installation	14
2.1.1 Servo drive installation environment	14
2.1.2 Servo drive dimension	14
2.2 Servo Motor Installation	17
2.2.1 Installation conditions	
2.2.2 Precautions during installation	17
2.3 ELD2-RS Wiring Diagram	18
2.4 Servo Drive Ports	19
2.4.1 CN1 I/O Signal Port	21
2.4.2 CN3/CN4 Power supply & Regenerative Resistor Port	24
2.4.3 CN5 Modbus RS485 Communication Port	24
2.4.4 CN6 Safe Torque Off (STO) Port	25
2.4.5 CN7 RS232 Tuning Port	26
2.4.6 CN9 Logic Circuit Power Supply Port	27
2.4.7 ENC Encoder Feedback Port	27
2.4.8 ID spin dial RSC	
2.4.9 Baud rate/Terminal resistor switch SW	
2.5 Cable Selection	29
2.5.1 Motor Power Cable	29
2.5.2 Motor Encoder Cable	32
2.5.3 Motor Brake Cable	34
2.5.4 Drive Communication Cable	34
2.5.4 Tuning Cable	34
2.6 Regenerative Resistor Selection	35
CHAPTER 3 PARAMETER	39
3.1 Parameters list	39
3.2 Parameters description	
3.2.1 [Class 0] Basic Settings	
3.2.2 [Class 1] Gain adjustments	56
3.2.3 [Class 2] Vibration suppression	
3.2.4 [Class 3] Velocity/Torque control	66



3.2.5 [Class 4]I/O Monitoring Settings	73
3.2.6 [Class 5] Extension Settings	80
3.2.7 [Class 6] Other settings	84
3.2.8 [Class 7] Factory settings	88
3.2.9 [Class 8] PR control parameters	89
3.2.10 [Class 9] PR control path parameters	98
3.2.11 [Class B] Status Parameters	114
CHAPTER 4 CONTROL MODE	117
4.1 Position control	118
4.1.1 Pulse input and direction settings	119
4.1.2 Electronic Gear Ratio	120
4.1.3 Position command filter	121
4.1.4 Encoder feedback output	123
4.1.5 Positioning completed INP signal output	124
4.2 Velocity control mode	125
4.2.1 Velocity command input control	126
4.2.2 Velocity command acceleration/deceleration	128
4.2.3 Velocity reached signal AT-SPEED output	129
4.2.4 Velocity coincidence V-COIN signal output	130
4.2.5 Zero Speed Clamp	130
4.3 Torque control	131
4.3.1 Torque command input control	132
4.3.2 Torque velocity limit	134
4.3.3 Torque limit (TL-SEL)	134
4.4 Hybrid Control Mode	135
CHAPTER 5 APPLICATION CASE	136
5.1 Gain Adjustment	136
5.2 Inertia ratio identification function	138
5.3 Auto gain adjustment	141
5.4 Manual gain adjustment	
5.4.1 Parameters adjustment under different control modes	148
5.4.2 Gain switching	150
5.5 3rd gain switching	154
5.6 Model following control	155
5.7 Feedforward gain	156
5.7.1 Velocity feedforward	156
5.7.2 Torque feedforward	157
5.8 Friction compensation function	159
5.9 Safety Functions	
5.9.1 Max. motor rotational speed limitation	
5.9.2 Max. duration for motor to stop after disabling	
5.9.3 External brake deactivation output signal BRK-OFF	
5.9.4 Servo stopping mode	
5.9.5 Emergency stop function	163



5.10 Vibration Suppression	165
5.10.1 Mechanical resonance suppression	165
5.10.2 End vibration suppression	169
5.11 Multiturn absolute encoder	170
5.11.1 Parameters setting	170
5.11.2 Read absolute position	171
5.11.3 Absolute Encoder Related Alarm	173
5.12 Regenerative resistor settings	174
CHAPTER 6 MODBUS COMMUNICATION	175
6.1 Communication connection	175
6.2 Modbus RS485 communication parameters and ports	176
6.3 Modbus Protocol	178
6.3.1 Read Data 0x03	178
6.3.2 Write single data 0x06	178
6.3.3 Write multiple data 0x10	179
6.3.4 Reply error	180
6.3.5 Auxiliary function parameters	180
6.3.6 Alarm info parameters	181
6.4 Frequently occurred issues and solutions with RS485 communication	182
CHAPTER 7 PR MODE	185
7.1 PR functions introduction	186
7.2 Control parameters	187
7.3 PR Motion	189
7.3.1 Homing	189
7.3.2 Position limit and emergency stop	194
7.3.3 JOG	194
7.3.4 Path motion	195
7.4 PR Control	198
7.4.1 PR module in Motion Studio	198
7.4.2 Physical I/O	200
7.4.3 485 communication	202
7.4.4 Path trigger	204
7.5 PR motion	205
7.5.1 Trigger using physical I/O	205
7.5.2 Control using 485 communication	206
CHAPTER 8 WARNING AND ALARM	208
8.1 Servo Drive alarm indicator	
8.2 Servo drive alarm	
8.3 Alarm Handling	
8.4 Alarm clearing	221
8.4.1 Servo Drive Alarm Clearing	221
CONTACT US	222



Chapter 1 Introduction

1.1 Product Introduction

ELD2-RS Series DC Servo Product is a new DC servo drivers and motors product range that we have proudly developed at Leadshine Technology Co.,Ltd. This product series provides more in demanded functionalities and control.

ELD2-RS Series DC Servo Drive comes with voltage rating of 24 to 70VDC and current rating from 5A up to 60A (max. peak current: 180A). This series supports Modbus communication protocol in addition to pulse + direction input control. Using RS485 protocol, multi axis network of ELD2-RS series servo drive can be realized and controlled from 1 single master device.

ELD2-RS series DC Servo Drive also comes with new ELVM series DC servo motors with 17-bit magnetic absolute and 2500-line incremental encoder which offers better accuracy and stability.

First time user of the ELD2-RS series servo products can refer to this manual for more information on this product that cannot be covered in this short introduction. For further technical support, please do contact us or any local Leadshine certified retailers on Contact Us page.




1.2 Model Number Structure

1.2.1 Servo Drive

ELD2	- <u>RS</u>	<u>7030</u>	<u>B</u>
1	2	3	4

No.	Description					
1	Series No.	ELD2: DC Servo Drive Series				
2	Communication protocol	RS: Pulse train + Modbus RTU CAN: CANopen + Analogue				
3	Power Rating	7020: 24-70VDC, rated current 20A 7030: 24-70VDC, rated current 30A				
4	Туре	B: Holding brake output Blank: Without holding brake output				

1.2.2 Servo Motor





1.3 Servo Drive Technical Specifications


ELD2-RS series	RS7005B RS7010B		RS7015B		RS7020B	RS7030B
Rated Current (Arms)	5	10	15		20	30
Peak Current (Arms)	21	42	4	15	80	90
Dimension(mm)	118*79.5*25.5			175*100.5*33		
ELD2-RS series	RS7040B			RS7060B		
Rated Current (Arms)	40			60		
Peak Current (Arms)			180			
Dimension(mm)	194*103*41					
Logic Power Supply	24VDC			DC DC		
Safe Torque Off (STO)		STO	SIL3			

Main power supply	24~70VDC					
Direct Drive Holding Brake	Yes					
Drive mode	SVPWM sinusoidal wave drive					
Velocity regulation ratio	5000:1					
Electronic gear ratio	1 ~ 32767/1 ~ 32767					
Matching encoders	Hall signal UVW + ABZ or RS485 encoder(Tamagawa protocol)					
Input	2 pulse differential 5V Digital input (Pulse+direction) 4 configurable NPN/PNP 24V Digital Inputs: DI3-DI6 1. Servo enabled (SRV-ON) 2. Positive limit switch (POT) 3. Negative limit switch (NOT) 4. Clear Alarm (A-CLR) 5. Gain switching (GAIN) 6. Deviation counter clearing (CL) 7. Command pulse prohibition(INH) 8. Crossover frequency input switching(DIV1) 9. Internal command velocity selection(INTSPD) 10. Zero speed clamp(ZEROSPD) 11. Velocity sign(VC-SIGN) 12. Torque sign(TC-SIGN) 13. Emergency Stop (E-STOP)					
13. Emergency Stop (E-STOP) 1 holding brake output; 2 configurable single-ended NPN/PNP 24V, 8mA digital outputs 1. Alarm (ALARM) 2. Servo ready (SRDY) 3. External brake off (BRK-OFF) 4. Positioning completed (INP1) 5. Reached velocity(AT-SPEED) 6. Zero speed position (ZSP) 7. Velocity coincidence (V-COIN) 8. Position command (P-CMD) 9. Velocity command (V-CMD) Current circuit error, DC bus overvoltage, DC bus undercurrent, overcurrent on IPM, motor overload, regenerative resistor overlod disconnected, encoder initialization error, encoder data error, exposition deviation, overspeed, I/O configuration error, EEPROM saving CRC checksum error, positive/negative position limit valid						
Indicator light	alarm input valid Red & Green LED					
maicator ngiit	INCU & GICCHILLD					




Tuning Software	Motion Studio 2			
Motion Studio 2	Configure parameters for current, position and velocity loop. Parameter uploading using .lsr parameter files. Drive and motor data monitoring using oscilloscope.			
Communication Port	RS-232 , 1 : 1 ; RS485 , 0 : N (0≤N≤127), Modbus protocol			
Load-Inertia		Smaller tl	nan 20 times motor inertia	
Dimension	175*100*27 mm 118*79.5*25.5 mm			
	Storage condition	Avoid direct sunlight. Keep away from heat generating devices, dust, oil, corrosive liquid/gas and places with strong vibration or high humidity. Prohibit combustible gas and conductive material waste.		
Environmental	Temperature	-20°C ~ +45°C (Please allow air circulation if >45°C)		
requirements	Storage temperature	- 20°C ~	+ 65℃	
	Humidity	40—90%RH (Condensation free)		
	Installation	Vertical ar	nd level to ground	

1.4 Servo Drive Ports and Connectors








1.5 Motor Ports and Connectors

ELVM Series DC Servo Motor






Chapter 2 Installation & Wiring

2.1 Servo Drive Installation

2.1.1 Servo drive installation environment


Temperature	Storage: -20~+65°C (Condensation free); Installation: -20~+45°C (Please allow air circulation if >45°C)			
Humidity Under 90%RH (Condensation free)				
Altitude	Up to 1000m above sea level			
Atmospheric pressure	86 ~ 106kPa			
Vibration	Less than 0.5G (4.9m/s2) 10-55Hz (non-continuous working)			
Atmospheric	No corrosive gas, combustibles, dirt or dust.			
IP ratings	IP20			

2.1.2 Servo drive dimension






Dimension 2: ELD2-RS7015B/7020B/7030B




Dimension 3: ELD2-RS7040B/7060B





Space requirement for installation

- 1. Please install the drive vertical to ground.
- 2. Please ensure optimal heat dissipation with enough room (>50mm) between each drives or to surrounding. It is recommended to install cooling fans for drives to achieve optimal performance.



Please refer to the diagram above for a visual guide on how to properly install the DC servo drives.



2.2 Servo Motor Installation

2.2.1 Installation conditions

Installation conditions may affect the lifespan of a motor

- Please keep away from corrosive fluid and combustibles.
- If dusty working environment is unavoidable, please use motors with oil seal.
- Please keep away from heat source.
- > If motor is used in enclosed environment without heat dissipation, motor lifespan will be short.
- Please check and clean the installation spot before installation.

2.2.2 Precautions during installation

Installation method

Install horizontal to ground

Make sure power cable and encoder cable is facing downwards to make sure fluid doesn't leak into the ports.

Install vertical to ground

Please use a motor with oil seal when paired with a reducer to prevent reducer oil from leaking into the motor.

Oil- and waterproofing

- Do not submerge motor/cable under oil/water
- Please use a motor with oil seal when paired with a reducer to prevent reducer oil from leaking into the motor.
- > If there is an unavoidable fluid leakage near the motor, please use motor with better IP ratings.
- Make sure power cable and encoder cable is facing downwards to make sure fluid doesn't leak into the ports.
- Avoid the usage of motor in water/oil leaking prone environment.

Cable under stress

- Do not the bend the cable especially at each ends of the connectors.
- Make sure to not let the cables be too tight and under tremendous stress especially thinner cables such as signal cables.

Connectors

- Please to remove any conductive foreign objects from the connectors before installation
- The connectors are made of resin. May not withstand impact.
- Please hold the driver during transportation, not the cables.
- Leave enough "bend" on the connector cables to ensure less stress upon installation.


Encoder & coupling

- During installation or removal of coupling, please do not hit the motor shaft with a hammer as it would cause damage to internal encoder.
- Please make sure to centralize the motor shaft and coupling, it might cause damage to motor or encoder due to vibration.
- Please make sure axial and radial load is within the limits specified as it might affect the lifespan of the motor or cause damage to it.



2.3 ELD2-RS Wiring Diagram

ELD2-RS Wiring Diagram




- Make sure data transferring cables are as short as possible. Keep CN1 cable under 3m and CN2 cable under 10m. Use shielded double winding cables to cut down on electromagnetic interference.
- > If the load for DO is an inductive load such as a relay, please install freewheeling diodes on both ends of the load in parallel. Please keep in mind that if the diode is connected in reverse, it might cause damage to the drive.
- Use non-fuse breaker (NFB) to cut off power supply to the drive in case of emergency.




2.4 Servo Drive Ports

ELD2-RS 7005/7010/7015B/7020B/7030B





ELD2-RS 7040B/7060B



Connector	Label			
CN1	I/O signal port			
CN3	Motor power output (U, V, W, PE)			
CNS	Main Power Supply (DC+, DC-)			
CN4	Regenerative resistor port (RB+, RB-)			
CN5	Modbus Communication port			
CN6	Safe Torque Off (STO) port			
CN7	RS232 tuning port			
CN9	Logic circuit power supply port			
ENC	Motor encoder feedback			
SW	Baud rate/Terminal resistor switch			
RSC	ID spin dial			




2.4.1 CN1 I/O Signal Port

Diagram	CN	Pin	Signal	Description	
		1	DI1+	D 1 1 1 1 1 1 1 1 1	
			2	DI1+	Pulse input, differential, 500kHz
		3	DI2+	Direction input differential FOOLIL	
1		4	DI2+	Direction input, differential, 500kHz	
		5	COM_IN	Common DI	
		6	DI3	Servo enable	
		7	DI4	Alarm clear	
		8	DI5	Homing switch	
		9	DI6	Position limit	
		10	A1+	Analog input, voltage -10-+10VDC,	
	CN1	11	A1-	resistance 20kΩ	
		12	A+	Encoder signal A sustaut	
		13	A-	Encoder signal A output	
		14	B+	Encoder signal B output	
	20	15	B-	Encoder signal B output	
		16	BR+	Holding brake output positive and negative	
19 20		17	BR-	terminal, max current output: 1A	
		18	DO1	Alarm output, current output <100mA	
		19	DO2	Servo ready, current output <100mA	
		20	COM_OUT	Common output	




Pulse input

Pulse and direction input only support 5V signal. Please connect in series a resistor with resistance of $2k\Omega$ for 24V pulse and direction signal. Please refer to the following differential and single-ended input wiring diagrams.



Following tables show pulse input signal and sequences. When a 2-phase input is used, 4 times of pulse frequency is \leq 500kHz.

Pulse input mode	Counter clockwise	Clockwise	Settings
Pulse signal	PUL TITLE		Command pulse + direction




Symbol	Differential input	Single-ended input
t _{ck}	>2µs	>5μs
t _h	>1µs	>2.5µs
t _l	>1µs	>2.5µs
t _{rh}	<0.2μs	<0.3μs
t _{rl}	<0.2μs	<0.3µs
t _s	>1µs	>2.5µs
t _{qck}	>8µs	>10μs
t _{qh}	>4µs	>5μs



t _{ql}	>4µs	>5µs
t _{qrh}	<0.2μs	<0.3µs
t _{qrl}	<0.2μs	<0.3µs
t _{qs}	>1µs	>2.5µs


I/O Signal Wiring Diagram

- 1. DI3-DI6 supports NPN and PNP configuration. Recommended to use an external control signal power s supply of 12-24VDC.
- 2. DO1-DO2 are single ended outputs with 100mA current output that supports NPN and PNP configuration. Recommended to use an external power supply of 24VDC. If the load is an inductive load such as a relay, please install freewheeling diodes on both ends of the load in parallel. If the diode is connected in reverse, it might cause damage to the driver.



CN1 control signal cable selection


To ensure I/O signal to not be affected by electromagnetic interference, a **shielded cable** is recommended for this application.



Cables for different analogue signals should be using isolated shielded cable while cables for digital signals should be shielded twisted pair cable. Cables for CN1 connectors should be 24-28AWG in diameter.



2.4.2 CN3/CN4 Power supply & Regenerative Resistor Port



		CN3					
Port	Pin	Signal	Description				
	1	DC+	DC Dower Supply positive and pogative terminals				
	2	DC-	DC Power Supply positive and negative terminals				
CN3	3	PE					
CIVS	.N3 4	U	II V W DE terminals for motor				
	5	V	U, V, W, PE terminals for motor				
	6	W					
CN4	1	DC+	DC Dawar Supply positive and pogative terminals				
CN4	2	DC-	DC Power Supply positive and negative terminals				

2.4.3 CN5 Modbus RS485 Communication Port

Port	Diagram	Pin	Signal	Label
		1	RS485+	Modbus positive terminal
		3	RS485+	Modbus negative terminal
	10 8 6 4 2	5	GND	Power supply ground
CN5	9 7 5 3 1	Others	NC	10 pins are not applicable

Note:

- Molex 55959-1030 Connector Header (Driver side)
- Molex 51353-1000 10-pin rectangle connector 1pcs for each axis (Provided)
- Molex 56134-9000 female terminal reel 10pcs for each axis (Provided)



2.4.4 CN6 Safe Torque Off (STO) Port

Port	Diagram	Pin	Signal	Description	Remarks			
		1	5V	24v power supply	Connect to SF1 and SF2			
		2	GND	Reference ground	when not in use. Do not use to supply power.			
	4 STO1- STO 1 negative inp 5 STO2+ STO 2 positive inp 7 8 6 STO2- STO 2 negative in	1	3	STO1+	STO 1 positive input			
CN6		STO1-	STO 1 negative input	When SF1 = OFF or SF2 =				
					5	STO2+	STO 2 positive input	OFF, STO is enabled.
				6	STO2-	STO 2 negative input		
		External monitoring	When SF1 = OFF and SF2					
		8	EDM-	differential double	, ,	, ,	= OFF,EDM = ON	

Introduction to Safe Torque Off (STO)

Function: Cut off motor current supply physically (through mechanical means)

STO module (CN6 connector) consists of 2 input channels. It cuts off the motor current supply by blocking of PWM control signal from the power module. When the motor current is cut off, the motor will still move under inertia and stops gradually.

The STO function is set up ready to be used by factory default. Please remove STO connector if it is not needed.


STO functional principle

STO module cuts off the motor current supply and stops motor gradually by blocking of PWM control signal from the power module through 2 isolated circuits. When a STO error occurs, the actual status of STO can be determined by the EDM status feedback.

ST01 Input Status	ST02 Input Status	EDM Output Status	PWM control signal	Alarm code
ON	ON	OFF	Normal	-
ON	OFF	OFF	Blocked	Er 1c2
OFF	ON	OFF	Blocked	Er 1c1
OFF	OFF	ON	Blocked	Er 1c0



STO wiring diagram



- Please take precautions when enabling STO functions as servo drive will lose control over the motion of the motor. Motor might dropped under gravitational pull (vertically mounted load) or moved when external forces are applied to it. Alternatively, motor with holding brake can be chosen.
- > STO is not meant to cut off the power supply of the servo drivers and motors completely. Please power off and wait for a few minutes before starting maintenance work.
- It is recommended to use an isolated power supply for STO signal input as any current leakage might cause STO malfunction.

2.4.5 CN7 RS232 Tuning Port

Port	Diagram	Pin	Signal
		1	5V
CN7	3	2	TX
	2	3	GND
		4	RX

ELD2-RS Series DC Servo Drive can be connected to Motion Studio for parameters tuning and data monitoring using **CABLE-PC-1**.



2.4.6 CN9 Logic Circuit Power Supply Port

Port	Diagram	Pin	Signal	Description
CN9		1	24V	24V positive terminal
	1 2	2	GND	24V negative terminal

ELD2-RS7040B/7060B dual-axis DC servo drives include an optional logic circuit power supply port. When main power supply is cut, logic circuit power supply port can be connected to realize:

- 1. Partially functional DSP
- 2. Holding brake output to directly control the status of motor holding brake

2.4.7 ENC Encoder Feedback Port

Port	Diagram	Pin	Signal	Description
		1	Foil Shield	Encoder cable shielded layer
		2	HU	Motor Hall U signal
		3	HW	Motor Hall W signal
		4	HV	Motor Hall V signal
		5	VCC	5V power supply from driver. Only
	12	6	GND	for encoder
ENC		7	EZ+/D+	Encoder Z phase positive signal / encoder positive terminal
		8	EZ-/D-	Encoder Z phase negative signal / encoder negative terminal
		9	EB+	Encoder B phase positive signal
		10	EB-	Encoder B phase negative signal
		11	EA+	Encoder A phase positive signal
		12	EA-	Encoder B phase negative signal

For motors with 17-bit magnetic encoder (battery kit connected externally for absolute encoder):

Port	Diagram	Pin	Signal	Description
		1	Frame	Protective earth
		5	VCC5V	Power Supply 5V
ENC		6	GND	Power Supply Ground
		7	SD+	SSI Data+
	Leaturnanches L	8	SD-	SSI Data-



Note:

- Molex 55959-1230 Connector Header (Driver side)
- Molex 51353-1200 12-pin rectangle connector 1pcs for each axis (Provided)
- Molex 56134-9000 female terminal reel 12pcs for each axis (Provided)

2.4.8 ID spin dial RSC

	Diagram	Bit	Modbus address	Bit	Modbus address
		0	Pr5.31 Default : 16	8	8
		1	1	9	9
	23 4 5	2	2	Α	10
RCS	188	3	3	В	11
	8 C D &	4	4	С	12
		5	5	D	13
		6	6	E	14
		7	7	F	15

2.4.9 Baud rate/Terminal resistor switch SW

Diagram	Function		Pr6.33	SW4	Baud rate	SW1	SW2	Terminal resistor	SW3
6	Motor direction	CCW (Default)	0	OFF	Pr5.30 Default: 9600	OFF	OFF	Disconnect ed	OFF
		CW		ON	19200	ON	OFF		
	Modbus high bit address	Spin dial	8	OFF	38400	OFF	ON	Connected	ON
1 🛄		16+Spin dial		ON	57600	ON	ON		




2.5 Cable Selection


2.5.1 Motor Power Cable

Motor winding power cable


- Wire length available: 0.5m, 1.5m, 3m, 5m, 7m and 10m.
- Connectors type available: SP21 connector
- Please contact Leadshine sales team or any Leadshine certified local retailers for any customized needs.












Recommended wire diameter for each drive

Drive	Wiring diameter (mm²/AWG)					
Dilve	DC+, DC-	UVW	PE			
ELD2-RS7005B	AWG18	AWG18	AWG18			
ELD2-RS7010B	AWG16	AWG16	AWG16			
ELD2-RS7015B	AWG14	AWG16	AWG16			
ELD2-RS7020B	AWG12	AWG12	AWG12			
ELD2-RS7030B	AWG10	AWG10	AWG10			
ELD2-RS7040B	AWG8	AWG8	AWG8			
ELD2-RS7060B	AWG6	AWG6	AWG6			




- **Grounding**: Grounding wire should be thicker. Ground PE terminal of servo drive and servo motor together with resistance $<100 \Omega$.
- Connect a line filter to power supply to reduce electromagnetic interference.
- Please install a fuseless circuit breaker to cut off power supply in time when the driver fails.

2.5.2 Motor Encoder Cable






For ELVM series motors with 130 flange size







2.5.3 Motor Brake Cable



2.5.4 Drive Communication Cable



2.5.4 Tuning Cable





2.6 Regenerative Resistor Selection

The use of regenerative resistor

When the motor opposes the direction of rotation as in deceleration or vertical axis escalation, part of the regenerative energy will be delivered back to the driver. This energy will first be stored in internal capacitors of the driver. When the energy stored in the capacitors reach the maximum capacity, a regenerative resistor is required the excessive energy to prevent over-voltage.

Calculation of regenerative resistance under normal operation

Steps:

- 1. Determine if driver comes with a regenerative resistor. If not, please prepare a regenerative resistor with resistance value higher than might be required.
- 2. Monitor the load rate of the regenerative resistor using front panel (d14). Set the driver on high velocity back and forth motions with high acceleration/deceleration.
- 3.Please make sure to obtain the value under following conditions: Driver temperature < 60°C, d14<80(Won't trigger alarm), Regenerative resistor is not fuming, No overvoltage alarm(Err120).

Pb(Regenerative power rating) = Resistor power rating x Regenerative load rate (%)

Please choose a regenerative resistor with power rating Pr about **2-4 times the value of Pb** in considered of harsh working conditions and some 'headroom'.

If the calculated Pr value is less than internal resistor power rating, external resistor is not required.

 $R(Max. required regenerative resistance) = (380^2 - 370^2)/Pr$

Problem diagnostics related to regenerative resistor:

- If driver temperature is high, reduce regenerative energy power rating or use an external regenerative resistor.
- If regenerative resistor is fuming, reduce regenerative energy power rating or use an external regenerative resistor with higher power rating.
- ➤ If d14 is overly large or increasing too fast, reduce regenerative energy power rating or use an external regenerative resistor with higher power rating.
- If driver overvoltage alarm (Er120) occurs, please use an external regenerative resistor with lower resistance or connect another resistor in parallel.

Please take following precautions before installing an external regenerative resistor.

- 1. Please set the correct resistance value in Pr0.16 and resistor power rating Pr0.17 for the external regenerative resistor.
- 2. Please ensure the resistance value is higher or equals to the recommended values in table 2-3. Regenerative resistors are generally connected in series but they can also be connected in parallel to lower the total resistance.
- 3. Please provided enough cooling for the regenerative resistor as it can reach above 100°C under continuous working conditions.
- 4. The min. resistance of the regenerative resistor is dependent on the IGBT of the regenerative resistor circuit. Please refer to the table above.



Theoretical selection of regenerative resistor

Without external loading torque, the need for an external regenerative resistor can be determined as the flow chart below







Diagram below shows the acceleration and deceleration cycle periods and the regenerative torque that occurs during the process.



Steps to calculate capacity of regenerative resistor

Steps	Calculation	Symbol	Formula
1	Servo system regenerative energy	E1	E1=(N+1)×J×V ² /182
2	Depleted energy from loss of load system during acceleration	E _L	$E_L = (\pi/60) \text{ V} \times T_L \times \text{tD}$ If loss is not determined, please assume $E_L = 0$.
3	Depleted energy due to motor coil resistance.	E _M	$E_M = (U^2/R) \times tD$ R= coil resistance, U = operating voltage If R is not determined, please assume $E_M = 0$.
4	Energy stored by internal DC capacitors	Ec	Please refer to table 2-5
5	Depleted energy due to regenerative resistance	Eĸ	E _K =E1-(EL+EM+EC), If loss is ignored, EK=E1-EC
6	Required power rating of regenerative resistor	Pr	Pr=E _k /(0.5×T)

Note:

- > 0.5 in the calculation for **Pr** represent 50% load rate of regenerative resistor.
- E1-EK: Energy(Joule) TL: Load torque(Nm)
 V: Motor velocity(rpm/min)
 Pr: Regenerative resistor power rating
 J: Rotor inertia (kgm²) T: Motor cycle time(s)
 N: Ratio of load inertia and rotor inertia



Internal capacitor capacity and rotor inertia

ELD2 Drives	Servo motor	Rotor Inertia (× 10 ⁻⁴ kg.m ²)	Max. regenerative energy stored in capacitor Ec(J)
750W (7020B)	ELVM8075V48FH-M17	1.5	2.26
1000W (7030B)	ELVM80100V48FH-M17	1.79	2.26

There are motors with low, medium and high inertia. Different motor models have different rotor inertia. Please refer to product catalogue for more information on rotor inertia. Please cut down 30%-40% of load rate if the product is used in harsh environment with less than ideal heat dissipation measures.

Recommended regenerative resistor specification for each drives

Drives	Resistance (Ω)	Power rating(W)	Min. Resistance(Ω)
ELD2-RS7005B	10	30	5
ELD2-RS7010B	10	50	5
ELD2-RS7015B	10	50	5
ELD2-RS7020B	10	100	5
ELD2-RS7030B	10	100/150	5
ELD2-RS7040B	10	150/200	5
ELD2-RS7060B	10	150/200	5

Note:

- 1. Use 10 Ω /100W resistor for test operation and make sure: Drive temperature d33<60 $^{\circ}$ C, dynamic brake is not in alarm mode (Braking rate d14<80), brake resistor is not overheated, drive has no overcurrent alarm.
- 2. If drive temperature is too high, increase power rating of regenerative resistor or reduce drive power.
- 3. If brake resistor is overheated, reduce drive power or use regenerative resistor with higher resistance.
- 4. If d14 is too high, reduce drive power or use regenerative resistor with higher resistance and power ratings.
- 5. External torque might cause regenerative energy to flow back into drive. During normal operation, torque output in the same direction as rotational direction but if external torque exists, directions might oppose and in this case, regenerative resistor with higher resistance may be required.



Chapter 3 Parameter

3.1 Parameters list

Valid mode:

P: Valid in position control mode

S: Valid in velocity control mode

T: Valid in torque control mode

PR: Valid in PR control mode

Activation:

"O" - Restart driver for parameter changes to be valid

"—" – Valid immediately

" Δ " – Valid when axis stops

"●"- Valid after re-enabling

[Class 0] Basic settings

	Dadio Settings		Antive	Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	Р	S	Т	Byte	Op.	485 Addr.
Pr0.00	Model-following bandwidth	1	Δ	0	ı	_	16bit	R/W	0x0001
Pr0.01	Control Mode Settings	0	0	0	0	0	16bit	R/W	0x0003
Pr0.02	Real time Auto Gain Adjusting	0x1	_	0	0	0	16bit	R/W	0x0005
Pr0.03	Real time auto stiffness adjusting	70	_	0	0	0	16bit	R/W	0x0007
Pr0.04	Inertia ratio	250	_	0	0	0	16bit	R/W	0x0009
Pr0.05	Command pulse input selection	0	0	0	ı	_	16bit	R/W	0x000B
Pr0.06	Command pulse polarity inversion	0	0	0	ı	_	16bit	R/W	0x000D
Pr0.07	Command pulse input mode	3	0	0	ı	_	16bit	R/W	0x000F
Pr0.08	1 st command pulse count per revolution	10000	0	o	_	_	32bit	R/W	0x0010 0x0011
Pr0.09	1 st command frequency divider/multiplier numerator	1	0	0	-	_	32bit	R/W	0x0012 0x0013
Pr0.10	1 st command frequency divider/multiplier denominator	1	0	0	-	_	32bit	R/W	0x0014 0x0015
Pr0.13	1st Torque Limit	350	_	0	0	0	16bit	R/W	0x001B
Pr0.14	Excessive position deviation	30	_	0	_	_	16bit	R/W	0x001D
Pr0.15	Absolute Encoder settings	0	0	0	0	0	16bit	R/W	0x001F
Pr0.16	Regenerative resistance	100	_	0	0	0	16bit	R/W	0x0021



			Activ	Val	id mo	ode	Communication mode			
Code	Label	Default	ation	Р	S	Т	Byte	Op.	485 Addr.	
Pr0.17	Regenerative resistor power rating	50	1	0	0	0	16bit	R/W	0x0023	
Pr0.18	Vibration suppression after stopping	0	ı	0	0	0	16bit	R/W		
Pr0.19	Micro-vibration suppression	0	-	0	0	0	16bit	R/W		
Pr0.20	External pulse valid edge settings	0	1	0	0	0	16bit	R/W		

[Class 1] Gain adjustment

[Class 1]	1] Gain adjustment Valid mode Communication m								
			Activ	Val	id mo	ode	Comm	unicati	
Code	Label	Default	ation	Р	S	Т	Byte	Ор.	485 Addr.
Pr1.00	1 st position loop gain	320	_	0	_		16bit	R/W	0x0101
Pr1.01	1st velocity loop gain	180	_	0	0	0	16bit	R/W	0x0103
Pr1.02	1st Integral Time Constant of Velocity Loop	310	_	0	0	0	16bit	R/W	0x0105
Pr1.03	1st velocity detection filter	15	_	0	0	0	16bit	R/W	0x0107
Pr1.04	1 st Torque Filter Time Constant	126	_	0	0	0	16bit	R/W	0x0109
Pr1.05	2 nd Position Loop Gain	380	_	0	_	_	16bit	R/W	0x010B
Pr1.06	2 nd velocity loop gain	180	_	0	0	0	16bit	R/W	0x010D
Pr1.07	2 nd Integral Time Constant of Velocity Loop	10000	_	o	o	0	16bit	R/W	0x010F
Pr1.08	2 nd velocity detection filter	15	_	0	0	0	16bit	R/W	0x0111
Pr1.09	2 nd Torque Filter Time Constant	126	_	0	0	0	16bit	R/W	0x0113
Pr1.10	Velocity feed forward gain	300	_	0	_	_	16bit	R/W	0x0115
Pr1.11	Velocity feed forward filter time constant	50	_	0	_	_	16bit	R/W	0x0117
Pr1.12	Torque feed forward gain	0	_	0	0	_	16bit	R/W	0x0119
Pr1.13	Torque feed forward filter time constant	0	_	0	0	_	16bit	R/W	0x011B
Pr1.14	2 nd gain switching	1	_	0	0	_	16bit	R/W	
Pr1.15	Position control gain switching mode	0	_	0	_	_	16bit	R/W	0x011F
Pr1.16	Position control gain switching delay time	50	_	0	0	_	16bit	R/W	
Pr1.17	Position control gain switching level	50	_	0	_	_	16bit	R/W	0x0123
Pr1.18	Hysteresis at position control switching	33	_	0	_	_	16bit	R/W	0x0125
Pr1.19	Position control switching time	33	_	0	_	_	16bit	R/W	0x0127
Pr1.35	Position command pulse filter time	8	0	0	_	_	16bit	R/W	0x0147
Pr1.37	Special function register	0		0	0	0	16bit	R/W	

[Class 2] Vibration Suppression

			Activ	Val	id mo	ode	Communication mode			
Code	Label	Default	ation	Р	S	т	Byte	Op.	485 Addr.	
Pr2.00	Adaptive filtering mode settings	0	_	0	0	_	16bit	R/W	0x0201	
Pr2.01	1st notch frequency	4000	_	0	0	0	16bit	R/W	0x0203	
Pr2.02	1st notch width	4	_	0	0	0	16bit	R/W	0x0205	
Pr2.03	1 st notch depth	0	_	0	0	0	16bit	R/W	0x0207	



			A ative	Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	Р	S	т	Byte	Op.	485 Addr.
Pr2.04	2 nd notch frequency	4000	_	0	0	0	16bit	R/W	0x0209
Pr2.05	2 nd notch width	4	_	0	0	0	16bit	R/W	0x020B
Pr2.06	2 nd notch depth	0	_	0	0	0	16bit	R/W	0x020D
Pr2.07	3 rd notch frequency	4000	_	0	0	0	16bit	R/W	0x020F
Pr2.08	3 rd notch width	4	_	0	0	0	16bit	R/W	0x0211
Pr2.09	3 rd notch depth	0	_	0	0	0	16bit	R/W	0x0213
Pr2.14	1 st damping frequency	0	_	0	-	I	16bit	R/W	0x021D
Pr2.16	2 nd damping frequency	0	_	0	_	_	16bit	R/W	0x0221
Pr2.22	Position command smoothing filter	0	Δ	0	_	_	16bit	R/W	0x022D
Pr2.23	Position command FIR filter	0	Δ	0	_	_	16bit	R/W	0x022F

[Class 3] Velocity / Torque Control

[31435 0]	Velocity / Torque Control		A	Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	Р	s	Т	Byte	Op.	485 Addr.
Pr3.00	Velocity internal/external switching	1	_	_	0	_	16bit	R/W	0x0301
Pr3.01	Velocity command rotational direction selection	0	ı	_	0	_	16bit	R/W	0x0303
Pr3.02	Velocity command input gain	500	_	_	0	0	16bit	R/W	0x0305
Pr3.03	Velocity command input inversion	0	_	_	0	_	16bit	R/W	0x0307
Pr3.04	1st speed of velocity setting	0	_	_	0	_	16bit	R/W	0x0309
Pr3.05	2nd speed of velocity setting	0	1	_	0		16bit	R/W	0x030B
Pr3.06	3rd speed of velocity setting	0	1	_	0		16bit	R/W	0x030D
Pr3.07	4th speed of velocity setting	0	_	-	0	_	16bit	R/W	0x030F
Pr3.08	5th speed of velocity setting	0	_	_	0	_	16bit	R/W	0x0311
Pr3.09	6th speed of velocity setting	0	_	_	0	_	16bit	R/W	0x0313
Pr3.10	7th speed of velocity setting	0	_	_	0	_	16bit	R/W	0x0315
Pr3.11	8th speed of velocity setting	0	_	_	0	_	16bit	R/W	0x0317
Pr3.12	Acceleration time settings	100	_	_	0	_	16bit	R/W	0x0319
Pr3.13	Deceleration time settings	100	_	_	0	_	16bit	R/W	0x031B
Pr3.14	Sigmoid acceleration/deceleration settings	0	0	_	o	_	16bit	R/W	0x031D
Pr3.15	Zero speed clamp function selection	0	_	_	0	_	16bit	R/W	0x031F
Pr3.16	Zero speed clamp level	30	_	-	0	_	16bit	R/W	0x0321
Pr3.17	Torque internal/external switching	0	_	-	_	0	16bit	R/W	0x0323
Pr3.18	Torque command direction selection	0	_	-	_	0	16bit	R/W	0x0325
Pr3.19	Torque command input gain	30	_	-	_	0	16bit	R/W	0x0327
Pr3.20	Torque command input inversion	0	_	_	_	0	16bit	R/W	0x0329
Pr3.21	Velocity limit in torque mode	0	_	_	_	0	16bit	R/W	0x032B
Pr3.22	Torque command	0	_	0	0	0	16bit	R/W	0x032D
Pr3.23	Zero speed delay time in velocity mode	0	_	_	0	_	16bit	R/W	0x032F
Pr3.24	Maximum motor rotational speed	0	_	0	0	0	16bit	R/W	0x0331
Pr3.25	Velocity offset – Logistics	0	_	_	_	0	16bit	R/W	
Pr3.26	Pulse deviation tolerance at disabling - Logistics	0	1	_	_	o	16bit	R/W	



			Active	Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	P	S	т	Byte	Op.	485 Addr.
Pr3.28	Position gain - Logistics	0	1	_	_	0	16bit	R/W	
Pr3.29	Delay time gain - Logistics	0	-	_	_	0	16bit	R/W	

[Class 4] I/O Monitoring Settings

[Class 4] I	/O Monitoring Settings								
			Activ	Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	ation	Р	S	Т	Byte	Op.	485 Addr.
Pr4.00	Input selection DI1	0x1	_	0	0	0	16bit	R/W	0x0401
Pr4.01	Input selection DI2	0x2	_	0	0	0	16bit	R/W	0x0403
Pr4.02	Input selection DI3	0x8	_	0	0	0	16bit	R/W	0x0405
Pr4.03	Input selection DI4	0x4	_	0	0	0	16bit	R/W	0x0407
Pr4.04	Input selection DI5	0x3	_	0	0	0	16bit	R/W	0x0409
Pr4.05	Input selection DI6	0x0	_	0	0	0	16bit	R/W	0x040B
Pr4.10	Output selection DO1	0x2	_	0	0	0	16bit	R/W	0x0415
Pr4.11	Output selection DO2	0x4	_	0	0	0	16bit	R/W	0x0417
Pr4.12	Output selection DO3	0x3	_	0	0	0	16bit	R/W	0x0419
Pr4.22	Analog input 1(AI-1) Zero drift settings	0	_	-	0	0	16bit	R/W	0x042D
Pr4.23	Analog input 1(AI-1) filter	0	_	-	0	0	16bit	R/W	0x042F
Pr4.24	Analog input 1(AI-1) overvoltage settings	0	_	-	0	0	16bit	R/W	0x0431
Pr4.31	Positioning complete range	50	_	0	0	0	16bit	R/W	0x0445
Pr4.32	Positioning complete output setting	50	_	_	0	_	16bit	R/W	0x0447
Pr4.33	INP positioning delay time	1000	_	_	0	_	16bit	R/W	0x0449
Pr4.34	Zero speed	150	_	0	0	0	16bit	R/W	0x044B
Pr4.35	Velocity coincidence range	0	_	0	0	0	16bit	R/W	0x044D
Pr4.36	Reached velocity	30	_	0	0	0	16bit	R/W	0x044F
Pr4.37	Holding brake deactivation delay time	0	_	0	0	0	16bit	R/W	
Pr4.38	Holding brake activation delay time	0	_	0	0	0	16bit	R/W	
Pr4.43	Emergency stop function	0	_	0	0	0	16bit	R/W	0x0457



[Class 5] Extension settings

[Olass of I	extension settings			Val	id mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	Р	S	Т	Byte	Op.	485 Addr.
Pr5.00	2nd pulse count per revolution	10000	O	0	_	1	32bit	R/W	0x0500 0x0501
Pr5.01	2nd Command frequency divider/multiplier numerator	1	O	0	_	-	32bit	R/W	0x0502 0x0503
Pr5.02	2nd Command frequency divider/multiplier denominator	1	O	0	_	-	32bit	R/W	0x0504 0x0505
Pr5.04	Driver prohibition input settings	0	_	0	0	0	16bit	R/W	0x0509
Pr5.06	Servo-off mode	0	_	0	0	0	16bit	R/W	0x050D
Pr5.08	DC bus voltage undervoltage	50	_	0	0	0	16bit	R/W	0x0513
Pr5.11	Servo braking torque setting	0	_	0	0	0	16bit	R/W	0x0519
Pr5.12	Overload level setting	0	_	0	0	0	16bit	R/W	0x051B
Pr5.13	Overspeed level setting	0	_	0	0	0	16bit	R/W	
Pr5.15	I/O digital filter	0	0	0	0	0	16bit	R/W	0x051F
Pr5.16	Alarm clearing input	0	_	0	_	_	16bit	R/W	
Pr5.17	Counter clearing input mode	3	_	0	_	_	16bit	R/W	0x0523
Pr5.20	Position unit settings	1	_	0	_	_	16bit	R/W	0x0529
Pr5.21	Torque limit selection	0	_	0	0	0	16bit	R/W	0x052B
Pr5.22	2nd torque limit	300	_	0	0	0	16bit	R/W	0x052D
Pr5.23	Positive torque warning threshold	0	_	0	0	0	16bit	R/W	0x052F
Pr5.24	Negative torque warning threshold	0	_	0	0	0	16bit	R/W	0x0531
Pr5.29	RS485 communication mode	0x5	_	0	0	0	16bit	R/W	0x053B
Pr5.30	RS485 communication Baud rate	4	_	0	0	0	16bit	R/W	0x053D
Pr5.31	RS485 axis address	1	_	0	0	0	16bit	R/W	0x053F
Pr5.32	Max. command pulse input frequency	0	_	0	_	ı	16bit	R/W	0x0541
Pr5.33	Communication cycle 1 for RS485	0	_	0	0	0	16bit	R/W	
Pr5.38	Warning auto clearing delay time	0	_	0	0	0	16bit	R/W	
Pr5.39	Enable duration time - Logistics	0	_	0	0	0	16bit	R/W	



[Class 6] Other Settings

			Activ		lid m	ode	Comm	unicati	on mode
Code	Label	Default	ation	Р	s	Т	Byte	Op.	485 Addr.
Pr6.01	Encoder zero position compensation	0	0	0	0	0	16bit	R/W	0x0603
Pr6.03	JOG trial run torque command	350		_	_	0	16bit	R/W	0x0607
Pr6.04	JOG trial run velocity command	30		0	0	0	16bit	R/W	0x0609
Pr6.05	Position 3rd gain valid time	0	_	0	_	_	16bit	R/W	0x060B
Pr6.06	Position 3rd gain scale factor	100	_	0	-	-	16bit	R/W	0x060D
Pr6.07	Torque command additional value	0	_	0	0	0	16bit	R/W	0x060F
Pr6.08	Positive direction torque compensation value	0	0 0 0		16bit	R/W	0x0611		
Pr6.09	Negative direction torque compensation value	0 —		0	0	0	16bit	R/W	0x0613
Pr6.11	Current response settings	100		0	0	0	16bit	R/W	0x0617
Pr6.12	Encoder zero position torque correction	50	_	0	0	0	16bit	R/W	
Pr6.14	Max. time to stop after disabling	500		0	0	0	16bit	R/W	0x061D
Pr6.20	Trial run distance	10		0	_	_	16bit	R/W	0x0629
Pr6.21	Trial run waiting time	300		0	_	_	16bit	R/W	0x062B
Pr6.22	No. of trial run cycles	5	_	0	-	-	16bit	R/W	0x062D
Pr6.25	Trial run acceleration	200		0	0	_	16bit	R/W	0x0633
Pr6.28	Shaft lock current raising time	0	_	0	0	0	16bit	R/W	0x0639
Pr6.29	Shaft lock duration time	0	_	0	0	0	16bit	R/W	0x063B
Pr6.30	Special function registry 1	0x0		0	0	0	16bit	R/W	
Pr6.34	Angle for zero electric angle searching	0	_	0	0	0	16bit	R/W	
Pr6.38	Special function registry 2	0x0	_	0	0	0	16bit	R/W	
Pr6.56	Blocked rotor alarm torque threshold	300	_	0	0	0	16bit	R/W	0x0671
Pr6.57	Blocked rotor alarm delay time	400	_	0	0	0	16bit	R/W	0x0673
Pr6.63	Absolute multiturn data upper limit	0	0	0	0	0	16bit	R/W	0x067F

[Class 7] Factory settings

			Activ	Val	id m	ode	Comi	nunicati	on mode
Code	Label	Default	ation	Р	s	Т	Byte	Op.	485 Addr.
Pr7.15	Motor model no.	0x8010							
Pr7.16	Encoder model no.	0x201							
Pr7.23	Encoder wiring extensions	150							
Pr7.28	Regenerative energy alarm window time	0							
Pr7.30	Under voltage point	20							
Pr7.31	Regenerative energy control mode	2							
Pr7.32	Regenerative energy vent on threshold	80							
Pr7.33	Regenerative energy control hysteresis	5							
Pr7.34	Over voltage point	90							
Pr7.48	Enabling delay time	500							
Pr7.50	Motor IIT time settings	0							



[Class 8] Pr-Control Parameters

			Activ	Val	id m	ode	Comm	unicati	on mode
Code	Label	Default	ation	P R	s	Т	Byte	Ор.	485 Addr.
Pr8.00	PR Control	0	_	0	_	_	16bit	R/W	0x6000
Pr8.01	Path count	16	_	0	_	_	16bit	R/W	0x6001
Pr8.02	Control Operation		_	0	_	_	16bit	R/W	0x6002
Pr8.06	Software positive limit H	0		0			16bit	R/W	0x6006
Pr8.07	Software positive limit (L)	0	_	0	_	_	16bit	R/W	0x6007
Pr8.08	Software negative limit H	0	_	0	_	_	16bit	R/W	0x6008
Pr8.09	Software negative limit (L)	0	_	0	_	_	16bit	R/W	0x6009
Pr8.10	Homing mode	0	_	0	_	_	16bit	R/W	0x600A
Pr8.11	Zero position H	0	_	0	_	_	16bit	R/W	0x600B
Pr8.12	Zero position (L)	0	_	0	_	_	16bit	R/W	0x600C
Pr8.13	Home position off set H	0	_	0	_	_	16bit	R/W	0x600D
Pr8.14	Home position off set (L)	0		0	_	_	16bit	R/W	0x600E
Pr8.15	High homing velocity	200	_	0	_	_	16bit	R/W	0x600F
Pr8.16	Low homing velocity	50	_	0	_	_	16bit	R/W	0x6010
Pr8.17	Homing acceleration	100	_	0	_	_	16bit	R/W	0x6011
Pr8.18	Homing deceleration	100	_	0	_	_	16bit	R/W	0x6012
Pr8.19	Homing torque holding time	100	_	0	_	_	16bit	R/W	0x6013
Pr8.20	Homing torque	100	_	0	_	_	16bit	R/W	0x6014
Pr8.21	Homing overtravel alarm range	0	_	0		_	16bit	R/W	0x6015
Pr8.22	Emergency stop at limit deceleration	10	_	0		_	16bit	R/W	0x6016
Pr8.23	STP emergency stop deceleration	50	_	0		_	16bit	R/W	0x6017
Pr8.24	I/O combination trigger mode	0	_	0		_	16bit	R/W	0x601A
Pr8.25	I/O commbination filter	5	_	0			16bit	R/W	0x601B
Pr8.26	S-code current output value	0	_	0		_	16bit	R/W	0x601C
Pr8.27	PR warning	0	_	0		_	16bit	R/W	0x601D
Pr8.39	JOG velocity	100	_	0		_	16bit	R/W	0x6027
Pr8.40	JOG acceleration	100		0			16bit	R/W	0x6027
Pr8.41	JOG deceleration	100	_	0	_		16bit	R/W	0x6028
Pr8.42	Command position H	0	_	0	_	_	16bit	R/W	0x6029
Pr8.43	Command position (L)	0		0					
Pr8.44				0	_	_	16bit	R/W	0x602B
Pr8.45	Motor position H Motor position (L)	0	_	0	_	_	16bit	R/W R/W	0x602C
Pr8.46				0	_		16bit	R/W	0x602D 0x602E
Pr8.47	Input I/O status	0	_	 	_	_	16bit		
Pr8.48	Output I/O status			0	_		16bit	R/W	0x602F
Pr8.49	Path 1 S code	0		0	_		16bit	R/W	0x6030
Pr8.50	Path 1 S-code	0		0	-		16bit	R/W	0x6031
Pr8.51	Path 2 S code	0	_	0	_		16bit	R/W	0x6032
Pr8.52	Path 4 S and a	0	_	0	-	_	16bit	R/W	0x6033
	Path 4 S-code	0	_	0	-	_	16bit	R/W	0x6034
Pr8.53	Path 5 S-code	0	_	0	_	_	16bit	R/W	0x6035
Pr8.54	Path 6 S-code	0	_	0	-	_	16bit	R/W	0x6036
Pr8.55	Path 7 S-code	0		0		_	16bit	R/W	0x6037
Pr8.56	Path 8 S-code	0	_	0	_	_	16bit	R/W	0x6038
Pr8.57	Path 9 S-code	0	_	0	_	_	16bit	R/W	0x6039
Pr8.58	Path 10 S-code	0	_	0	_	_	16bit	R/W	0x603A
Pr8.59	Path 11 S-code	0		0	_	_	16bit	R/W	0x603B
Pr8.60	Path 12 S-code	0	_	0	_	_	16bit	R/W	0x603C



		Activ		Valid mode		Communication mode			
Code	Label	Default Activ F		Р	u	Т	Byte	On	485
			ation	R	0	•	Буце	Op.	Addr.
Pr8.61	Path 13 S-code	0	_	0	-	-	16bit	R/W	0x603D
Pr8.62	Path 14 S-code	0	l	0	1	1	16bit	R/W	0x603E
Pr8.63	Path 15 S-code	0	l	0	1	1	16bit	R/W	0x603F

[Class 9] Pr-Control Path Parameters

[Class 9]	Pr-Control Path Parameters			Valid					
			Activ		lid m	ode	Comm	unicati	on mode
Code	Label	Default	ation	P R	S	Т	Byte	Op.	485 Addr.
Pr9.00	PR0 mode	0	_	0	_		16bit	R/W	0x6200
Pr9.01	PR0 position H	0	_	0	-		16bit	R/W	0x6201
Pr9.02	PR0 position(L)	0	_	0	-	_	16bit	R/W	0x6202
Pr9.03	PR0 velocity	60		0	_	_	16bit	R/W	0x6203
Pr9.04	PR0 acceleration time	100	_	0	_		16bit	R/W	0x6204
Pr9.05	PR0 deceleration time	100	_	0	_	_	16bit	R/W	0x6205
Pr9.06	PR0 pause time	0	_	0	_	_	16bit	R/W	0x6206
Pr9.07	PR0 special parameter	0	_	0	_	_	16bit	R/W	0x6207
Pr9.08	PR1 mode	0	_	0	-	_	16bit	R/W	0x6208
Pr9.09	PR1 position H	0	_	0	_	_	16bit	R/W	0x6209
Pr9.10	PR1 position(L)	0	_	0	_		16bit	R/W	0x620A
Pr9.11	PR1 velocity	60	_	0	_	_	16bit	R/W	0x620B
Pr9.12	PR1 acceleration time	100	_	0	_	_	16bit	R/W	0x620C
Pr9.13	PR1 deceleration time	100	_	0	-		16bit	R/W	0x620D
Pr9.14	PR1 pause time	0	_	0	-		16bit	R/W	0x620E
Pr9.15	PR1 special parameter	0	_	0	_	_	16bit	R/W	0x620F
Pr9.16	PR2 mode	0	_	0	_	_	16bit	R/W	0x6210
Pr9.17	PR2 position H	0	_	0	_	_	16bit	R/W	0x6211
Pr9.18	PR2 position(L)	0	_	0	_	_	16bit	R/W	0x6212
Pr9.19	PR2 velocity	60		0	-		16bit	R/W	0x6213
Pr9.20	PR2 acceleration time	100	_	0	-	_	16bit	R/W	0x6214
Pr9.21	PR2 deceleration time	100	_	0	_	_	16bit	R/W	0x6215
Pr9.22	PR2 pause time	0	_	0	_		16bit	R/W	0x6216
Pr9.23	PR2 special parameter	0	_	0	_	_	16bit	R/W	0x6217
Pr9.24	PR3 mode	0	_	0	_	_	16bit	R/W	0x6218
Pr9.25	PR3 position H	0	_	0	_	_	16bit	R/W	0x6219
Pr9.26	PR3 position(L)	0	_	0	_	_	16bit	R/W	0x621A
Pr9.27	PR3 velocity	60	_	0	_	_	16bit	R/W	0x621B
Pr9.28	PR3 acceleration time	100	_	0	_	_	16bit	R/W	0x621C
Pr9.29	PR3 deceleration time	100	_	0	_	_	16bit	R/W	0x621D
Pr9.30	PR3 pause time	0	_	0	_	_	16bit	R/W	0x621E
Pr9.31	PR3 special parameter	0	_	0	_	_	16bit	R/W	0x621F
Pr9.32	PR4 mode	0	_	0	_		16bit	R/W	0x6220
Pr9.33	PR4 position H	0	_	0	_	_	16bit	R/W	0x6221
Pr9.34	PR4 position(L)	0	_	0	_	_	16bit	R/W	0x6222
Pr9.35	PR4 velocity	60		0	_	_	16bit	R/W	0x6223
Pr9.36	PR4 acceleration time	100	_	0	_	_	16bit	R/W	0x6224
Pr9.37	PR4 deceleration time	100	_	0	_	_	16bit	R/W	0x6225
Pr9.38	PR4 pause time	0	_	0	_	_	16bit	R/W	0x6226
Pr9.39	PR4 special parameter	0	_	0	_	_	16bit	R/W	0x6227



Pr9.40 PR5 mode 0 — 0 — 16bit Pr9.41 PR5 position H 0 — 0 — 16bit I Pr9.42 PR5 position(L) 0 — 0 — 16bit I Pr9.43 PR5 velocity 60 — 0 — 16bit I Pr9.44 PR5 acceleration time 100 — 0 — 16bit I Pr9.45 PR5 deceleration time 100 — 0 — 16bit I Pr9.46 PR5 pause time 0 — 0 — 16bit I Pr9.47 PR5 special parameter 0 — 0 — 16bit I Pr9.48 PR6 mode 0 — 0 — 16bit I Pr9.49 PR6 position H 0 — 0 — 0 — 16bit I Pr9.50 PR6 position(L) 0 <th>R/W R/W R/W </th> <th>485 Addr. 0x6228 0x6229 0x622A 0x622B 0x622C 0x622D 0x622E 0x6230 0x6231 0x6232 0x6233</th>	R/W R/W	485 Addr. 0x6228 0x6229 0x622A 0x622B 0x622C 0x622D 0x622E 0x6230 0x6231 0x6232 0x6233
Pr9.40 PR5 mode 0 — 0 — 16bit I Pr9.41 PR5 position H 0 — 0 — 0 — 16bit I Pr9.42 PR5 position(L) 0 — 0 — — 16bit I Pr9.43 PR5 velocity 60 — 0 — — 16bit I Pr9.44 PR5 acceleration time 100 — 0 — 16bit I Pr9.45 PR5 deceleration time 0 — 0 — 16bit I Pr9.45 PR5 pause time 0 — 0 — 16bit I Pr9.46 PR5 pause time 0 — 0 — 16bit I Pr9.47 PR5 special parameter 0 — 0 — 16bit I Pr9.48 PR6 mode 0 — 0 — 0 — 16bit I	R/W R/W	0x6228 0x6229 0x622A 0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.41 PR5 position H 0 — 0 — 16bit I Pr9.42 PR5 position(L) 0 — 0 — 16bit I Pr9.43 PR5 velocity 60 — 0 — 16bit I Pr9.44 PR5 acceleration time 100 — 0 — 16bit I Pr9.45 PR5 deceleration time 100 — 0 — 16bit I Pr9.46 PR5 pause time 0 — 0 — 16bit I Pr9.47 PR5 special parameter 0 — 0 — 16bit I Pr9.48 PR6 mode 0 — 0 — 16bit I Pr9.49 PR6 position H 0 — 0 — 16bit I Pr9.50 PR6 position(L) 0 — 0 — 16bit I Pr9.51 PR6 velocity 60 <td< th=""><th>R/W R/W R/W </th><th>0x6229 0x622A 0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232</th></td<>	R/W R/W	0x6229 0x622A 0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.42 PR5 position(L) 0 — O — 16bit I Pr9.43 PR5 velocity 60 — O — 16bit I Pr9.44 PR5 acceleration time 100 — O — 16bit I Pr9.45 PR5 deceleration time 0 — O — 16bit I Pr9.46 PR5 pause time 0 — O — 16bit I Pr9.47 PR5 special parameter 0 — O — 16bit I Pr9.48 PR6 mode 0 — O — 16bit I Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — 16bit I Pr9.52 PR6 acceleration time 100 —	R/W	0x622A 0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.43 PR5 velocity 60 — O — 16bit I Pr9.44 PR5 acceleration time 100 — O — 16bit I Pr9.45 PR5 deceleration time 100 — O — 16bit I Pr9.46 PR5 pause time 0 — O — 16bit I Pr9.47 PR5 special parameter 0 — O — 16bit I Pr9.48 PR6 mode 0 — O — 16bit I Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 0 — </td <td>R/W R/W R/W R/W R/W R/W R/W R/W R/W R/W</td> <td>0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232</td>	R/W	0x622B 0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.44 PR5 acceleration time 100 — O — 16bit I Pr9.45 PR5 deceleration time 100 — O — 16bit I Pr9.46 PR5 pause time 0 — O — 16bit I Pr9.47 PR5 special parameter 0 — O — 16bit Pr9.48 PR6 mode 0 — O — 16bit Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 —	R/W	0x622C 0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.45 PR5 deceleration time 100 — O — 16bit I Pr9.46 PR5 pause time 0 — O — 16bit I Pr9.47 PR5 special parameter 0 — O — 16bit Pr9.48 PR6 mode 0 — O — 16bit Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W R R/W R/W R/W R/W	0x622D 0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.46 PR5 pause time 0 — O — 16bit I Pr9.47 PR5 special parameter 0 — O — — 16bit Pr9.48 PR6 mode 0 — O — — 16bit I Pr9.49 PR6 position H 0 — O — — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W R/W R/W R/W R/W	0x622E 0x622F 0x6230 0x6231 0x6232
Pr9.47 PR5 special parameter 0 — O — 16bit Pr9.48 PR6 mode 0 — O — 16bit I Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R R/W R/W R/W R/W	0x622F 0x6230 0x6231 0x6232
Pr9.48 PR6 mode 0 — O — 16bit I Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W R/W R/W	0x6230 0x6231 0x6232
Pr9.49 PR6 position H 0 — O — 16bit I Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W R/W	0x6231 0x6232
Pr9.50 PR6 position(L) 0 — O — 16bit I Pr9.51 PR6 velocity 60 O — 16bit I Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W R/W	0x6232
Pr9.51 PR6 velocity 60 O — — 16bit I Pr9.52 PR6 acceleration time 100 — O — — 16bit I Pr9.53 PR6 deceleration time 100 — O — — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W R/W	
Pr9.52 PR6 acceleration time 100 — O — 16bit I Pr9.53 PR6 deceleration time 100 — O — — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I	R/W	0x6233
Pr9.53 PR6 deceleration time 100 — O — 16bit I Pr9.54 PR6 pause time 0 — O — 16bit I		
Pr9.54 PR6 pause time 0 − 0 − 16bit I	D // /	0x6234
		0x6235
DrQ 55 DDG appoint parameter	R/W	0x6236
Pr9.55 PR6 special parameter 0 — 0 — 16bit I	R/W	0x6237
Pr9.56 PR7 mode 0 — O — I febit I	R/W	0x6238
Pr9.57 PR7 position H 0 — O — I 16bit I	R/W	0x6239
Pr9.58 PR7 position(L) 0 — O — I debit I	R/W	0x623A
Pr9.59 PR7 velocity 60 — O — I dbit I	R/W	0x623B
Pr9.60 PR7 acceleration time 100 — O — — 16bit I	R/W	0x623C
Pr9.61 PR7 deceleration time 100 — O — — 16bit I	R/W	0x623D
Pr9.62 PR7 pause time 0 — O — I debit I	R/W	0x623E
	R/W	0x623F
Pr9.64 PR8 mode 0 — 0 — 16bit	R/W	0x6240
Pr9.65 PR8 position H 0		0x6241
		0x6242
		0x6243
		0x6244
		0x6245
		0x6246
		0x6247
		0x6248
		0x6249
		0x624A
		0x624B
		0x624C
		0x624D
		0x624E
		0x624F
		0x6250
		0x6251
		0x6252
		0x6253
		0x6254
		0x6254
		0x6255
		0x6256



			A ative	Val	lid mo	ode	Comm	unicati	on mode
Code	Label	Default	Activ ation	Р	S	Т	Byte	Op.	485
			ation	R	3	•	Dyte	Op.	Addr.
Pr9.88	PR11 mode	0	_	0	_	_	16bit	R/W	0x6258
Pr9.89	PR11 position H	0	_	0	_	_	16bit	R/W	0x6259
Pr9.90	PR11 position(L)	0	_	0	_	_	16bit	R/W	0x625A
Pr9.91	PR11 velocity	60	_	0	_	_	16bit	R/W	0x625B
Pr9.92	PR11 acceleration time	100	_	0	_	_	16bit	R/W	0x625C
Pr9.93	PR11 deceleration time	100	_	0	_	_	16bit	R/W	0x625D
Pr9.94	PR11 pause time	0	_	0	_	_	16bit	R/W	0x625E
Pr9.95	PR11 special parameter	0	_	0	_	_	16bit	R/W	0x625F
Pr9.96	PR12 mode	0	_	0	_	_	16bit	R/W	0x6260
Pr9.97	PR12 position H	0	_	0	_	_	16bit	R/W	0x6261
Pr9.98	PR12 position(L)	0	_	0	_	_	16bit	R/W	0x6262
Pr9.99	PR12 velocity	60		0	_	_	16bit	R/W	0x6263
Pr9.100	PR12 acceleration time	100	_	0	_	_	16bit	R/W	0x6264
Pr9.101	PR12 deceleration time	100	_	0	_	_	16bit	R/W	0x6265
Pr9.102	PR12 pause time	0	_	0	_	_	16bit	R/W	0x6266
Pr9.103	PR12 special parameter	0	_	0	_	_	16bit	R/W	0x6267
Pr9.104	PR13 mode	0	_	0	_	_	16bit	R/W	0x6268
Pr9.105	PR13 position H	0	_	0	_	_	16bit	R/W	0x6269
Pr9.106	PR13 position(L)	0	_	0	_	_	16bit	R/W	0x626A
Pr9.107	PR13 velocity	60	_	0	_	_	16bit	R/W	0x626B
Pr9.108	PR13 acceleration time	100	_	0	_	_	16bit	R/W	0x626C
Pr9.109	PR13 deceleration time	100	_	0	_	_	16bit	R/W	0x626D
Pr9.110	PR13 pause time	0	_	0	_	_	16bit	R/W	0x626E
Pr9.111	PR13 special parameter	0	_	0	_	_	16bit	R/W	0x626F
Pr9.112	PR14 mode	0	_	0	_	_	16bit	R/W	0x6270
Pr9.113	PR14 position H	0	_	0	_	_	16bit	R/W	0x6271
Pr9.114	PR14 position(L)	0	_	0	_	_	16bit	R/W	0x6272
Pr9.115	PR14 velocity	60		0	_	_	16bit	R/W	0x6273
Pr9.116	PR14 acceleration time	100	_	0	_	_	16bit	R/W	0x6274
Pr9.117	PR14 deceleration time	100	_	0	-		16bit	R/W	0x6275
Pr9.118	PR14 pause time	0	_	0	_	_	16bit	R/W	0x6276
Pr9.119	PR14 special parameter	0	_	0	_	_	16bit	R/W	0x6277
Pr9.120	PR15 mode	0	_	0	_	_	16bit	R/W	0x6278
Pr9.121	PR15 position H	0	_	0			16bit	R/W	0x6279
Pr9.122	PR15 position(L)	0	_	0			16bit	R/W	0x627A
Pr9.123	PR15 velocity	60	_	0	_	_	16bit	R/W	0x627B
Pr9.124	PR15 acceleration time	100	_	0			16bit	R/W	0x627C
Pr9.125	PR15 deceleration time	100	_	0			16bit	R/W	0x627D
Pr9.126	PR15 pause time	0	_	0	_	_	16bit	R/W	0x627E
Pr9.127	PR15 special parameter	0	_	0	_	_	16bit	R/W	0x627F



[Class B] Status Parameters

[Class b]	Status Parameters			Val	id mo	ode	Com	municati	on mode
Code	Label	Default	Activ ation	Р	S	Т	Byte	Op.	485 Addr.
PrB.00	Software version 1 (DSP)	/	_	0	0	0	16bit	R	0x0B00
PrB.01	Software version 2 (CPLD)	/	_	0	0	0	16bit	R	0x0B01
PrB.02	Software version 3 (Others)	/	_	0	0	0	16bit	R	0x0B02
PrB.03	Current alarm	/	_	0	0	0	16bit	R	0x0B03
PrB.04	Motor not rotating cause	/	_	0	0	0	16bit	R	0x0B04
PrB.05	Driver operation status	/	_	0	0	0	16bit	R	0x0B05
PrB.06	Motor speed (Before filter)	/	-	0	0	0	16bit	R	0x0B06
PrB.07	Motor torque	/	l	0	0	0	16bit	R	0x0B07
PrB.08	Motor current	/	l	0	0	0	16bit	R	0x0B08
PrB.09	Motor speed (After filter)	/	1	0	0	0	16bit	R	0x0B09
PrB.10	DC bus voltage	/	l	0	0	0	16bit	R	0x0B0A
PrB.11	Driver temperature	/		0	0	0	16bit	R	0x0B0B
PrB.12	External analog 1	/	_	0	0	0	16bit	R	0x0B0C
PrB.13	External analog 2	/	_	0	0	0	16bit	R	0x0B0D
PrB.14	External analog 3	/	l	0	0	0	16bit	R	0x0B0E
PrB.15	Motor overload rate	/	_	0	0	0	16bit	R	0x0B0F
PrB.16	Vent overload rate	/	l	0	0	0	16bit	R	0x0B10
PrB.17	Physical I/O input status	/	1	0	0	0	16bit	R	0x0B11
PrB.18	Physical I/O output status	/	l	0	0	0	16bit	R	0x0B12
PrB.20	Command position (Command unit)	/	-	0	0	0	32bit	R	0x0B14 0x0B15
PrB.21	Motor position (Command unit)	/	_	0	-	-	32bit	R	0x0B16 0x0B17
PrB.22	Position deviation (Command unit)	/	_	0	0	0	32bit	R	0x0B18 0x0B19
PrB.23	Command position (Encoder unit)	/	_	0	0	0	32bit	R	0x0B1A 0x0B1B
PrB.24	Motor position (Encoder unit)	/	_	0	-	-	32bit	R	0x0B1C 0x0B1D
PrB.25	Position deviation (Encoder unit)	/	_	0	o	o	32bit	R	0x0B1E 0x0B1F
PrB.26	Rotational encoder position feedback	/	_	0	-	-	32bit	R	0x0B20 0x0B21



3.2 Parameters description

3.2.1 [Class 0] Basic Settings

	Label	Label Model-following/Zero tracking control Valid models				Р
Pr0.00	Range	0-10000	Unit	0.1Hz	Default	1
	Byte length	16bit	Attribute	R/W	485 address	0x0001
	Valid	At stop				

Model-following bandwidth, also known as model-following control (MFC), is used to control the position loop to improve the responsiveness to commands, speed up positioning time and reduce following error. The effect is obvious especially in low and medium mechanical stiffness.

Value	Description
0	Disable model following/zero tracking control
1	Set bandwidth automatically
2~9	Reserved
10~2000	Manually set control bandwidth. 30~100 recommended for belt
10~2000	application

	Label	Control Mo	de Settings		Valid mode(s)	Р	S	T
Pr0.01	Range	0~10	Unit	_	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x000)3	
	Valid	After restar	t					

Value	Descrip	
Value	1 st mode	2 nd mode
[0]	Position	_
1	Velocity	_
2	Torque	_
3	Position	Velocity
4	Position	Torque
5	Velocity	Torque
		Position Pr0.22=1
6	PR internal	Velocity Pr0.22=1
	ommand control	Torque Pr0.22=2
7~10	Reserved	

- ◆When 3, 4, 5, 6 combination hybrid mode, 1st and 2nd mode can be chosen accordingly with control mode switching input (C-MODE). C-MODE: Invalid, select 1st mode. C-MODE: Valid, select 2st mode. Please allow some time in between mode switching commands.
- ◆Please set Pr0.01 = 6 to switch to other modes from PR mod, then set 2nd mode using Pr0.22.

C-MODE is defaulted to Normally Open



0x_00

reserved

	Label		Real time	Auto Gain Adjus	sting	Valid mode(s)	Р	S	Т
Pr0.02	Range		0x0~0xFF F	Unit	_	Default	0x1		
	Byte len	gth	16bit	Attribute	R/W	485 address	0x000)5	
	Valid		Immediate						
Value	Category	S	Settings			Application			
		chara mode rapid	I to set motion setting mode, which can be selected according to the motion acteristics or setting requirements. Generally, it is recommended to select a 1 with good generality when there is no special requirement, mode 2 who positioning is needed If mode 1 and mode 2 cannot meet the requirement se choose mode 0.						ct vhen ents,
	Motion	1:0	0:Manual Pr0.03 invalid. Gain value must be adjusted manually accordingly.					ually and	
0x00_	setting mode	1:S	tandard	Pr0.03 valid. Quick gain adjusting can be achieved by changing Pr0.03 stiffness value. Gain switching is not used in this mode, suitable for applications with requirements for stability.					
		2:Pc	ositioning	Pr0.03 valid. Quick gain adjusting can be achieved by changing Pr0.03 stiffness value. This mode is suitable for applications requiring quick positioning. Not recommended for load mounted vertical to ground, or please compensate for the load using Pr6.07					
					ose acco	rding to load-inertia	a ratio a	ınd	
		mech	anical struct		• • •			41.1	
	Lood time		: Rigid ructure	when there is	a relative ation inclu	stem responsivenerally rigid structure with uding directly connerals, etc.	th low I	oad inert	tia.
0x0_0	Load type setting	1:Hi	gh inertia	For applications with higher load inertia (10 times or above					, .
			Flexible ructure	there is low rig	idity stru	vstem stability. Use cture with high load elts and chains.			

The setting type combination is a hexadecimal standard, as follows:

0 71					
Setting type combination	Application type				
0X000	Rigid structure + Manual				
0X001	Rigid structure +Standard				
0X002	Rigid structure +Positioning				
0X010	High inertia + Manual				
0X011	High inertia + Standard				
0X012	High inertia + Positioning				
0X020	Flexible structure + Manual				
0X021	Flexible structure +Standard				
0X022	Flexible structure +Positioning				



	Label	Real time auto stiffness adjusting			Valid mode(s)	Р	S	Т		
Pr0.03	Range	50 ~ 81	Unit		Default	70				
	Byte length	16bit	Attribute	R/W	485 address	0x00	07			
	Valid	Immediate								
	Low ──Mechanical stiffness High									
	Low Servo gain \longrightarrow High $ 81.80 \cdots \cdots 70.69.68 \cdots \cdots 51.50 $ $ Low \longrightarrow \text{Responsiveness} \longrightarrow \text{High} $									
		•	•		and mechanical s					

	Label	Inertia ratio			Valid mode(s)	Р	S	T
Pr0.04	Range	0~20000	Unit	%	Default	250		
	Byte length	16bit	Attribute	R/W	485 address	0x000	9	
	Valid	Immediate						

Pr0.04=(load inertia/motor rotational inertia)×100%

Set inertia ratio according to actual load inertia. When both are uniform, actual motor velocity loop responsiveness and gain settings will be consistent. If inertia ratio is greater than actual value, velocity loop gain settings will be higher and vice versa. For motor with high inertia, Pr0.04 can be left unfilled but optimal setting of Pr0.04 could improve system performance

	Label	Command pulse input selection			Valid mode(s)	Р		
Pr0.05	Range	0~1	Unit	_	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x000B		
	Valid	After restart						

Value	Description
[0]	Pulse input low speed channel (200/500kHz pulse input)
1	Pulse input high speed channel (4MHz pulse input)

Both channels cannot be used at the same time.

	Label	Command pulse polarity inversion			Valid mode(s)	Р	
Pr0.06	Range	0~1	Unit	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x000D	
	Valid	After restart					
Pr0.06 and Pr0.07 set command pulse input inversion and mode correspondingly.							



Pr0.07	Label	Command p	ulse input mo	ode	Valid mode(s)	P		
	Range	0~3	Unit	_	Default	3		
	Byte length	16bit	Attribute	R/W	485 address	0x000)F	
	Valid	After restart						

Command pulse input

Command puls	se input					
Command Polarity inversion (Pr0.06)	Command pulse input mode settings (Pr0.07)	Command Pulse Mode	Positive signal	Negative signal		
	0 or 2	90°phase difference 2 phase pulse (Phase A+ Phase B)	A t1 t1 B t1 t1	t1 t1		
[0]	1	CW pulse sequence + CCW pulse sequence	t3 t2 t2			
	[3]	Pulse sequence + Directional symbol	t4 t5 t4 t5 t6 t6 t6			
	0 or 2	90°phase difference 2 phase pulse (Phase A+Phase B)	A TI	tl tl		
1	1	CW pulse sequence + CCW pulse sequence	t2 t2			
	3	Pulse sequence + Directional symbol	Pulse sequence + 14 t5 14 t5			

Command pulse input signal max. frequency and min. duration needed

Command pulse input interface		Max.	Max. Min. duration needed (µ s)						
		Frequency	t1	t2	t3	t4	t5	t6	
Pulse sequence interface	Differential drive	500 kHz	2	1	1	1	1	1	
	Open collector	200 kHz	5	2.5	2.5	2.5	2.5	2.5	
	High speed differential drive	4Mhz	0.25	0.125	0.125	0.125	0.125	0.125	

Please set $>0.1\mu s$ for the duration between rising and falling edge of command pulse input signal.

¹ revolution with 2500 pulses 2-phase pulse input when Pr0.07=0 or 2, Pr0.08 = 10000;

¹ revolution with 10000 pulses 1-phase pulse input when Pr0.07=1 or 3, Pr0.08 = 10000



Pr0.08	Label	1st command revolution	pulse count	Valid mode(s)	Р	S	T	
	Range	0-67100864	Unit	PULSE	Default	10000		
	Byte length	32bit	Attribute	R/W	485 address	H: 0x0010 L: 0x0011		
	Valid	After restart						

Control will affected if value set is too low. Err1b1 might occur if value < 500.

- (1) Pr0.08 valid when \neq 0: Motor revolution = input pulse count / [Pr0.08 value]
- (2) Pr0.08 invalid when = 0: Pr0.09 and Pr0.10 valid.

Pr0.09	Label	1st command freq divider/multiplier n	Valid mode(s)	Р					
	Range	1~2147483647	Unit		Default	1			
F10.09	Byte length	32bit	Attrib	R/W	485 address	H: 0x0012			
			ute			L: 0x0	0013		
	Valid	After restart							
Valid when Pr0.08 = 0, please refer to description in Pr0.10.									
		1 at command fraguency				В			

	Label	1st command freq divider/multiplier of		or	Valid mode(s)	Р		
D=0.40	Range	1~2147483647	Unit	_	Default	1		
Pr0.10	Byte length	32bit	Attrib	R/W	485 address	H: 0x		
					L: 0x	0015		
	Valid	After restart						

- 1. Settings:
- (1)Driver command pulse input count: X
- (2) Encoder pulse count after frequency divider/multiplier: Y
- (3)Encoder pulse count per revolution: Z
- (4)Motor revolution: W
- 2. Calculation:
- (1) X, Y

Y = X * Pr0.09 / Pr0.10

Please keep the value of Pr0.09 and Pr0.10 to be smaller than 2²⁴ (16777216).

(2) Z

Motor with 23-bit motor: $Z=2^{23}=8388608$

(3) Y, Z, W

W = Y / Z

Performance cannot be guaranteed if frequency divider/multiplier ratio is set to extreme values. Err1b1 might occur if W < 500.

	Label	1 st torque limi	t		Valid mode(s)	Р	S	Т
Pr0.13	Range	0~500	Unit	%	Default	350		
	Byte length	16bit	Attribute	R/W	485 address	0x001	В	
	Valid	Immediate						

^{1&}lt;sup>st</sup> torque limit is set according to ratio percentage of motor rated current. Do not exceed max driver output current.

Please refer to Pr5.21 on how to set torque limit.



	Label	Excessive po	Excessive position deviation			Р	
Pr0.14	Range	0~310	Unit	0.1rev	Default	30	
	Byte length	16bit	Attribute	R/W	485 address	0x001D	
	Valid	Immediate					

Please set threshold value for position deviation accordingly. Default factory setting = 30, Er180 will be triggered if positive deviation is in excess of 3 revolutions.

	Label	Absolute en	coder setting	js	Valid mode(s)	P	S	Т	
Pr0.15	Range	0~15	Unit	-	Default	0			
	Byte length	16bit	Attribute	R/W	485 address	0x001F			
	Valid	After restart							
Value	Mode			De	scription				
[0]	Incremental	Doesn't retai	n position da	ata on po	wer off. Unlimited tr	avel d	istance		
1	Multiturn absolute linear	Retrain posit distance and			. For applications werflow.	ith fixe	ed trave	el	
2	Multiturn absolute rotary	Retrain positi (Pr6.63+1). U	•		. Actual data feedba	ack in	oetwee	n 0-	
3	Single turn absolute	Used when tr overflow will			n 1 revolution of the	enco	der. Da	ta	
5	Multi turn		de once alar		multiturn absolute f d, if remains at 5 af				
9	absolute	absolute fund remains at 9	Clear multiturn position, reset multiturn alarm and activate multiturn absolute function. Will switch to multiturn mode once alarm cleared, if remains at 9 after 3s, please solve according to Er153. Please disable axis before setting to 9 and home the axis before using.						
Others		Do not use!							

	Label		Regenerati	ve resistance			Valid mode(s)	Р	S	T
D#0 46	Range	9	25~500	Unit	Ohm)	Default	100		•
Pr0.16	Byte I	ength	16bit	Attribute	R/W		485 address	0x002	<u>?</u> 1	
	Valid		Immediate							
	To set	resistan	ce value of r	egenerative r	esistor	٢				
				e determine ala						
	If set value > actual regenerative resistance, Er120 occurrence might be delayed.									
	Label		Regenerati	ve resistor po	wer		Valid mode(s)	Р	S	Т
	Label		rating				valia illoac(3)			
Pr0.17	Range	Range 20~5000		Unit W			Default	50		
	Byte I	ength	16bit	Attribute	R/W		485 address	0x002	23	
	Valid		Immediate							
	To set	power r	ating of rege	nerative resist	or. Ple	ease	refer to table belo	W		
		Drives		Resistance (Ω)	Pov	wer rating(W)			
		ELD2-R	S7005B	10			30			
	ELD2-I		S7010B	10			50			
	ELD2-F		S7015B	10			50			
	ELD2-F			10		100				
		ELD2-R	S7030B	10			100/150			



ELD2-RS7040B	10	150/200
ELD2-RS7060B	10	150/200

Pr0.16 and Pr0.17 determines the threshold value of Er120. Please set accordingly or it might trigger false alarm or damage to servo drive.

Note: If external regenerative resistor is used, please set according to its labeled power rating.

3.2.2 [Class 1] Gain adjustments

	Label	1 st position loop gain			Valid mode(s)	P
Pr1.00	Range	0~30000	Unit	0.1/s	Default	320
Pr1.00	Byte length	16bit	Attribute	R/W	485 address	0x0101
	Valid	Immediate				

Higher position loop gain value improves the responsiveness of the servo driver and lessens the positioning time.

Position loop gain value shouldn't exceed responsiveness of the mechanical system and take in consideration velocity loop gain, if not it might cause vibration, mechanical noise and overtravel.

As velocity loop gain is based on position loop gain, please set both values accordingly. Recommended range: 1.2≤Pr1.00/Pr1.01≤1.8

	Label	1 st velocity loop gain			Valid mode(s)	Р	S	T
Pr1.01	Range	1~32767	Unit	0.1Hz	Default	180		
	Byte length	16bit	Attribute	R/W	485 address	0x0103	}	
	Valid	Immediate						

To determine the responsiveness of the velocity loop. If inertia ratio of Pr0.04 is uniform with actual inertia ratio, velocity loop responsiveness = Pr1.01.

To increase position loop gain and improve responsiveness of the whole system, velocity loop gain must be set at higher value. Please notice that if the velocity loop gain is too high, it might cause vibration.

	Label	1 st Integral T Velocity Loo		t of	Valid mode(s)	Р	S	Т	
Pr1.02	Range	1~10000	Unit	0.1ms	Default	310	310		
	Byte length	16bit	Attribute	R/W	485 address	0x010)5		
	Valid	Immediate							

The lower the set value, the closer the lag error at stop to 0 but might cause vibration. If the value set is overly large, overshoot, delay of positioning time duration and lowered responsiveness might occur.

Set 10000 to deactivate Pr1.02.



	Label	1 st velocity detection filter			Valid mode(s)	Р	S	Т
D 4 00	Range	0~31	Unit	_	Default	15		
Pr1.03	Byte length	16bit	Attribute	R/W	485 address	0x0107		
	Valid	Immediate						

This filter is a low pass filter. It blocks high frequencies which cause system instability from velocity feedback data. The higher the set value, lower frequencies will be blocked and velocity responsiveness will also be lowered. Pr1.03 needs to match velocity loop gain. Please refer to the following table.

Value	Velocity Detection Filter Cut-off Frequency(Hz)	Value	Velocity Detection Filter Cut-off Frequency(Hz)
0	2500	16	750
1	2250	17	700
2	2100	18	650
3	2000	19	600
4	1800	20	550
5	1600	21	500
6	1500	22	450
7	1400	23	400
8	1300	24	350
9	1200	25	300
10	1100	26	250
11	1000	27	200
12	950	28	175
13	900	29	150
14	850	30	125
【15】	800	31	100

	Label	1 st Torque F	ilter Time Co	Valid mode(s)	Р	S	T	
Pr1.04	Range	0~2500	Unit	0.01ms	Default	126		
	Byte length	16bit	Attribute	R/W	485 address	0x0109		
	Valid	Immediate						

To set torque command low-pass filter, add a filter delay time constant to torque command and filter out the high frequencies in the command.

Often used to reduce or eliminate some noise or vibration during motor operation, but it will reduce the responsiveness of current loop, resulting in undermining velocity loop and position loop control. Pr1.04 needs to match velocity loop gain.

Recommended range: 1,000,000/(2π×Pr1.04) ≥Pr1.01×4

For example: Velocity loop gain Pr1.01=180(0.1Hz) which is 18Hz. Time constant of torque filter should be Pr1.01≤221(0.01ms)

If mechanical vibration is due to servo driver, adjusting Pr1.04 might eliminate the vibration. The smaller the value, the better the responsiveness but also subjected to machine conditions. If the value is too large, it might lower the responsiveness of current loop.

With higher Pr1.01 value settings and no resonance, reduce Pr1.04 value; With lower Pr1.01 value settings, increase Pr1.04 value to lower motor noise.



	Label	2 nd Position	Loop Gain		Valid mode(s)	P		
Pr1.05	Range	0~30000	Unit	0.1/s	Default	380		
F11.05	Byte length	16bit	Attribute	R/W	485 address	0x010	В	
	Valid	Immediate						
	Label	2 nd velocity I	oop gain		Valid mode(s)	Р	S	T
Pr1.06	Range	1~32767	Unit	0.1Hz	Default	180		
	Byte length	16bit	Attribute	R/W	485 address	0x010	D	
	Valid	Immediate						
	Label	_	2 nd Integral Time Constant of /elocity Loop			Р	Ø	T
Pr1.07	Range	1~10000	Unit	0.1ms	Default	10000		
	Byte length	16bit	Attribute	R/W	485 address	0x010F		
	Valid	Immediate						
	Label	2 nd velocity of	detection filte	r	Valid mode(s)	Р	S	T
Pr1.08	Range	0~31	Unit	_	Default	15		
F11.00	Byte length	16bit	Attribute	R/W	485 address	0x011	1	
	Valid	Immediate						
	Label	2 nd Torque F	ilter Time Co	onstant	Valid mode(s)	P	S	T
Pr1.09	Range	0~2500	Unit	0.01ms	Default	126		
F11.09	Byte length	16bit	Attribute	R/W	485 address	0x011	3	
	Valid	Immediate	1 2 1 4			C14		

Position loop, velocity loop, velocity detection filter, torque command filter each have 2 pairs of gain or time constant (1st and 2nd).

	Label	Velocity feed	Velocity feed forward gain			P
Pr1.10	Range	0~1000	Unit	0.10%	Default	300
	Byte length	16bit	Attribute	R/W	485 address	0x0115
	Valid	Immediate				

Used for decreasing following error caused by low responsiveness of velocity loop. Might cause overshoot or increase in noise if set value is too high.

	Label	Velocity feed constant	Velocity feed forward filter time constant			Р			
Pr1.11	Range	0~6400	Unit	0.01ms	Default	50			Ī
	Byte length	16bit	Attribute	R/W	485 address	0x0117	7	,	Ī
	Valid	Immediate							1

Set velocity feed forward low pass filter to eliminate high or abnormal frequencies in velocity feed forward command. Often used when position command with low resolution or high electronic gear ration to smoothen velocity feed forward.

Position deviation under constant velocity can be lowered with higher velocity feed forward gain. Please to refer to the equation below.

Reduce Pr1.11 value to suppress velocity overshoot during deceleration; Increase Pr1.11 value to suppress noise or vibration due to long driver control cycle or position command uneven pulse frequency.

<Application>

Set Pr1.11 = 50 (0.5ms), improve feedforward effect by gradually increase Pr1.10. The equation below can be used to determine the position deviation due to velocity feedforward gain under constant velocity.

Position deviation[Uint]= $\frac{Set \ velocity[\frac{Uint}{s}]}{Position \ loop \ gain[Hz]} \ x \ \frac{100 - Velocity \ feed \ foward \ gain[\%]}{100}$



	Label	Torque feed forward gain			Valid mode(s)	P S
Pr1.12	Range	0~1000	Unit	0.1%	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0x0119
	Valid	Immediate				

Before using torque feed forward, please set correct inertia ratio Pr0.04. By increasing torque feed forward gain, position deviation on constant acceleration/deceleration can be reduced to close to 0. Under ideal condition and trapezoidal speed profile, position deviation of the whole motion can be reduced to close to 0. In reality, perturbation torque will always exist, hence position deviation can never be 0.

	Label	Torque feed constant	forward filter	Valid mode(s)	Р	S		
Pr1.13	Range	0~6400	Unit	0.01ms	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x011	В	
	Valid	Immediate						

Low pass filter to eliminate abnormal or high frequencies in torque feed forward command. Usually used when encoder has lower resolution or precision.

Noise reduces if torque feed forward filter time constant is set higher but position deviation will increase at acceleration varied points.

<Application>

- Set Pr1.13 = 50ms, please increase torque forward gain gradually to enable torque feedforward.
- By increasing Pr1.13, noise will reduce but position deviation will become larger.



	Label	Position con mode	itrol gain swit	ching	Valid mode(s)	P		
Pr1.15	Range	0~10	Unit	_	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x011F		
	Valid	Immediate						

In position control, set the conditions for gain switching to be valid.

Value	Condition	Gain switching condition
[0]	1 st gain fixed	Fixed on using 1 st gain(Pr1.00-Pr1.04)
1	2 nd gain fixed	Fixed on using 2 nd gain (Pr1.05-Pr1.09)
2	Gain switching input valid	 Gain switching input (GAIN) invalid: 1st gain. Gain switching input (GAIN) valid: 2nd gain. *Default: 1st gain
3	High command torque	Switch to 2 nd gain when set torque command absolute value larger than (level + hysteresis)[%] Switch to 1 st gain when set torque command absolute value smaller than (level + hysteresis)[%]
4-9	Reserved	Reserved
10	Pending position command +actual velocity	Valid for position control. Switch to 2 nd gain if position command ≠ 0 Switch to 1 st gain if positional command = 0 throughout the duration of delay time and absolute value of actual velocity remains smaller than (level - hysteresis) (r/min)

** Above 'level' and 'hysteresis' are in correspondence to Pr1.17 Position control gain

switching level and Pr1.18 Hysteresis at position control switching.

	Label	Position con level	trol gain swi	tching	Valid mode(s)	Р		
Pr1.17	Range	0~20000		Mode dependent	Default	50		
	Byte length	16bit	Attribute	R/W	485 address	0x012	3	
	Valid	Immediate						

Set threshold value for gain switching to occur. Unit is mode dependent.

Switching condition	Unit			
Position	Encoder pulse count			
Velocity	RPM			
Torque	%			

Please set level ≥ hysteresis




	Label	Hysteresis a switching	Hysteresis at position control switching			Р		
Pr1.18	Range	0~20000	Unit	Mode dependent	Default	33		
	Byte length	16bit	Attribute	R/W	485 address	0x012	5	
	Valid	Immediate						

To eliminate the instability of gain switching. Used in combination with Pr1.17 using the same unit.

If level< hysteresis, drive will set internally hysteresis = level.

	Label Position control switching time					Р
Pr1.19	Range	0~10000	Unit	0.1ms	Default	33
	Byte length	16bit	Attribute	R/W	485 address	0x0127
	Valid	Immediate				

During position control, if 1st and 2nd gain difference is too large, to ease torque changes and vibration due to rapid changes in position loop gain, set suitable Pr1.19 value For example: 1st (pr1.00) <-> 2nd (Pr1.05)



	Label	Position con	Position command pulse filter time			P
Pr1.35	Range	0~200	Unit	0.01us	Default	8
	Byte length	16bit	Attribute	R/W	485 address	0x0147
	Valid	After restart				

To filter position setting pulse, getting rid of narrow pulse frequency with interference. Low-speed pulse input unit: 0.05us; High-speed pulse input unit: 0.01us.

If set value is overly large, it will affect the receiving of high frequency command pulse and wth high delay time.

Pr1.35 formula:

Filter frequency =
$$\frac{1}{2 \times Pr1.35 \times 0.05us} \times 1000000Hz$$

Example: Pr1.35=100, pulse frequency > 100KHz will be filtered;

Pr1.35	Filter frequency	Pr1.35	Filter frequency
0	Null	100	100kHz(500KHz)
8	1.25MHz(6.25MHz)	125	80kHz(400KHz)
10	1MHz(5MHz)	160	62.5kHz(312KHz)
20	500kHz(2.5MHz)	200	50kHz(250KHz)
50	200kHz(1MHz)		
80	125kHz(625KHz)		



3.2.3 [Class 2] Vibration suppression

Pr2.00	Label	Adaptive filtering mode settings			Valid mode(s)	P S
	Range	0~4	Unit	_	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0x0201
	Valid	Immediate				
			•			•
	Value			Descri	intion	

Value		Description
0	Adaptive filter: invalid	Parameters related to 3 rd notch filter remain unchanged
1	Adaptive filter: 1 filter valid for once.	1 adaptive filter becomes valid. 3 rd notch filter related parameters updated accordingly. Pr2.00 switches automatically to 0 once updated.
2	Adaptive filter: 1 filter remains valid	1 adaptive filter becomes valid. 3 rd notch filter related parameters will keep updating accordingly.
3-4	Reserved	-

Pr2.01	Label	1 st notch frequency			Valid mode(s)	P	S	T
	Range	50~4000	Unit	Hz	Default	4000		
112.01	Byte length	16bit	Attribute	R/W	485 address	0x020	3	
	Valid	Immediate						

Set center frequency of 1st torque command notch filter.

Set Pr2.01 to 4000 to deactivate notch filter

		Label	1 st notch widt	h		Valid mode(s)	Р	S	T	
	Pr2.02	Range	0~20	Unit		Default	4	4		
		Byte length	16bit	Attribute	R/W	485 address	0x020)5		
		Valid	Immediate							

Set notch bandwidth for 1st resonant notch filter.

Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.01 and Pr2.03, Pr2.02 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings

	Label	1 st notch dep	th		Valid mode(s)	P	S	T	
Dr2 02	Range	0~99	Unit	l	Default	0	0		
Pr2.03	Byte length	16bit	Attribute	R/W	485 address	0x0207	•		
	Valid	Immediate							

Set notch depth for 1st resonant notch filter.

Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.01 and Pr2.02, Pr2.03 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings



Pr2.04	Label	2 nd notch freq	uency		Valid mode(s)	Р	S	T
	Range	50~4000	Unit	Hz	Default	4000		
F12.04	Byte length	16bit	Attribute	R/W	485 address	0x0209		
	Valid	Immediate						

Set center frequency of 2nd torque command notch filter.

Set Pr2.04 to 4000 to deactivate notch filter

Pr2.05	Label	2 nd notch widt	th		Valid mode(s)	Р	S	T
	Range	0~20	Unit		Default	4		
F12.05	Byte length	16bit	Attribute	R/W	485 address	0x020B		
	Valid	Immediate						

Set notch bandwidth for 2nd resonant notch filter.

Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.06, Pr2.05 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.

	Label	2 ¹¹⁰ notch dep	oth		Valid mode(s)	Р	S	T
D*2.06	Range	0~99	Unit		Default	0		
Pr2.06	Byte length	16bit	Attribute	R/W	485 address	0x020D		
	Valid	Immediate						

Set notch depth for 1st resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.

	Label	3 ^{ra} notch freq	uency		Valid mode(s)	Р	S	T
D-2.07	Range	50~4000	Unit	Hz	Default	4000		
Pr2.07	Byte length	16bit	Attribute	R/W	485 address	0x020F		
	Valid	Immediate						

Set center frequency of 3rd torque command notch filter.

Set Pr2.07 to 4000 to deactivate notch filter

Pr2.08	Label	3 rd notch widt	h		Valid mode(s)	P	S	T
	Range	0~20	Unit	_	Default	4		
Pr2.08	Byte length	16bit	Attribute	R/W	485 address	0x0211		
	Valid	Immediate						

Set notch depth for 3rd resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.

Pr2.09	Label	3 ^{ra} notch dept	:h		Valid mode(s)	Р	S	T
	Range	0~99	Unit		Default	0		
F12.09	Byte length	16bit	Attribute	R/W	485 address	0x0213		
	Valid	Immediate						

Set notch depth for 3rd resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.



	Label	1 st damping frequency			Valid mode(s)	P
Dr2 44	Range	0/10~2000	Unit	0.1Hz	Default	0
Pr2.14	Byte length	16bit	Attribute	R/W	485 address	0x021D
	Valid	Immediate				

Set Pr2.16 to 0 to deactivate this parameter.

To suppress wobble at load end. Often used when wobble of flexible structure due to high deceleration upon stopping. Especially effective for wobble with frequencies under 100Hz. Set Pr2.15 to wobble frequency (wobble frequency can be determined using tracing function of Motion Studio)

	Label	2 nd damping frequency			Valid mode(s)	P
Pr2.16	Range	0/10~2000	Unit	0.1Hz	Default	0
P12.10	Byte length	16bit	Attribute	R/W	485 address	0x0221
	Valid	Immediate				


Set Pr2.16 to 0 to deactivate this parameter.

To suppress wobble at load end. Often used when wobble of flexible structure due to high deceleration upon stopping. Especially effective for wobble with frequencies under 100Hz. Set Pr2.16 to wobble frequency (wobble frequency can be determined using tracing function of Motion Studio)

	Label Position command smoothing filter				Valid mode(s)	P
Pr2.22	Range	0~32767	Unit	0.1ms	Default	0
P12.22	Byte length 16bit Attribute R/W		R/W	485 address	0x022D	
	Valid	At stop				

To set time constant of 1 time delay filter of position command.

To set time constant of 1 time delay filter, according to target velocity Vc square wave command as show below.




Usually applied when there is rather sharp acceleration which might cause motor overshoot or undershoot. To smoothen command signal, reduces impact to machines and eliminate vibration. If Pr2.22 is set too high, overall time will be lengthened.




	Label Position command FIR filter				Valid mode(s)	P
Pr2.23	Range	0~2500	Unit	0.1ms	Default	0
112.20	Byte length	16bit	Attribute	R/W	485 address	0x022F
	Valid	At stop				

As shown below, when target velocity Vc square wave command reaches Vc, it becomes trapezoidal wave after filtering.



As shown below, when target velocity Vc trapezoidal command reaches Vc, it becomes S wave after filtering.



Usually applied when there is rather sharp acceleration which might cause motor overshoot or undershoot. To smoothen command signal, reduces impact to machines and eliminate vibration. If Pr2.23 is set too high, overall time will be lengthened.

Note: Please wait for command to stop and after filter idle time to modify Pr2.23. Filter switching time = $(Pr2.23 \text{ set value } \times 0.1 \text{ms} + 0.25 \text{ms})$



3.2.4 [Class 3] Velocity/Torque control


	Label	Velocity inter	nal/external s	switching	Valid mode(s)	S
D 0 00	Range	0~3	Unit	_	Default	1
Pr3.00	Byte length	16bit	Attribute	R/W	485 address	0x0301
	Valid	Immediate				

Connect to the right DI to control internal command velocity settings.

Value	Velocity settings
0	Analog - Velocity command (SPR)
[1]	Internal velocity settings 1 st – 4 th speed (Pr3.04~Pr3.07)
2	Internal velocity settings 1 st – 3 rd speed(Pr3.04~P3.06)、Analog velocity command(SPR)
3	Internal velocity settings 1 st – 8 th speed (Pr3.00~Pr3.11)

Value	Internal command velocity 1 (INTSPD 1)	Internal command velocity 2 (INTSPD2)	Internal command velocity 3 (INTSPD3)	Velocity command
	OFF	OFF		1 st speed
1	ON	OFF	No effect	2 nd speed
'	OFF	ON	No enect	3 rd speed
	ON	ON		4 th speed
	OFF	OFF		1 st speed
	ON	OFF		2 nd speed
2	OFF	OFF ON No effe		3 rd speed
	ON	ON		Simulated speed
	Similar to	Pr3.00=1	OFF	1 st – 4 th speed
	OFF	OFF	ON	5 th speed
3	ON	OFF	ON	6 th speed
	OFF	ON	ON	7 th speed
	ON	ON	ON	8 th speed

Please change internal command velocity as per diagram below as unexpected axis movement might occurs if 2 command velocities are changed at the same time.





	Label	Velocity comma		al	Val	id mode(s)		S
Pr3.01	Range	0~1	Unit	_	Def	ault	0	
	Byte length	16bit	Attribute	R/W	485	address	0x0303	
	Valid	Immediate						
	To set positiv	e/negative direction	of velocity of	ommand				
	Value	Velocity settings (Analog or internativelocity)	al sign se	Velocity command sign selection (VC SIGN)		Velocity co directi		
	[0]	+	No	o effect	Pos		ve	
		_	No effect			Negative		
	1	No effect	OFF			Positive		
		No effect		ON		Negat	ive	٦


	Label	Velocity com	mand input g	gain	Valid mode(s)		S	
Pr3.02	Range	10~2000	Unit	(r/min)/V	Default	500		
110.02	Byte length	16bit	Attribute	R/W	485 address	0x030	5	
	Valid	Immediate						

To set gain changes from voltage added onto analog velocity command (SPR) to motor command velocity

Pr3.02 sets command input voltage and rotational speed slope.

Factory default: Pr3.02=500(r/min)/V. Hence 6V input: 3000 r/min

- 1. Do not supply more than ±10V power for analog velocity command (SPR).
- 2. If Pr3.02 set value is too large, it might cause vibration.





	Label	Velocity command input inversion			Valid mode(s)		S	
Pr3.03	Range	0~1	Unit	_	Default	0		
P13.03	Byte length	16bit	Attribute	R/W	485 address	0x0307	7	
	Valid	Immediate						

To set voltage polarity of analog velocity command.

Only valid when Pr3.01 = 0. When Pr3.01 = 1, rotational direction is only related to VC-SIGN.

Value		Motor rotational direction				
[0]	Not	「Positive voltage 」 → 「Positive direction 」				
	inversed	\[\int Negative voltage \] → \[\int Negative direction \]				
1	Inversed	\[\int \text{Positive voltage } \] \[\] \[\text{Positive direction } \]				
		「Negative voltage」 → 「Negative direction」				

If there is an external position sensor with different polarity from Pr3.03, motor might undergo abnormal motion.

Pr3.04 Range		Label	1st speed of vel	ocity setting		Valid mode(s)	S
Pr3.04 Byte length 16bit					r/min		
Pr3.05 Range	Pr3.04	Byte length		Attribute	R/W	485 address	0x0309
Pr3.05 Range		Valid	Immediate				
Pr3.05 Byte length 16bit Attribute R/W A85 address 0x030B		Label	2nd speed of velocity setting			Valid mode(s)	S
Pr3.06 Byte length 16bit Attribute R/W 485 address 0x030B	D=2.05	Range	-10000~10000	Unit	r/min	Default	0
Pr3.06 Range	P13.05	Byte length	16bit	Attribute	R/W	485 address	0x030B
Pr3.06 Range		Valid	Immediate				
Pr3.06 Byte length 16bit Attribute R/W 485 address 0x030D		Label	3rd speed of vel	ocity setting		Valid mode(s)	S
Pr3.07 Byte length 16bit Attribute R/W 485 address 0x030D	Dr2 06	Range	-10000~10000	Unit	r/min	Default	0
Pr3.07 Label	F13.00	Byte length	16bit	Attribute	R/W	485 address	0x030D
Pr3.07 Range -10000~10000 Unit r/min Default 0 Byte length 16bit Attribute R/W 485 address 0x030F Pr3.08 Label 5th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default 0 Byte length 16bit Attribute R/W 485 address 0x0311 Pr3.09 Label 6th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default 0 Byte length 16bit Attribute R/W 485 address 0x0313 Pr3.10 Range -10000~10000 Unit r/min Default Byte length 16bit Attribute R/W 485 address 0x0315 Pr3.11 Byte length 16bit Attribute R/W 485 address 0x0317 Pr3.11 Byte length		Valid	Immediate				
Pr3.07 Byte length 16bit		Label	4th speed of vel	ocity setting		Valid mode(s)	S
Pr3.08 Byte length 16bit Attribute R/W 485 address 0x030F	Dr2 07	Range	-10000~10000	Unit	r/min	Default	0
Pr3.08 Eabel 5th speed of velocity setting Valid mode(s) S	F13.07	Byte length	16bit	Attribute	R/W	485 address	0x030F
Range		Valid	Immediate				
Pr3.08 Byte length 16bit Attribute R/W 485 address 0x0311		Label	5th speed of velocity setting				S
Pr3.09 Byte length 16bit Attribute R/W 485 address 0x0311	Dr2 00	Range	-10000~10000	Unit	r/min	Default	0
Pr3.09 Comparison Compari	F13.06	Byte length	16bit	Attribute	R/W	485 address	0x0311
Pr3.09 Range		Valid	Immediate				
Pr3.09 Byte length 16bit Attribute R/W 485 address 0x0313		Label	6th speed of vel	ocity setting		Valid mode(s)	S
Pr3.10 Byte length 16bit Attribute R/W 485 address 0x0313	Dr3 00		-10000~10000	Unit	r/min	Default	0
Pr3.10 Label 7th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default Valid mode(s) S Label 8th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default Byte length 16bit Attribute R/W 485 address 0x0317 Valid Immediate	F13.09	Byte length	16bit	Attribute	R/W	485 address	0x0313
Pr3.10 Range		Valid	Immediate				
Pr3.10 Byte length 16bit Attribute R/W 485 address 0x0315 Valid Immediate Valid mode(s) S Label 8th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default 0 Byte length 16bit Attribute R/W 485 address 0x0317 Valid Immediate Immediate		Label	7th speed of vel	ocity setting		Valid mode(s)	S
Byte length 16bit Attribute R/W 485 address 0x0315	Dr2 10	Range	-10000~10000	Unit	r/min	Default	
Pr3.11 Label 8th speed of velocity setting Valid mode(s) S Range -10000~10000 Unit r/min Default 0 Byte length 16bit Attribute R/W 485 address 0x0317 Valid Immediate	113.10	Byte length	16bit	Attribute	R/W	485 address	0x0315
Byte length 16bit Attribute R/W 485 address 0x0317 Valid Immediate 0		Valid	Immediate				
Byte length 16bit Attribute R/W 485 address 0x0317 Valid Immediate		Label	8th speed of vel	ocity setting			S
Byte length16bitAttributeR/W485 address0x0317ValidImmediate	Dr2 44	Range	-10000~10000	Unit	r/min	Default	0
Valid Immediate	P13.11	Byte length	16bit	Attribute	R/W	485 address	0x0317
To set internal velocity command 1 st .8 th speed							
ro set internat velocity contination in so speed		To set interna	l velocity commar	nd 1 st -8 th spe	ed	•	



	Label	Acceleration	time settings		Valid mode(s)	S
Pr3.12	Range	0~10000	Unit	ms/ (1000rpm)	Default	100
	Byte length	16bit	Attribute	R/W	485 address	0x0319
	Valid	Immediate				
	Label	Deceleration	Deceleration time settings			S
Pr3.13	Range	0~10000	Unit	ms/ (1000rpm)	Default	100
	Byte length	16bit	Attribute	R/W	485 address	0x031B
	Valid	Immediate				


Set max acceleration/deceleration for velocity command.

If target velocity = x [rpm], max acceleration = a [unit: rpm/ms], acceleration time = t [ms] Pr3.12 = 1000/a

Pr3.13 = 1000/a

a = x/t

For example: If motor is to achieve 1500rpm in 30s, a=1500/30=50rpm/ms Pr3.12 = 1000/a=20. Hence when Pr3.12 = 20, motor can achieve 1500rpm in 30s.




Usually used when there is rapid acceleration or trapezoidal wave velocity command due to many different internal speed segments under velocity control mode which causes instable while motor in motion.

Under velocity control mode, 6083 and 6084 is limited by Pr3.12 and Pr3.13 correspondingly.



	Label	Sigmoid accele settings	ration/decele	ration	Valid mode(s)	S
Pr3.14	Range	0~1000	Unit	ms	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0x031D
	Valid	After restart				

To set sigmoid acceleration and deceleration turning point in accordance to Pr3.12 and Pr3.13.



	Label	Zero speed selection	clamp functio	n	Valid mode(s)		S	
Pr3.15	Range	0~3	Unit	_	Default	0		
	Byte length 16bit Attribute R/W		485 address	0x031F	1			
	Valid	Immediate						

Value	Zero speed clamp function
0	Invalid: zero speed clamp deactivated
1	Velocity command is forced to 0 when the zero speed clamp (ZEROSPD) input signal is valid.
2	Velocity command is forced to 0 when actual velocity is lower than Pr3.16.
3	Includes conditions from 1 and 2

	Label	Zero speed clamp level			Valid mode(s)	S
Pr3.16	Range	10~2000	Unit	r/min	Default	30
P13.10	Byte length	16bit	Attribute	R/W	485 address	0x0321
	Valid	Immediate				

Valid when Pr3.15 = 2/3, velocity command is forced to 0 when actual velocity is lower than Pr3.16 and after static time set in Pr3.23.

	Label	Torque intern	al/external s	witching	Valid mode(s)		T	
D=2.47	Range	0~3	Unit		Default	0		
Pr3.17	Byte length	16bit	Attribute	R/W	485 address	0x0323	}	
	Valid	Immediate						

Value	Torque command input	Velocity limit input
[0]	Analog input 3(AI 3)	Pr3.21 set value
1	Analog input 3(AI 3)	Analog input 1(Al 1)
2	Pr3.22 set value	Pr3.21 set value




	Label Torque comma		d direction se	election	Valid mode(s)		Т
D-2.40	Range	0~1	Unit		Default	0	
Pr3.18	Byte length	16bit	Attribute	R/W	485 address	0x032	25
	Valid	Immediate					
	To set torque	command positive/r	negative dire	ction			
	Value	Direction settings					
	TC-SIGN ON/OFF has no effect on torque direction Torque command input 「Positive 」→Positive direction Negative 」→Negative direction						
	1	Use TC-SIGN ON/O OFF: Positive direc					

Pr3.19	Label	Torque comn	nand input ga	ain	Valid mode(s)	Т
	Range	10~100	Unit	0.1V/100%	Default	30
F13.19	Byte length	16bit	Attribute	R/W	485 address	0x0327
	Valid	Immediate				
	To set gain cha	anges from vol	tage added c	onto analog to	rque command (TR	QR) to torque

To set gain changes from voltage added onto analog torque command (TRQR) to torque command (%)

- ·Unit: (0.1V/100%) 。
- •Set input voltage required for rated output torque.
- ·Default = 30, which is 3V/100%



Pr3.20	Label	Torque comma	nd input inver	sion	Valid mode(s)	T
	Range	0~1	Unit	_	Default	0
P13.20	Byte length	16bit	Attribute	R/W	485 address	0x0329
	Valid	Immediate				

To set voltage polarity of analog torque command.

Only valid when Pr3.18 = 0.

Value		Motor torque direction				
[0]	Not	「Positive voltage 」 → 「Positive direction 」				
	inversed	\[\text{Negative voltage } \] \[\text{Negative direction } \]				
1	Inversed	「Positive voltage 」 → 「Positive direction 」				
		「Negative voltage」 → 「Negative direction」				



D-2 04	Label	Velocity limit in to	Velocity limit in torque mode			T			
	Range	0~10000	Unit	r/min	Default	0			
Pr3.21	Byte length	16bit	Attribute	R/W	485 address	0x032B			
	Valid	Immediate							
	To set velocity limit in torque control mode. Only valid when Pr3.17 = 0 / 2.								

Pr3.22	Label	Torque command			Valid mode(s)		T	
	Range	0~300	Unit	%	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x032D		
	Valid	Immediate						
	To set torque limit in torque control mode. Only valid when Pr3.17 = 2.							
	Please refer to Pr3.17.							

Pr3.23	Label	Zero speed delay time in velocity mode			Valid mode(s)	S			
	Range	0~2000	Unit	ms	Default	0			
	Byte length	16bit	Attribute	R/W	485 address	0x032F			
	Valid	Immediate							
To set the time interval between axis reaches zero speed level and the moment it totally stops.									
Used when axis crawls under velocity mode. Set 0 to deactivate this parameter.									

Pr3.24	Label	Maximum motor rotational speed			Valid mode(s)	P	S	T
	Range	0~10000	Unit	r/min	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x0331		
	Valid	Immediate						
	To set maximur	n motor rotationa	al speed but r	ot higher th	nan motor rated sp	eed		
	If $Pr3.24 = 0$, m	aximum motor ro	otational spee	d = max. s	peed in motor para	ameter.		

Pr3.29	Label	Analog 1 clamping voltage			Valid mode(s)			Т
	Range	0~20000	Unit	mν	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x033I		
	Valid	Immediate						
	Only valid whe When Pr3.17=		o 0 if analog ′	I voltage i	s below Pr3.29 set	t value.		
Pr3.30	Label	Analog 3 clampi	ng voltage		Valid mode(s)			T
	Range	0~20000	Unit	mv	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x033D		
	Valid	Immediate						
	Vallu	IIIIIIediale						

When Pr3.17=1 / 0, velocity is set to 0 if analog 1 voltage is below Pr3.30 set value.



3.2.5 [Class 4]I/O Monitoring Settings

	Label	Input selection DI3			Valid mode(s)	P S T
Pr4.00	Range	0x00~0xFF	Unit	_	Default	0x2
	Byte length	16bit	Attribute	R/W	485 address	0x0401
	Valid	Immediate				

Please refer to the table below to set DI signals and table on the right for corresponding pin and parameters

	Symbol	Va	lue
Signal	Symbol	NO	NC
Invalid	_	0	-
Positive limit switch	POT	1	81
Negative limit switch	NOT	2	82
Servo enabled	SRV-ON	3	83
Clear alarm	A-CLR	4	-
Control mode switching	C-MODE	5	85
Gain switching	GAIN	6	86
Clear deviation count	CL	7	-
Command pulse prohibited	INH	8	88
Torque limit switching	TL-SEL	9	89
Command frequency	DIV1	С	8C
divider/multiplier switching			
Internal command velocity 1	INTSPD1	E	8E
Internal command velocity 2	INTSPD2	F	8F
Internal command velocity 3	INTSPD3	10	90
Zero speed clamp	ZEROSPD	11	91
Velocity command sign	VC-SIGN	12	92
Torque command sign	TC-SIGN	13	93
Forced alarm	E-STOP	14	94

CN1&2 PIN	Input	Parameters
6/20	DI3	Pr4.00
7/21	DI4	Pr4.01
8/22	DI5	Pr4.02
9/23	DI6	Pr4.03

Please don't set anything other than listed in table above.

Normally open (NO): Valid when input = ON Normally close (NC): Valid when input = OFF

Er210 might occur if same function is allocated to different channels at the same time

Servo enabled (SRV-ON) has to be allocated to enabled servo drive.

Inputs related to Pr-mode:

Cianal	Cumbal	Value			
Signal	Symbol	NO	NC		
Trigger command	CTRG	20	A0		
Home	HOME	21	A1		
Forced stop	STP	22	A2		

Signal	Cumbal	Value			
Signal	Symbol	NO	NC		
Positive JOG	PJOG	23	A3		
Negative JOG	NJOG	24	A4		
Positive limit	PL	25	A5		



Negative limit	NL	26	A6
Origin	ORG	27	A7
Path address 0	ADD0	28	A8
Path address 1	ADD1	29	A9
Path address 2	ADD2	2A	AA
Path address 3	ADD3	2B	AB

Note: CTRG, HOME are edge triggered, please make sure electronic bits last 1ms or above.

	Label	Input selection D	14		Valid mode(s)	P	S	T
5.4.04	Range	0x0~0xFF	Unit	_	Default		0x1	
Pr4.01	Byte length	16bit	Attribute	R/W	485 address		0x0403	
	Valid	Immediate						
	Label	Input selection D	l5		Valid mode(s)	P	S	T
D 4 00	Range	0x0~0xFF	Unit		Default	0x0		
Pr4.02	Byte length	16bit	Attribute R/W 485 address		0x0405			
	Valid	Immediate						
	Label	Input selection DI6			Valid mode(s)	P	S	T
D-4.02	Range	0x0~0xFF	Unit	1	Default	0x6		
Pr4.03	Byte length	16bit	Attribute R/W 485 address		485 address	0x0407		
	Valid	Immediate						
	DI4~DI6alloca	tion is the same a	s DI1. Pleas	e refer to l	Pr4.00.			

	Label	Output selection DO1			Valid mode(s)	P	S	T
Pr4.10	Range	0x0~0xFF	Unit		Default	0x3		
	Byte length	16bit	Attribute	R/W	485 address	0x041	5	
	Valid	Immediate						

Please allocate DO as per table below. ALARM logic is the opposite of others

Value		Signal	Symbol
NO	NC	Signal	Symbol
00	80	Invalid	_
01	81	Alarm	ALARM
02	82	Servo-Ready	SRDY
03	83	External brake released	BRK-OFF
04	84	Positioning completed	INP
05	85	At-speed	AT-SPPED
06	86	Torque limit signal	TLC
07	87	Zero speed clamp detection	ZSP
08	88	Velocity coincidence	V-COIN
12	92	Servo Status	SRV-ST
15	95	Positive limit valid	POT-OUT
16	96	Negative limit valid	NOT-OUT
0B	8B	Position command ON/OFF	P-CMD
0F	8F	Velocity command ON/OFF	V-CMD
0D	8D	Velocity limit signal	V-LIMIT
14	94	Position comparison	CMP-OUT



Same signal can be assigned to multiple different outputs.

Normally open(NO): Active low Normally close(NC): Active high

Err212 might occur if output is allocated to signals other than listed in the table above.

Outputs related to PR-mode

Signal	Cumbal	Value			
Signal	Symbol	NO	NC		
Command completed	CMD-OK	20	A0		
Path completed	PR-OK	21	A1		
Homing done	HOME-OK	22	A2		

Note: CMD-OK indicates PR command is sent by axis might not yet be in position. PR-OK indicates axis is in place.

	Label	Output selection DO2			Valid mode(s)	P	S	Т
D-4.44	Range	0x0~0xFF	0x0~0xFF Unit _ Default		Default	0x2		
Pr4.11	Byte length	16bit	Attribute	R/W	485 address	0x0417		
	Valid	Immediate						
	Label	Output selection DO3			Valid mode(s)	Р	S	Т
D::4.40	Range	0x0~0xFF	Unit	_	Default	0x1		
Pr4.12	Byte length	16bit	Attribute	R/W	485 address	0x0419		
	Valid	Immediate						

DO2/DO3 is allocated by the same method as per DO1. Please refer to Pr4.10.

	Label	Analog input 1(Al-1) Zero dri	ft settings	Valid mode(s)	S		
5 4 66	Range	-1860~1860	Unit	5.37mv	Default	0		
Pr4.22	Byte length	16bit	Attribute	R/W	485 address	0x042D		
	Valid	Immediate						
To set zero drift compensation value on analog input 1 voltage for zero drift correction.								
	Label	Analog input 1(AI-1) filter		Valid mode(s)	S		
Pr4.23	Range	0~6400	Unit	0.01ms	Default	0		
114.23	Byte length	16bit	Attribute	R/W	485 address	0x042F		
	Valid	Immediate						
	To set a delay voltage will be		cient for AI1 in	put voltage	. When filter time	takes effect, input		
	Label	Analog input 1(Al-1) overvoltage settings			Valid mode(s)	S		
Pr4.24	Range	0~100	Unit	0.1V	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x0431		
	Valid	Immediate						
	Pr4.24 is invalid when set to 0. Er270 might occur when the input voltage of Al1 is higher than the voltage after zero drift correction.							



Pr4.31	Label	Positioning	g complete ra	ange	Valid mode(s)	P
	Range	0~ 10000	Unit	Pr5.21 set unit	Default	20
	Byte length	16bit	Attribute	R/W	485 address	0x043F
	Valid	Immediate				

To set position deviation range of INP1 positioning completed output signal. INP1 output signal will be valid once position is complete within the range of deviation set.

Default unit: 0.00001rev. Can be set on Pr5.21 as command unit (pulse) or encoder unit (pulse)


	Label	Positioning con	nplete output	setting	Valid mode(s)	P					
	Range	0~4	Unit	_	Default	1					
Pr4.32	Byte length	16bit	Attribute	R/W	485 address	0x0441					
	Valid	Immediate									
	To set condition	ons for INP1 outp									
	Value	Positioning c	ompleted sig	gnal							
	0	Signal valid wh	nen the positi	on deviation	n is smaller than F	Pr4.31					
	1	Signal valid wheel smaller than P		o position o	command and pos	sition deviation is					
	2				command, zero-sp ositional deviation						
	3		Signal valid when there is no position command and position deviation is smaller than Pr4.31. Signal ON when within the time set in Pr4.33 otherwise OFF.								
	4	in Pr4.33.	nen there is r	·		er the delay time set sitional deviation is					
	Label	INP positioning	delay time		Valid mode(s)	P					
	Range	0~15000	Unit	1ms	Default	0					
Pr4.33	Byte length	16bit	Attribute	R/W	485 address	0x0443					
	Valid	Immediate									
	Valid when Pr	4.32 = 3.		•	•						
	Set value	Positioning co	ompleted sig	gnal							
	0	Indefinite delay	/ time, signal	ON until ne	ext position comm	and					
	1-15000	OFF within the position comm		l after time s	set. Switch OFF a	fter receiving next					



Pr4.34	Label	Zero speed		Valid mode(s)	Р	S	Т	
	Range	1~2000	Unit	r/min	Default	50		
	Byte length	16bit	Attribute	R/W	485 address	0x0445		
	Valid	Immediate						

To set threshold value for zero speed clamp detection.

Zero speed clamp detection (ZSP) output signal valid when motor speed goes under the value set in Pr4.34




Pr4.35	Label	Velocity coincidence range			Valid mode(s)	S
	Range	10~2000	Unit	r/min	Default	50
	Byte length	16bit	Attribute	R/W	485 address	0x0447
	Valid	Immediate				

If the difference between velocity command and motor actual speed is below Pr4.35, Velocity coincidence (V-COIN) output signal valid.

Due to 10RPM hysteresis:


Velocity coincidence output OFF -> ON timing (Pr4.35 -10) r/min Velocity coincidence output ON -> OFF timing (Pr4.35 +10) r/min





Pr4.36	Label	Reached velocity			Valid mode(s)	S		
	Range	10~2000	Unit	r/min	Default	1000		
	Byte length	16bit	Attribute	R/W	485 address	0x0449		
	Valid	Immediate						
When motor velocity > Pr4.36, AT-speed output signal is valid.								
	D ()	400041						

Detection using 10RPM hysteresis.




Pr4.37	Label	Holding brake deactivation delay time			Valid mode(s)	Р	S	T
	Range	0~3000	Unit	1ms	Default	150		
	Byte length	16bit	Attribute	R/W	485 address	0x044B		
	Valid	Immediate						

To set delay time for holding brake to be activated after motor power off to prevent axis from sliding.

When Pr5.06 = 0, SRV-ON signal is off, holding brake is activated (delay time is determined by Pr4.39 or Pr6.14). Motor powered-off once delay time set in Pr4.37 is due.

Pr4.38	Label	Holding brake activation delay time			Valid mode(s)	P.	S	T
	Range	0~3000	Unit	1ms	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x044	ID.	
	Valid	Immediate						

To set delay time for holding brake to be released after motor power on. Motor will remain at current position and input command is masked to allow holding brake to be fully released before motor is set in motion.





- *1: Delay time set in Pr4.38
- *2: Delay time from the moment BRK_OFF signal is given until actual holding brake is released or BRK_ON signal is given until actual holding brake is activated. It is dependent on the holding brake of the motor.
- *3: Deceleration time is determined by Pr6.14 or if motor speed goes below Pr4.39, whichever comes first. BRK_OFF given after deceleration time.
- *4: Pr4.37 set time value.

Delay time from the moment SRV_ON is given until BRK_OFF switch to BRK_ON, is less than 500ms.

		Label	Emergency stop function			Valid mode(s)	P	S	T
	Range	0~1	Unit		Default	0			
P	Pr4.43	Byte length	16bit	Attribute	R/W	485 address	0x0457		
	Valid	Immediate							

Value	Description.
[0]	Emergency stop is valid, servo driver will be forced to STOP and Err570 occurs.
1	Emergency stop is invalid, servo driver will not be forced to STOP. Servo can be enabled once E-STOP signal is cleared.



3.2.6 [Class 5] Extension Settings

	Label	2 nd pulse count per revolution			Valid mode(s)	P
	Range	0-67108864	Unit	PULSE	Default	10000
Pr5.00	Byte length	32bit	Attribute	R/W	485 address	H: 0x0500
						L: 0x0501
	Valid	After restart				

Switch between Pr0.08 and Pr5.00 with DI signal DIV1.

When switch to Pr5.00:

(1) Pr5.00 valid when \neq 0:

Motor revolution = Input pulse count / [Pr5.00 set value]

(2) Pr5.00 invalid when = 0:

Actual position pulse count is according to Pr5.01 and Pr5.02.

Switching with DIV1 signal only valid when servo drive is re-enabled.

	Label	2 nd Command freq divider/multiplier n			Valid mode(s)	Р				
Pr5.01	Range	1~1073741824	Unit	_	Default	1				
F13.01	Byte length	32bit	Attribute	R/	485 address	H: 0x0502				
				W		L: 0x0503				
	Valid	After restart								
To set command pulse input frequency division and multiplication numerator										
	Label	2 nd Command frequency divider/multiplier denominator			Valid mode(s)	P				
Pr5.02	Range	1~1073741824	Unit	_	Default	1				
P15.02	Byte length	32bit	Attribute	R/	485 address	H: 0x0504				
				W		L: 0x0505				
	Valid	After restart								
To set command pulse input frequency division and multiplication denominator. Please refer to Pr0.09 and Pr0.10. Switch using DIV1 signal										

	Label	Driver prohibition	n input settin	gs	Valid mode(s)	P	S	T		
	Range	0/1/2	Unit	ĺ	Default	0				
Pr5.04	Byte length	16bit	Attribute	R/W	485 address	0x0509				
	Valid	Immediate								
To set driver prohibition input (POT/NOT)										
	Value			escription						
	0	POT → Positive	direction driv	ve prohibite	d					
		NOT → Negative	e direction di	ive prohibit	ed					
	1	POT and NOT in	POT and NOT invalid							
	2	Any single sided	input from F	OT or NOT	might cause Er26	60				

	Label	Servo-off mode		Valid mode(s)	P	S	T	
D.5.00	Range	0~1	Unit		Default	0		
Pr5.06	Byte length	16bit	Attribute	R/W	485 address	0x050	OD	
	Valid	Immediate						



To set servo driver disable mode and status.

Set value	Explanation
0	Driver disables after velocity reaching value set in Pr4.39
1	Driver disables immediately, axis in free stopping mode

	Label	Servo braking t	orque setting		Valid mode(s)	Р	S	T
D.E 44	Range	0~500	Unit	%	Default	0		
Pr5.11	Byte length	16bit	Attribute	R/W	485 address	0x05′	17	
	Valid	Immediate						

To set torque limit for servo braking mode.

If Pr5.11 = 0, use torque limit as under normal situation.

Please note that if Pr5.11 set value is too low, emergency stop will take longer.

	Label	Overload level	Overload level setting V		Valid mode(s)	P S T
Pr5.12	Range	0~115	Unit	%	Default	0
P15.12	Byte length	16bit	Attribute	R/W	485 address	0x0519
	Valid	Immediate				

- When set to 0, overload level = 100%.
- Set to 0 under regular usage. Lowering overload level will cause motor to overload in shorter time.
- Er100 occurs when driver output current higher than motor rated current (overload) Er101 occurs when driver output current lower than motor rated current

	Label	Overspeed leve	Valid mode(s)	Р	S	T		
Range 0~10000 Unit		Unit	r/min	Default	0			
Pr5.13	Byte length 16bit Attribute R/W 485 address 0x		0x051	В				
	Valid	Immediate						
	If motor speed exceeds Pr5.13, Er1A0 might occur.							
	When Pr5.13 =	= 0, overspeed le	evel = max. m	otor speed	x 1.2			

	Label	I/O digital filter			Valid mode(s)	P	S	T
Pr5.15	Range	0~255	Unit	0.1ms	Default	0		
P15.15	Byte length	16bit	Attribute	R/W	485 address	0x051	F	
	Valid	After restart						
	Digital filtering of I/O input. Overly large value set will cause control delay.							

	Label	Counter clearing	input mode		Valid mode(s)	P	
Pr5.17	Range	0~4)~4 Unit —		Default	3	
F13.17	Byte length	16bit	Attribute	R/W	485 address	0x0523	
	Valid	Immediate					

To set the clearing conditions for deviation counter clearing input signal.

Value	Condition
0/2/4	Invalid
1	Always clear
3	Clear only once (Rising edge trigger)



	Label	Position unit settings			Valid mode(s)	P
D.5.00	Range	0~2	Unit	_	Default	1
Pr5.20	Byte length	16bit	Attribute	R/W	485 address	0x0529
	Valid	Immediate				

Set unit for position related parameters

Value	Unit	
0	Encoder unit	
1	Command unit	
2	0.0001rev	

Command unit: Pulse from host (Affected by electronic gear ratio) Encoder unit: Pulse from encoder (Related to encoder resolution)

Pr5.20 can only be modified when axis is disabled as it will clear position data

	Label	Torque limit sele	Torque limit selection			P	S	T
Pr5.21 Range		0~6	Unit	_	Default	0		
F13.21	Byte length	16bit	Attribute	R/W	485 address	0x052	В	
	Valid	Immediate						

	Value	Limit		
ľ	0]	1 st torque limit Pr0.13		
1		2 nd torque limitPr5.22		
2	TL-SEL OFF	Pr0.13		
	TL-SEL ON	Pr5.22		
3~	4	Reserved		
5		Pr0.13 →Positive torque limit Pr5.22 →Negative torque limit		

	Label	2 nd torque limit			Valid mode(s)	P	S	T
Pr5.22	Range	0~500	Unit	%	Default	300		
	Byte length	16bit	Attribute	R/W	485 address	0x052	:D	
	Valid	Immediate						

Pr5.22 is limited by max. torque set in motor parameter.

	Label	Positive torque w	varning thres	shold	Valid mode(s)	P	S	T
Pr5.23	Range	0~300	Unit	%	Default	0		
P15.23	Byte length	16bit	Attribute	R/W	485 address	0x052F		
	Valid	Immediate						
	•	hich is 95%. Other	•					
•	If actual torque	e higher than thres	shold TLC to	orque limit s	ignal will be valid			

	Label	Negative torque warning threshold			Valid mode(s)	P	S	Т
Pr5.24	Range	0~300	Unit	%	Default	0		
Pro.24	Byte length	16bit	Attribute	R/W	485 address	0x053	31	
	Valid	Immediate						

Default = 0, which is 95%. Other values only valid when Pr5.21 = 5. If actual torque higher than threshold, TLC torque limit signal will be valid.



	Label	RS485 commu	unication mod	е	Valid mode(s)	Р	S	T
Pr5.29	Range	0~255	Unit		Default	5		
	Byte length	16bit	Attribute	R/W	485 address	0x053	3B	
	Valid	After restart						

Value	Bit	Checksum	Stop
0	8	Even	2
1	8	Odd	2
2	8	Even	1
3	8	Odd	1
4	8	Null	1
(5)	8	Null	2

	Label RS485 communication Baud rate					P	S	T
Pr5.30	Range	0~15	Unit		Default	4		
	Byte length	16bit	Attribute	R/W	485 address	0x053	D	
	Valid	After restart					•	

Value	Baud rate
0	2400bps
1	4800bps
2	9600bps
3	19200bps

Value	Baud rate
[4]	38400bps
5	57600bps
6	115200bps

Baud rate tolerance: 2400~38400bps±0.5%, 57600~115200bps±2%

	Label	RS485 axis ac	RS485 axis address			P	Ø	T
Pr5.31	Range	0~127	Unit	_	Default	1		
F13.31	Byte length	16bit	Attribute	R/W	485 address	0x053	3F	
	Valid	After restart						

When controller is connected to multiple axis and controller needs to identify the axis, Pr5.31 can be used to set the axis ID/address.

Please set to a max of 31 if the communication is between RS232 and RS485

Pr5.32	Label	Max. comman	d pulse input t	frequency	Valid mode(s)	P
	Range	0~8000	Unit	kHz	Default	4100
	Byte length	16bit	Attribute	R/W	485 address	0x0541
	Valid	Immediate				

Please set the max. frequency required for command pulse input. Er1B0 will occur, if command pulse input frequency exceeds Pr5.32.



3.2.7 [Class 6] Other settings


	Label	Encoder zer	Encoder zero position compensation			P	S	T		
Pr6.01	Range	0~360	Unit	Electrical angel	Default 0					
	Byte length	16bit	Attribute	R/W	485 address	0x060)3			
	Valid	Power-off								
Zero position compensation for encoder zero drift to avoid abnormality due to zero drift.										

	Label	JOG trial run	torque comma	and	Valid mode(s)			T
D.: C. 0.0	Range	0~350	Unit	%	Default	350		
Pr6.03	Byte length	16bit	Attribute	R/W	485 address	0x060	0x0607	
	Valid	Immediate						
	To set torque	for JOG trial ru	ın command.					
	Label	JOG trial run velocity command			Valid mode(s)	P	S	Т
D=C 0.4	Range	0~10000	Unit	r/min	Default	30		
Pr6.04	Byte length	16bit	Attribute	R/W	485 address	0x0609	9	
	Valid	Immediate						
	To set velocity	y for JOG trial r	un command.	•		•		

	Label	Position 3 rd ga	in valid time		Valid mode(s)	Р
Pr6.05	Range	0~10000	Unit	0.1ms	Default	0
F10.03	Byte length	16bit	Attribute	R/W	485 address	0x060B
	Valid	Immediate				
	Only available	r 3 rd gain to be verin position modes, set Pr6.05=	de 0, Pr6.06=100			
	Label	Position 3 rd ga	in scale facto	ſ	Valid mode(s)	P
Pr6 06	Range 50~1000 Byte length 16bit		Unit	100%	Default	100
1 10.00			Attribute	R/W	485 address	0x060D
	Valid	Immediate				



Pr1.19.



	Label	Torque command additional value			Valid mode(s)	P	S	T
D.0.07	Range	-100~100	Unit	%	Default	0		
Pr6.07	Byte length	16bit	Attribute	R/W	485 address	0x060	F	
	Valid	Immediate						

To set torque forward feed additional value of vertical axis.

Applicable for loaded vertical axis, compensate constant torque.

Application: When load move along vertical axis, pick any point from the whole motion and stop the load at that particular point with motor enabled but not rotating. Record output torque value from d04, use that value as torque command additional value (compensation value)

	Label	Positive direction compensation v	•		Valid mode(s)	Р	S	Т
Pr6.08	Range	-100~100	Unit	%	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x061	11	
	Valid	Immediate						
	Label	Negative direct	•		Valid mode(s)	Р	S	Т
Pr6.09	Range	-100~100	Unit	%	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x061	13	
	Valid	Immediate						

To reduce the effect of mechanical friction in the movement(s) of the axis. Compensation values can be set according to needs for both rotational directions.

Applications:

1. When motor is at constant speed, d04 will deliver torque values.

Torque value in positive direction = T1;

Torque value in negative direction = T2



$$Pr6.08/Pr6.09 = T_f = \frac{|T1 - T2|}{2}$$

Positive/Negative compensation corresponds to actual position feedback.

Positive torque compensation value = $+(Pr6.08=+T_f)$

Negative torque compensation value = $-(Pr6.08=+T_f)$

Pr6.08 = x, Pr6.09 = y; friction compensation value = |x-y|/2

	Label	Current response settings			Valid mode(s)	Р	S	T
D=C 44	Range	50~100	Unit	%	Default	100		
Pr6.11	Byte length	16bit	Attribute	R/W	485 address	0x0617	7	
	Valid	Immediate						
	To set driver current loop related effective value ratio.							

	Label	Max. time to sto	Max. time to stop after disabling			P	S	T
D=C 4.4	Range	0~1000	Unit	ms	Default	500		
Pr6.14	Byte length	16bit	Attribute	R/W	485 address	0x061	D	
	Valid	Immediate						

To set the max. time allowed for the axis to stop on emergency stop or normal axis disabling. After disabling axis, if motor speed is still higher than Pr4.39 but the time set in Pr6.14 is reached, BRK_ON given and holding brake activated.

BRK_ON given time is determined by Pr6.14 or when motor speed goes below Pr4.39, whichever comes first.

Applications:

- 1. After disabling axis, if motor speed is still higher than Pr4.39 but the time set in Pr6.14 is reached, BRK ON given and holding brake activated.
- 2. After disabling axis, if motor speed is already lower than Pr4.39 but the time set in Pr6.14 is not yet reached, BRK_ON given and holding brake activated.

Dynamic brake will be provide the braking function if the function is activated for motors without holding brake.

	Label	Trial run distand	ce		Valid mode(s)	Р
Pr6.20	Range	0~1200	Unit	0.1rev	Default	10
110.20	Byte length	16bit	Attribute	R/W	485 address	0x0629
	Valid	Immediate				
	JOG (Position	control) : Distan	ce travel of e	ach motion	•	
	Label	Trial run waiting	g time		Valid mode(s)	P
Pr6.21	Range	0~10000	Unit	ms	Default	300
P10.21	Byte length	16bit	Attribute	R/W	485 address	0x062B
	Valid	Immediate				
	JOG (Position	control) : Waiting	g time interva	al after each	n motion cycle	
	Label	No. of trial run of	cycles		Valid mode(s)	P
Pr6.22	Range	0~10000	Unit	_	Default	5
	Byte length	16bit	Attribute	R/W	485 address	0x062D




	Valid	Immediate						
JOG (Position control): No. of cycles When Pr6.22, trial run goes into endless cycles.								
	Label	Trial run accele	ration		Valid mode(s)	P	S	
Pr6.25	Range	0~10000	Unit	ms	Default	200		
F10.25	Byte length	16bit	Attribute	R/W	485 address	0x063	33	
	Valid	Immediate						
To set the acceleration/deceleration time for JOG command between 0 rpm to 1000 rpm								

	Label	Shaft lock cur	rent raising t	Shaft lock current raising time			S	
Pr6.28	Range	0~32767	Unit	%	Default	0		
P10.20	Byte length	16bit	Attribute	R/W	485 address	0x06	39	
	Valid	Immediate						
	Label	Shaft lock du	ration time		Valid mode(s)	Р	S	
Dr6 20	Label Range	Shaft lock du	ration time Unit	μs	Valid mode(s) Default	P 0	S	
Pr6.29				μs R/W	· · · · ·			

	Label	Blocked rotor a threshold	alarm torque		Valid mode(s)	Р	S		
Pr6.56	Range	0~300	Unit	%	Default	300	300		
	Byte length	16bit	Attribute	R/W	485 address	0x06			
	Valid	Immediate							
	output% large If Pr6.56 = 0,	er than threshold blocked rotor ala	ue threshold of blocked rotor to trigger alarm. (Alarm triggered if torque than threshold value & under 10rpm) locked rotor alarm deactivated. is 10rpm or above, Er102 won't be triggered.						
	Label	Blocked rotor a	alarm delay t	ime	Valid mode(s)	P	S		
D.0.57	Range	1~10000	Unit	ms	Default	400			
Pr6.57	Byte length	16bit	Attribute	R/W	485 address	0x06	73		
	Valid	Immediate							
	To set delay time for blocked rotor alarm. Err102 won't be triggered if time doesn't exceed set time in Pr6.57. Blocked rotor alarm is activated by default, alarm torque threshold = 300%, delay time = 400ms; speed threshold = 10rpm;								





	Label	Absolute multiturn data upper limit			Valid mode(s)	Р	S	T
Pr6.63	Range	0~32766	Unit	rev	Default	0		
F10.03	Byte length	16bit	Attribute	R/W	485 address	0x067	'F	
	Valid	After restart						
	I Iso Pr∩ 15 –	2 in rotational mo	de Feedhad	k nosition (cycles hetween 0	and (Pr	6 63±	1) v

Use Pr0.15 = 2 in rotational mode, Feedback position cycles between 0 and (Pr6.63+1) x encoder resolution.

Absolute multiturn data will be set to 0 if reaches upper limit.

3.2.8 [Class 7] Factory settings

*Please take precaution when modifying Class 7 parameters. Might cause driver errors

	Label	Motor model	-		Valid mode(s)	Р	S	Т
D-7.45	Range	0x0~0x7FFF	Unit	_	Default	0x200)	
Pr7.15	Byte length	16bit	Attribute	R/W	485 address	0x071	F	
	Valid	After restart						
	Value			Description	1			
	0x100	Read from EE	PROM					
	[0x200]	Read from End	coder					
	When Pr7.15 =	= 0x200(2xx):						
	Parameter	Label						
	Pr7.00	Current loop g	ain					
	Pr7.01	Current loop in						
	Pr7.05	No. of motor p						
	Pr7.06	Motor phase re	esistance					
	Pr7.07	Motor D/Q ind	uction					
	Pr7.08	Motor back EN	/IF coefficien	t				
	Pr7.09	Motor torque of	coefficient					
	Pr7.10	Motor rated ro	tational spee	:d				
	Pr7.11	Motor max. rot	tational spee	d				
	Pr7.12	Motor rated cu	irrent					
	Pr7.13	Motor rotor ine	ertia		_	•		



Pr7.14	Driver power rating
Pr7.16	Encoder
Pr7.17	Motor max. current
Pr7.18	Encoder index angle compensation

Pr7.16	Label	Encoder			Valid mode(s)	Р	S	T
	Range	0x0~0x200	Unit		Default	Encod	ler	
	Byte length	16bit	Attribute	R/W	485 address	0x072	1	
	Valid	After restart						

3.2.9 [Class 8] PR control parameters

	Label	PR Control			Valid mode(s)	PR			
Pr8.00	Range	0 ~ 65535	Unit	/	Default	0			
	Byte length	16bit	Attribute	R/W	485 address	0X6000			
	It is recomme	ended to modify PF	R control para	meters usi	ng Motion Studio.				
	Bit	3	2	1		0			
	· I	=1, absolute value memory	=1, homing =1, so upon power on limit v		oftware position valid	=0, CTRG rising edge trigger			
		=0, absolute value with no memory	=0, no homi		oftware position not valid	=1, double edges trigger			
	If parameter modifications are done through the front panel or parameters list, please keep in mind that PR control parameters byte are decimal system. For example: If Bit 3, 2, 1, 0 are to be set to 1 (1111). Conversion using decimal system, 1111 = 15, Pr8.00 is to be set to 15.								

	Label	Path count	Path count			PR		
Pr8.01	Range	16	Unit	/	Default	16		
	Byte length	16bit	Attribute	R	485 address	0X6001		
	16 paths							
	Label	Control Operation	n		Valid mode(s)	PR		
Pr8.02	Range	0x0 ~ 0xFFFF	Unit	/	Default	0x0		
	Byte length	16bit	Attribute	R/W	485 address	0X6002		



Attributes of Pr8.02 functions are divided into Read/Write. P refers to positioning motion of *N* path. Please refer to the following table.

Attribute	Address	Description
Write	0x01P	N path positioning
Write	0x020	Reset
Write	0x021	Manually set currently position as 0 (Origin)
Write	0x040	Emergency stop
Read	0x000P	Positioning completed. Ready to receive new data
Read	0x01P,	
	0x020,	Yet to respond to command
	0x040	
Read	0x10P	Path motion undergoing
Read	0x200	Command completed. Waiting for positioning

Label Software positive limit H					Valid mode(s)	PR
Pr8.06	Range	0~ 65535	Unit	Pulse	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0X6006
	High bit of sof	tware positive lim	it; (Only val	id using 48	5 communication)	



	Label	Software positiv	ve limit (L)		Valid mode(s)	PR			
Pr8.07	Range	-2147483648~ 2147483647	Unit	Pulse	Default	0			
	Byte length	32bit	Attribute	R/W	485 address	0X6007			
	To set softwar	e positive limit po	osition (32 bit	base)					
	•	nmunication, only							
		it needs to be rea							
	When software positive limit = 994817, 0x000F2E01(Hexadecimal)								
	high16bit = 0x000F, hence Pr8.05 reading = 0x000F, controller = 15. R/W of high/low bit data is similar when using 485 communication.								
	Label	Software negati		ig 465 con	Valid mode(s)	PR			
D 0 00	Range			Dulaa	Default				
Pr8.08			Unit	Pulse		0			
	Byte length	16bit	Attribute	R/W	485 address	0X6008			
	High bit of soft	ware negative lin	nit; (Only va	lid using 4	85 communication	n)			
	Label	Software negati	ve limit (L)		Valid mode(s)	PR			
Pr8.09	Range	-2147483648~ 2147483647	Unit	Pulse	Default	0			
	Byte length	32bit	Attribute	R/W	485 address	0X6009			
		e positive limit po							
		nmunication, only			<u>-</u>				
	R/W high 16 bit needs to be realized through Pr8.08.								

	Label	Homing mode			Valid mode(s)	PR	
Pr8.10	Range	0~ 0xFFFF	Unit	/	Default	0	
	Byte length	16bit	Attribute	R/W	485 address	0X600A	
	To set homing using Motion	•	node. It is red	commended	I to modify PR co	ntrol parameters	
	Bit	8 (Z-signal homing)	2-7 (Hom	2-7 (Homing mode)		ition 0 (Homing direction)	
	Description	=1, homing with Z-signal =0, homing without Z-signal	=0 Limit ho =1 Origin h =2 Single t homing =3 Torque =8 Immed	noming urn Z	=1, Yes =0, No	=1, Forward =0, Reverse	
	Label	Zero position H			Valid mode(s)	PR	
Pr8.11	Range	0 ~ 65535	Unit /		Default	0	
	Byte length	16bit	Attribute	R/W	485 address	0X600B	
	High bit of zer	o position; (Onl	ly valid using	485 comm	unication)		

	Label	_abel Zero position (L)				PR	
Pr8.12	Range	-2147483648~ 2147483647	Unit	р	Default	0	
	Byte length	32bit	Attribute	R/W	485 address	0X600C	
	To set zero po	sition.					
Using 485 communication, only able to R/W low 16 bit.							
	R/W high 16 b	it needs to be real	ized through	Pr8.11.			



	Label	Home position of	offset H		Valid mode(s)	PR			
Pr8.13	Range	0 ~ 65535	Unit	/	Default	0			
	Byte length	16bit	Attribute	R/W	485 address	0X600D			
		ne position offset	: (Only vali		communication)	1 00000			
	Label	Home position of	•		Valid mode(s)	PR			
D:0.44	Range	-2147483648~			Default				
Pr8.14		2147483647	Unit	р		0			
	Byte length	32bit	Attribute	R/W	485 address	0X600E			
	To set home p								
		nmunication, only			•				
	Label	hit needs to be real. High homing ve		jn Pr8.13.	Valid mode(s)	PR			
Pr8.15	Range	1 ~ 6000	Unit	rom	Default	200			
P16.15				rpm					
	Byte length	16bit	Attribute	R/W	485 address	0X600F			
To set high homing velocity in PR mode.									
	Label	Low homing vel	ocity	1	Valid mode(s)	PR			
Pr8.16	Range	1 ~ 6000	Unit	rpm	Default	50			
	Byte length	16bit	Attribute	R/W	485 address	0X6010			
		oming velocity in PR mode.							
	Label	Homing accelera	ation		Valid mode(s)	PR			
Pr8.17	Range	1 ~ 32767 U	Jnit	ms/Krpm	Default	100			
	Byte length	16bit A	Attribute	R/W	485 address	0X6011			
	To set homing 1000rpm	acceleration time	e in PR mod	le, time nee	ded for Orpm to a	ccelerate to			
	Label	Homing deceler	ation		Valid mode(s)	PR			
Pr8.18	Range	. 0=.0.	Jnit	ms/Krpm	Default	100			
	Byte length		Attribute	R/W	485 address	0X6012			
		deceleration time	e in PR mod	le, time nee	eded for 1000rpm t	to decelerate to			
	0rpm Label	Homing torque I	aoldina tima		Valid mode(s)	PR			
Pr8.19	Range		Jnit	ms	Default	100			
110.19	Byte length		Attribute	R/W	485 address	0X6013			
		torque holding ti		1 1 7 1 7	1	5,10010			
	Label	Homing torque	-		Valid mode(s)	PR			
Pr8.20	Range	0 ~ 65535	Unit	%	Default	100			
10.20	Byte length	16bit	Attribute	R/W	485 address	0X6014			
	To set homing			1000	.00 4441000	0,0011			
1	ro secrionning torque								

Label Homing overtravel alarm range				nge	Valid mode(s)	PR			
Pr8.21	Range	0 ~ 65535	Unit	0.1r	Default	0			
	Byte length	16bit	Attribute	R/W	485 address	0X6015			
	To set homing overtravel alarm threshold.								

	Label	Emergency st	op at limit de	celeration	Valid mode(s)	PR		
Pr8.22	Range	1 ~ 32767	Unit	ms/Krpm	Default	10		
	Byte length	16bit	Attribute	R/W	485 address	0X6016		
	To set position limit emergency stop deceleration.							



	Label	STP emergen	cy stop dece	leration	Valid mode(s)	PR			
Pr8.23	Range	1 ~ 32767	Unit	ms/Krpm	Default	50			
	Byte length	16bit	Attribute	R/W	485 address	0X6017			
	To set STP emergency stop deceleration.								

	To set S	TP er	nergeno	cy stop o	dece	eleration.			
	Label		I/O co	mbinatio	on tr	trigger mode		Valid mode(s)	PR
Pr8.26	Range		0 ~ 65	535	J	Jnit	/	Default	0
	Byte len	gth	16bit		- 1	Attribute	R/W	485 address	0X601A
	Value	Desc	ription				L		
	[0]	Disal	ole I/O c	ombinat	ion t	rigger mod	e. Uses I/O (CTRG signal edge tr	igger.
	1	Enab	le I/O co	ombinati	on t	rigger. Valic	when HOM	E-OK signal is valid	
	2	Enab	le I/O co	ombinati	on t	rigger. HON	1E-OK signal	not required.	
	IO comb	inatio	n trigge	r select	path	n using AD	D0~ADD3.	Trigger mode is	set in Pr8.26.
	ADD3	AD	D2	ADD1		ADD0	Path sele	ction	
	OFF	OF	F	OFF		OFF	Path 0 (N	on-action)	
	OFF	OF	F	OFF		ON	Path1		
	OFF	OF	F	ON		OFF	Path2		
	OFF	OF	F	ON		ON	Path3		
	OFF	ON		OFF		OFF	Path4		
	OFF	ON		OFF		ON	Path5		
	OFF	ON		ON OFF		Path6			
	OFF	ON		ON		ON	Path7		
	ON	OF		OFF		OFF	Path8		
	ON	OF		OFF		ON	Path9		
	ON	OF		ON		OFF	Path10		
	ON	OF	•	ON		ON	Path11		
	ON	ON		OFF		OFF	Path12		
	ON	ON		OFF		ON	Path13		
	ON	ON	•	ON		OFF	Path14		
	ON	ON		ON		ON	Path15		
	Label			mbinatio			<u> </u>	Valid mode(s)	PR
Pr8.27	Range		0 ~ 65	535	Ur		ms	Default	5
	Byte len	_	16bit			tribute	R/W	485 address	0X601B
	To set I/0	O con	nbinatio	n filter ti	ime.				




	Label S-code current output value				Valid mode(s)	PR
Pr8.28	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0X601C

S-code (Status code) is the S-code of currently operating PR positioning data. Every PR path has a S-code setting.

S-code	Sx.H		Sx.L		
Bit	15	8-14	7	0-6	
Description	S-code valid when completed. 0: Invalid, retain previous value 1: Valid	S-code upon completion	S-code valid upon activation 0: Invalid 1: Valid	S-code upon activation	

Sequence diagram



Valid when S1 enabled and S2 completed

S-code bit	bit0/8	bit1/9	bit2/10	bit3/11	bit4/12	bit5/13	Bit6/14
SDx	SD0	SD1	SD2	SD3	SD4	SD5	SD6

	Label	PR warning			Valid mode(s)	PR		
Pr8.29	Range	0x0~0x20F	Unit	/	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0X601D		
	Address	Warning						
	0	Reset new command automatically						
	0x100	Position limit error	during homin	g				
	0x101	Emergency stop. Ho	oming not con	npleted				
	0x102	D2 Homing overtravel alarm						
	0x20x	Position limit error	on Path N					

	Label	JOG velocity			Valid mode(s)	PR			
Pr8.39	Range	0 ~ 65535	Unit	rpm	Default	100			
	Byte length	16bit	Attribute	R	485 address	0X6027			
Set JOG velocity in PR mode.									
	Label	JOG accelera	tion		Valid mode(s)	PR			
Pr8.40	Label Range	JOG accelera 0 ~ 65535	tion Unit	ms/Krpm	Valid mode(s) Default	PR 100			
Pr8.40			1	ms/Krpm	` '				



	Label	JOG decelera	tion		Valid mode(s)	PR
Pr8.41	Range	0 ~ 65535	Unit	ms/Krpm	Default	100
	Byte length	16bit	Attribute	R	485 address	0X6029
	Set JOG dece	leration in PR r	node.			

	Label	Command posit	tion H		Valid mode(s)	PR
Pr8.42	Range	0 ~ 65535 U	Jnit	/	Default	
	Byte length	16bit	Attribute	R	485 address	0X602A
	High bit of cor	nmand position;	(Only valid u	sing 485 c	ommunication)	
	Label	Command posit	tion (L)	Valid mode(s)	PR	
Pr8.43	Range	-2147483648~ 2147483647	Unit	р	Default	
	Byte length	32bit	Attribute	R	485 address	0X602B
	-	nmunication, only it needs to be rea Motor position I	alized through		Valid mode(s)	PR
Pr8.44	Range	0~ 0xFFFF	Unit	/	Default	
	Byte length	16bit	Attribute	R	485 address	0X602C
	High bit of cor	nmand position;	(Only valid u	sing 485 c	ommunication)	
	Label	Motor position	(L)		Valid mode(s)	PR
Pr8.45	Range	-2147483648~ 2147483647	Unit	р	Default	
	Byte length	32bit	Attribute	R	485 address	0X602D
	_	nmunication, only				
	R/W high 16 b	it needs to be rea	alized through	Pr8.44.		

	Label	Input I/O status	1		Valid mode(s)	PR			
Pr8.46	Range	0 ~ 65535	Unit	/	Default				
	Byte length	16bit	Attribute	R	485 address	0X602E			
Input I/O status, displays in decimal system. Convert to binary system to determine which bit is valid.									
	Label	Output I/O statu	JS		Valid mode(s)	PR			
Pr8.47	Range	0 ~ 65535	Unit	/	Default				
	Byte length	16bit	Attribute	R	485 address	0X602F			

	Label	Path 0 S-code	Path 0 S-code			PR	
Pr8.48	Range	0 ~ 65535	Unit	/	Default	0	
	Byte length	16bit	Attribute	R	485 address	0X6030	
Please refer to Pr8.28 for S-code setting.							

	Label	Path 1 S-code			Valid mode(s)	PR
Pr8.49	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6031
Please refer to Pr8.28 for S-code setting.						



	Label Path 2 S-code				Valid mode(s)	PR		
Pr8.50	Range	0 ~ 65535	Unit	/	Default	0		
	Byte length	16bit	Attribute	R	485 address	0X6032		
	Please refer to Pr8.28 for S-code setting.							

	Label	Path 3 S-code			Valid mode(s)	PR
Pr8.51	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6033
	Please refer to					

	Label	Path 4 S-code			Valid mode(s)	PR
Pr8.52	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6034
Please refer to Pr8.28 for S-code setting.						

	Label	Path 5 S-code			Valid mode(s)	PR
Pr8.53	Range	0 ~ 65535	Unit	1	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6035
	Please refer to	Pr8.28 for S-co				

	Label	Path 6 S-code			Valid mode(s)	PR
Pr8.54	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6036
	Please refer to	Pr8.28 for S-co				

	Label	Path 7 S-code			Valid mode(s)	PR
Pr8.55	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X6037
Please refer to Pr8.28 for S-code setting.						

	Label Path 8 S-code				Valid mode(s)	PR		
Pr8.56	Range	0 ~ 65535	Unit	/	Default	0		
	Byte length	16bit	Attribute	R	485 address	0X6038		
	Please refer to Pr8.28 for S-code setting.							

	Label	Path 9 S-code			Valid mode(s)	PR
Pr8.57	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	16bit Attribute R			0X6039
Please refer to Pr8.28 for S-code setting.						

	Label	Path 10 S-code			Valid mode(s)	PR		
Pr8.58	Range	0 ~ 65535	Unit	1	Default	0		
	Byte length	16bit	Attribute	R	485 address	0X603A		
	Please refer to Pr8.28 for S-code setting.							

	Label	Path 11 S-code	}		Valid mode(s)	PR
Pr8.59	Range	0 ~ 65535	Unit	1	Default	0
	Byte length	16bit	Attribute	R	485 address	0X603B
	Please refer to					



	Label	Path 12 S-code)		Valid mode(s)	PR
Pr8.60	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X603C
Please refer to Pr8.28 for S-code setting.						

	Label	Path 13 S-code	!		Valid mode(s)	PR
Pr8.61	Range	0 ~ 65535	Unit	1	Default	0
	Byte length	16bit Attribute R			485 address	0X603D
Please refer to Pr8.28 for S-code setting.						

	Label	Path 14 S-code)		Valid mode(s)	PR
Pr8.62	Range	0 ~ 65535	Unit	1	Default	0
	Byte length	16bit Attribute R			485 address	0X603E
	Please refer to	Pr8.28 for S-co				

	Label	Path 15 S-code	;		Valid mode(s)	PR
Pr8.63	Range	0 ~ 65535	Unit	/	Default	0
	Byte length	16bit	Attribute	R	485 address	0X603F
	Please refer to	Pr8.28 for S-co	de setting.			



3.2.10 [Class 9] PR control path parameters

It is more convenient to set Class 9 parameters on Motion Studio

	Label	PR0 mode		TO OIT WOULD	,,, <u>C</u>	raaro	Valid mode	2(8)	PR	
Pr9.00	Range	0x0~0xFFF		Unit	1	Default	<i>-</i> (3)	0		
113.00	Byte length	16bit	•	Attribute	+	R/W	485 addres		0X6200	
	Dyte length	TODIL		Attribute		\ / V V	+05 addres		070200	
Bit	14	8-13	6-7		5		4	0-3		
Definition		0-15:		solute	0:	No	0: Can be	0: n	ull	
Definition		Jump to		rrespond		erlap,	Interrupt		ositioning	
	I	correspond		mand		dicates	1: Can't be		elocity	
		path	•				Interrupt,	mot	•	
	1: Jump.	patri	mote	•		th SJ Overlap,	indicates		oming	
	Jump to SJ			01		dicated	using!		mergency	
	or CJ					th CJ	domb .	stop		
									cates using	
									/H/S	
								′ ′	, , -	
							l			I .
	Label	PR0 position	on H			Valid mode	e(s)	PR		
Pr9.01	Range	0~ 0xFFFF Unit Pulse					Default		0	
	Byte length	16bit					485 addres	S	0X6201	
	High bit of Pa	ath 0 position	; (Or	nly valid usi	ng 4	485 comr	munication)			
	Label	PR0 position					Valid mode	e(s)	PR	
Pr9.02	Range	-21474836	_	Unit		Pulse	Default		0	
113.02		214748364	1 7							
	Byte length	32bit		Attribute			485 addres		0X6202	
	For Path 0 po	•				-	e to R/W low	16 b	oit.	
	R/W high 16			alized throu	gh I	Pr9.02.		, ,		
	Label	PR0 veloc			<u> </u>		Valid mode(s)		PR	
Pr9.03	Range	-10000~1	0000			rpm	Default		60	
	Byte length	16bit		Attribu	Attribute R/W		485 addres	S	0X6203	
	To set PR pa							, ,		
	Label	PR0 accele				0.5	Valid mode	e(s)	PR	
Pr9.04	Range	1 ~ 32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X6204	
	To set PR pa									
D-0.05	Label						Valid mode	(S)		
Pr9.05	Range	1 ~32767		Jnit Maribuda	ms R/	s/Krpm	Default	_	100 0X6205	
	Byte length	16bit		Attribute			485 addres			
	To set PR pa				iee	ded for it	Valid mode		PR	
Pr9.06	Range	0 ~ 32767	PR0 pause time				Default	(3)	0	
F19.00	Byte length	16bit		Unit Attribute		ns R/W	485 addres		0X6206	
	To set pause		nath (3	UAU2U0	
	Label	PR0 specia			piet	ion to ne		16)	PR	
D*0.07	Range	· · · · · · · · · · · · · · · · · · ·	ai pai	Unit	1		Valid mode(s		\	
Pr9.07	•	0 ~ 65535			<u> </u>	`			0	
	Byte length	16bit		Attribute	F	Κ	485 addres	S	0X6207	
	Reserved									



	Label	PR1 mode	!				Valid mode	e(s)	PR	
Pr9.08	Range	0x0~0xFFI		Unit		/	Default	` '	0	
	Byte length	16bit		Attribute	T	R/W	485 addres	S	0X6208	
		-1					•		•	
Bit	14	8-13	6-7		5		4	0-3		
Definition	0: No	0-15:	0: ab	solute	0:	No	0: Can be	0: n	ull	
	Jump,	Jump to	1: cc	rrespond		erlap,	Interrupt	1: P	ositioning	
		correspond	com	mand		dicates	1: Can't be 2: Velocity			
		path	·				Interrupt,	• *		
	1: Jump.					Overlap,	indicates		oming	
	Jump to SJ					dicated	using!		mergency	
	or CJ			WI	th CJ		stop			
									cates using	
								P/ V/	/H/S	
	Label	PR1 position	on H				Valid mode	1(2)	PR	
Pr9.09	Range	0~ 0xFFFF		Unit	Т	Pulse	Default	<i>(3)</i>	0	
113.03	Byte length		16bit Attribute				485 addres	s	0X6209	
			: (Or		Attribute R/W y valid using 485 com				07.0200	
	Label	PR1 position		,	9		Valid mode	(s)	PR	
D 0 40	Range	-21474836					Default			
Pr9.10	3	214748364	_	Unit		Pulse			0	
	Byte length	32bit		Attribute	•	R/W	485 addres	S	0X620A	
	For Path pos	sition, using 4	85 cc	mmunication	on,	only able	to R/W low 1	6 bit		
	R/W high 16	bit needs to b	e rea	alized throu	gh	Pr9.09.				
	Label	PR1 veloc	ity				Valid mode(s)		PR	
Pr9.11	Range	-10000~1	0000			rpm	Default		60	
	Byte length	16bit		Attribu	ite	R/W	485 addres	S	0X620B	
	To set PR pa						T			
	Label	PR1 accele					Valid mode	(s)	PR	
Pr9.12	Range	1 ~ 32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute		W	485 addres	_	0X620C	
	To set PR pa				eec	iea for Orp	Valid mode		2 1000rpm PR	
Pr9.13		PR1 decel		In time Jnit		o/Krom	Default	(5)	100	
F19.13	Range Byte length	1 ~32767 16bit		Attribute		s/Krpm W	485 addres		0X620D	
	To set PR pa									
	Label	PR1 pause			100	aca for it	Valid mode		PR	
Pr9.14	Range	0 ~ 32767		Unit	r	ms	Default	(-)	0	
110114	Byte length	16bit	Attribute	_	R/W	485 addres	s	0X620E		
		time for PR path 2 from com						-	57.020L	
	Label	·					Valid mode	(s)	PR	
Pr9.15	Range	0 ~ 65535	PR1 special parameter 0 ~ 65535 Unit				Default	` '	0	
	Byte length	16bit		Attribute	' 	R 485 address 0X620F				
	Reserved	100.0			Т,	-	.00 444100	-	57.0201	
	Reserved									



	Labal	DD0 d-					Valid made	2/2)	PR	
Pr9.16	Label	PR2 mode		11!4		1	Valid mode	2 (S)		
Pr9.16	Range	0x0~0xFF	FF	Unit	+	/ D /	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	SS	0X6210	
Bit	14	8-13	6-7		5		4	0-3		ĺ
Definition	0: No	0-15:		osolute		No	0: Can be	0: n	ull	
Deminition	Jump,	Jump to		orrespond		verlap,	Interrupt		ositioning	
	indicates	correspond		mand		dicates	1: Can't be		elocity	
	with END	path		orrespond		ith SJ	Interrupt,	mot	•	
	1: Jump.	patri	mot	-		Overlap,	indicates		oming	
	Jump to SJ			01		dicated	using!		mergency	
	or CJ					ith CJ		stop		
									cates using	
									/H/S	
		1	•				I			
	Label	PR2 positi					Valid mode	e(s)	PR	
Pr9.17	Range	0~ 0xFFFF	=	Unit	_	Pulse	Default		0	
	Byte length			Attribute	_	R/W	485 addres	SS	0X6211	
	High bit of P	ath 2 position	; (Or	nly valid usi	ng	485 com	munication)			
	Label	PR2 positi	on(L)				Valid mode	e(s)	PR	
Pr9.18	Range	-21474836		1164		Dulas	Default	, ,	0	
Pr9.18		214748364	47	Unit		Pulse			0	
	Byte length			Attribute		R/W	485 addres		0X6212	
		osition, using					le to R/W low	16 b	oit.	
	R/W high 16	bit needs to be	oe rea	alized throu	gh	Pr9.17.				
	Label	PR2 veloc	eitv				Valid mode	e(s)	PR	
Pr9.19	Range	-10000~		Unit		rpm	Default	(-)	60	
	Byte length			Attribu	ıte	R/W	485 addres	s	0X6213	
		ath 2 velocity.		7 (61) 110 0		1.0.11	100 444.00		0710210	
	Label	PR2 accel	eratio	n time			Valid mode	e(s)	PR	
Pr9.20	Range	1 ~ 32767	U	Jnit	m	s/Krpm	Default		100	
	Byte length	16bit		Attribute	R	W	485 addres	S	0X6214	
		ath 2 accelera	tion t	ime, time n	eec	ded for Or			o 1000rpm	
	Label	PR2 decel	eratio	n time			Valid mode	e(s)	PR	
Pr9.21	Range	1 ~32767		Jnit		s/Krpm	Default		100	
	Byte length			Attribute		W	485 addres		0X6215	
		ath 2 decelera			nee	ded for 1				
	Label	PR2 pause					Valid mode	e(s)	PR	
Pr9.22	Range	0 ~ 32767		Unit	_	ms	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	S	0X6216	
		time for PR			olet	tion to ne				
	Label	PR2 specia	al par				Valid mode(s		PR	
Pr9.23	Range	0 ~ 65535		Unit	/	<u> </u>	Default		0	
	Byte length	16bit		Attribute	Ī	R	485 addres	s	0X6217	
	Reserved	-					•			



	Label	PR3 mode	!				Valid mode	e(s)	PR	
Pr9.24	Range	0x0~0xFFI		Unit		/	Default	(-,	0	
	Byte length	16bit		Attribute	Ť	R/W	485 addres	ss	0X6218	
		1001	1	711111111111111111111111111111111111111			100 444.00		07.02.10	
Bit	14	8-13	6-7		5		4	0-3		
Definition	0: No	0-15:	0: ab	solute	0:	No	0: Can be	0: n	ull	
	Jump,	Jump to	1: co	rrespond	ov	erlap,	Interrupt	1: P	ositioning	
	indicates	correspond	com	mand	ind	dicates	1: Can't be 2: Velocity			
	with END	path	· · · · · · · · · · · · · · · · · · ·				Interrupt, motion			
	1: Jump.		motor				indicates	3: H	oming	
	Jump to SJ				ind	dicated	using!	4: E	mergency	
	or CJ				wi	th CJ		stop		
									cates using	
								P/V,	/H/S	
	Label	PR3 position				Pulse	Valid mode	e(s)	PR	
Pr9.25	Range	0~ 0xFFFF					Default		0	
	Byte length	1	16bit Attribute				485 addres	S	0X6219	
			n 3 position; (Only valid using							
	Label	PR3 position		Т			Valid mode	e(s)	PR	
Pr9.26	Range	-2147483648~ Unit				Pulse	Default		0	
	5	214748364	1/				405 11		2)/22/4	
	Byte length	32bit	405	Attribute		R/W	485 addres		0X621A	
	For Path 3 po						e to R/W low	16 D	oit.	
	Label	PR3 veloc		ilized illiou	gii	F13.23.	Valid mode	(s)	PR	
Pr9.27	Range	-10000~1		Unit		rpm	Default		60	
	Byte length	16bit			Unit rpm Attribute R/W			s	0X621B	
	To set PR pa			7100		10,00	485 address		07(0212	
	Label	PR3 accele	eratio	n time			Valid mode(s)		PR	
Pr9.28	Range	1 ~ 32767		Jnit	m	s/Krpm	Default	` '	100	
	Byte length	16bit	A	Attribute	R/	W	485 addres	S	0X621C	
	To set PR pa	th 3 accelera	tion ti	me, time ne	eec	led for Orp	om to acceler	ate to	o 1000rpm	
	Label	PR3 decel	eratio	n time			Valid mode	e(s)	PR	
Pr9.29	Range	1 ~32767	Ų	Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X621D	
	To set PR pa				nee	ded for 10	•			
	Label	PR3 pause	time				Valid mode	e(s)	PR	
Pr9.30	Range	0 ~ 32767		Unit	_	ns	Default		0	
	Byte length	16bit Attribut				R/W	485 addres	S	0X621E	
		time for PR path 3 from comp				ion to nex	_	, ,		
	Label	PR3 specia	al par				Valid mode	e(s)	PR	
Pr9.31	Range	0 ~ 65535		Unit	/	₹	Default		0	
	Byte length	16bit	16bit Attribute				485 addres	S	0X621F	
	Reserved									



	Label	PR4 mode				Valid mode				
Pr9.32	Range	0x0~0xFFI		Unit	Т,	/	Default	,(0)	PR 0	
113.32	Byte length	16bit	•	Attribute	+	R/W	485 addres		0X6220	
	Dyte length	TODIC		Attribute	_ '	1 (/ / / /	+05 addres		070220	
Bit	14	8-13	6-7		5		4	0-3		
Definition		0-15:		solute		No	0: Can be	0: n	ull	
		Jump to		rrespond		erlap,	Interrupt 1:		ositioning	
	• •	correspond		mand			1: Can't be			
		path		rrespond		th SJ	Interrupt,	mot	•	
	1: Jump.		moto	•	1 (Overlap,	indicates	3: H	oming	
	Jump to SJ				ind	dicated	using!	4: E	mergency	
	or CJ					th CJ	_	stop)	
								Indi	cates using	
								P/V	/H/S	
	Label	PR4 positi	on H				Valid mode	e(s)	PR	
Pr9.33	Range	0~ 0xFFFF	=	Unit		Pulse	Default		0	
	Byte length	16bit		Attribute R/W			485 addres	s	0X6221	
	High bit of Pa	th 0 position	; (On	ly valid usi	ng	485 comr				
	Label	PR4 position	on(L)				Valid mode	e(s)	PR	
Pr9.34	Range	-21474836		Unit		Pulse	Default		0	
113.54		214748364	17						0	
	Byte length	32bit			Attribute R/W mmunication, only able			S	0X6222	
							e to R/W low	16 b	it.	
	R/W high 16			lized throu	gn	Pr9.33.	\/al¦al a ala	<i>(-</i>)	DD	
D.0.05	Label	PR4 veloc		11.2			Valid mode	e(S)	PR	
Pr9.35	Range	-10000~1	10000			rpm	Default		60	
	Byte length	16bit		Attribu	ite	R/W	485 addres	S	0X6223	
	To set PR pa			n 4inn n			Valid mode(s)		PR	
Pr9.36	Label	PR0 accele				o /// rp rp	Default	(8)		
F19.30	Range Byte length	1 ~ 32767 16bit		Init Attribute	R/	s/Krpm	485 addres		100 0X6224	
	To set PR pa									
	Label	PR4decele				icu ioi oil	Valid mode		PR	
Pr9.37	Range	1 ~32767		Init	m	s/Krpm	Default	(°)	100	
110.01	Byte length	16bit		ttribute	R/		485 addres	s	0X6225	
	To set PR pa									
	Label	PR4 pause					Valid mode		PR	
Pr9.38	Range	0 ~ 32767		Unit	r	ns	Default	` '	0	
	Byte length	16bit				?/W	485 addres	s	0X6226	
			time for PR path 4 f					ı	-	
	Label	PR4 specia					Valid mode	e(s)	PR	
Pr9.39	Range	0 ~ 65535	Unit	/	'	Default		0		
	Byte length		Attribute	F	₹			0X6227		
	Reserved	16bit						•		
	. 1000.100									



	Label	PR5 mode				Valid mode	2(5)	PR		
Pr9.40	Range	0x0~0xFFI		Unit	Τ,	,	Default			
113.40	Byte length	16bit		Attribute	+	R/W	485 addres		0 0X6228	
	Dyte leligtii	TODIL		Attribute	<u> </u>	\ / V V	405 addies	3	070220	
Bit	14	8-13	6-7		5		4	0-3		
Definition		0-15:	_	bsolute		No	0: Can be	0: n	ull	
		Jump to		orrespond		erlap,	Interrupt		ositioning	
		correspond		mand		dicates	1: Can't be		elocity	
		path		orrespond		th SJ	Interrupt,	mot	•	
	1: Jump.		or		Overlap,	indicates		oming		
	Jump to SJ					dicated	using!		mergency	
	or CJ				wi	th CJ		stop	• .	
									cates using	
								P/V	/H/S	
									-	
	Label	PR5 positi	on H	<u> </u>			Valid mode	e(s)	PR	
Pr9.41	Range	0~ 0xFFFF	=	Unit	F	Pulse	Default		0	
	Byte length	16bit		Attribute	F	R/W	485 addres	S	0X6229	
	High bit of Pa	th 5 position	Only valid using 485 com			munication)				
	Label	PR5 position	on(L)				Valid mode	(s)	PR	
Pr9.42	Range	-21474836	48~	Unit		Dulco	Default 0			
F13.42		214748364	17	Unit Pulse					U	
	Byte length	32bit		Attribute R/W			485 addres		0X622A	
	For Path 0 po	_				-	le to R/W low	16 b	it.	
	R/W high 16			alized through	gh I	Pr9.41.				
	Label	PR5 veloc				1	Valid mode(s)		PR	
Pr9.43	Range	-10000~1	0000		rpm		Default		60	
	Byte length	16bit		Attribu	te R/W		485 addres	S	0X622B	
	To set PR pa						T			
	Label	PR5 accele					Valid mode	(s)	PR	
Pr9.44	Range	1 ~ 32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X622C	
	To set PR pa			•	eed	ea for Ur				
Pr9.45	Label	PR5 decel			<u></u>	0/Krp.m	Valid mode	(5)	PR	
P19.40	Range Byte length	1 ~32767 16bit		Unit Attribute	ms R/	s/Krpm w/	Default 485 addres		100 0X622D	
	To set PR pa									
	Label	PR5 pause			ice	u c u 101 11	Valid mode		PR	
Pr9.46	Range	0 ~ 32767		Unit	r	ns	Default	(υ)	0	
	Byte length	16bit	Attribute		R/W	485 addres	•	0X622E		
							.	UNULLL		
	Label	e time for PR path 5 from completi PR5 special parameter					Valid mode	(s)	PR	
Pr9.47	Range						Default	(-)	0	
113:41	Byte length	16bit		Unit / Attribute R			485 address 0X622F		-	
		Allibule		`	+05 addie5	J	UNUZZE			
	Reserved									



	Label	PR6 mode					Valid mode	e(s)	PR	
Pr9.48	Range	0x0~0xFFF		Unit	1	/	Default	(-)	0	
113.40	Byte length	16bit		Attribute	+	R/W	485 addres		0X6230	
	Dyte length	TODIC		Attribute		1 V V V	+05 addres		070230	
Bit	14 8	3-13	6-7		5		4	0-3		
Definition		D-15:		solute		No	0: Can be	0: n	ull	
		ump to		rrespond		erlap,	Interrupt	1: Positioning		
	• •	correspond		mand		dicates	1: Can't be		elocity	
		oath		rrespond		th SJ	Interrupt,	mot	•	
	1: Jump.	Jacin	moto	•		Overlap,	indicates		oming	
	Jump to SJ		11100			dicated	using!		mergency	
	or CJ					th CJ		stop		
						00			cates using	
									/H/S	
								.,.,	.,,	
	Label	PR6 position					Valid mode	e(s)	PR	
Pr9.49	Range	0~ 0xFFFF	-	Unit		Pulse	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	S	0X6231	
	High bit of Pa	th 6 position:	; (Or	Only valid using 485 cor			munication)			
	Label	PR6 position	on(L)				Valid mode	(s)	PR	
Pr9.50	Range	-21474836	48~	l loit		Dulas	Default		0	
P19.50	_	214748364	1 7	Unit Pulse					U	
	Byte length	32bit		Attribute	•	R/W	485 addres	S	0X6232	
	For Path 6 po	sition, using	485 c	communicat	tior	, only abl	le to R/W low	16 b	it.	
	R/W high 16 b	oit needs to b	e rea	alized through Pr9.49.						
	Label	PR6 veloc	ity				Valid mode	e(s)	PR	
Pr9.51	Range	-10000~1	0000			rpm	Default		60	
	Byte length	16bit		Attribute R/W			485 addres	S	0X6233	
	To set PR pat						T			
	Label	PR6 accele					Valid mode	(s)	PR	
Pr9.52	Range	1 ~ 32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X6234	
	To set PR pat				eec	led for Orp				
	Label	PR6 decele					Valid mode	(s)	PR	
Pr9.53	Range	1 ~32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X6235	
	To set PR pat	1			ee	ded for 10				
	Label	PR6 pause	time				Valid mode	(s)	PR	
Pr9.54	Range	0 ~ 32767	Unit	_	ns	Default		0		
								S	0X6236	
					olet	ion to nex		, , 1		
		•		_		Valid mode(s)		PR		
Pr9.55		0 ~ 65535		Unit	/		Default		0	
	Byte length	16bit				485 address 0X6237				
		/te length 16bit eserved				7.11110410				
	Byte length To set pause Label Range	16bit A ime for PR path 6 fr PR6 special paran 0 ~ 65535 U		Attribute 6 from comp rameter Unit		R/W ion to nex	485 addres xt path Valid mode Default	e(s)	0X6236 PR 0	



	Label	PR7 mode	!				Valid mode	e(s)	PR	
Pr9.56	Range	0x0~0xFFI		Unit	/		Default	<u> </u>	0	
	Byte length	16bit		Attribute	F	R/W	485 addres	SS	0X6238	
		1	L.		1 -					
Bit	14	8-13	6-7		5		4	0-3		
Definition	0: No	0-15:	0: at	solute	0:1	No	0: Can be	0: n	ull	
	Jump,	Jump to	1: cc	rrespond	OV	erlap,	Interrupt	1: P	ositioning	
	indicates	correspond	com	mand	ind	licates	1: Can't be	2: V	elocity	
	with END	path	2: cc	rrespond	wit	:h SJ	Interrupt,	mot	ion	
	1: Jump.		mote	or	10	verlap,	indicates	3: H	oming	
	Jump to SJ				ind	licated	using!	4: E	mergency	
	or CJ				wit	:h CJ		stop		
								Indi	cates using	
								P/V	/H/S	
		T-5							22	
D-0 57	Label	PR7 positi		I I ! t			Valid mode	e(s)	PR	
Pr9.57	Range	0~ 0xFFFF					Default		0 0X6239	
	Byte length		(0)	Attribute		105 samr	485 addres	55	086239	
	High bit of Pa	itn / position	; (Or	ily valid usi	ng 2	182 COM	nunication)			
	Label	PR7 position	n(L)				Valid mode	e(s)	PR	
	Range	-21474836					Default	(-)		
Pr9.58	90	214748364	_	Unit	Pulse				0	
	Byte length	32bit		Attribute	Э	R/W	485 address		0X623A	
	For Path 7 po	sition, using	485 c	communica	tion	, only ab	le to R/W low	16 b	it.	
	R/W high 16	bit needs to b	e rea	alized throu	gh F	Pr9.57.				
	Label	PR7 veloc	city				Valid mode	e(s)	PR	
Pr9.59	Range	-10000~1	10000	Unit		rpm	Default		60	
	Byte length	16bit		Attribu	Attribute R/W		485 addres	S	0X623B	
	To set PR pa									
	Label	PR7 accel					Valid mode	e(s)	PR	
Pr9.60	Range	1 ~ 32767		Jnit		/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X623C	
	To set PR pa				eed	ed for Orp				
D 0 04	Label	PR0 decel					Valid mode	e(s)	PR	
Pr9.61	Range	1 ~32767		Jnit		Krpm	Default	_	100	
	Byte length	16bit		Attribute	R/		485 addres		0X623D	
	To set PR pa				ieec	ded for 10			ate to urpm PR	
D-0 C0	Label	PR7 pause	time		T.,		Valid mode	(S)		
Pr9.62	Range	0 ~ 32767		Unit		ns NAV	Default		0 0V622E	
	Byte length	16bit	t	Attribute		R/W	485 addres	S	0X623E	
	To set pause Label				vieti	on to ne	xt path Valid mode	\(c\	PR	
D*0 C2	Range	PR7 special 0 ~ 65535	aı par		,			(2)	0	
Pr9.63				Unit	/)	Default			
	Byte length	16bit		Attribute	F	`	485 addres	5	0X623F	
	Reserved									



	Label	PR8 mode					Valid mode	(e)	PR		
Pr9.64	Range	0x0~0xFFF		Unit	1		Default	(3)	0		
F13.04	Byte length	16bit		Attribute	/ [R/W	485 addres		0X6240		
	byte length	TODIL		Attribute		1/ V V	405 addres	.5	070240		
Bit	14	8-13	6-7		5		4	0-3			
Definition		0-15:		solute	0:1	Nο	0: Can be	0: n	ull		
		Jump to		rrespond		erlap,	Interrupt		ositioning		
	''	correspond		mand		licates	1: Can't be 2: Velocity				
		path	2: co	rrespond		th SJ	Interrupt, motion				
	1: Jump.	'	moto	-	1 (Overlap,	indicates 3: Homing				
	Jump to SJ				inc	licated	using!		mergency		
	or CJ					th CJ		stop)		
								Indi	cates using		
								P/V	/H/S		
	Label	PR8 position				Valid mode)(e)	PR			
Pr9.65	Range	0~ 0xFFFF		Unit		Pulse	Default	<i>,</i> (3)	0		
. 10100	Byte length					R/W	485 addres	S	0X6241		
		h 0 position; (Only valid using							07.02+1		
	ringir bit or r d	11 0 position; (Only valid using 465 co									
	Label	PR8 position(L) Valid mode(s) PR									
Pr9.66	Range	-21474836	48~	Unit		Pulse	Default		0		
F13.00		214748364	17	Offic					0		
	Byte length	32bit		Attribute		R/W	485 addres		0X6242		
	For Path 8 po						e to R/W low	16 b	it.		
	R/W high 16 l	PR8 veloc		alizea throug	gn i	² 19.65.	Valid mode	(c)	PR		
Pr9.67	Range	-10000~1		Unit		rpm	Default	(3)	60		
	Byte length	16bit		Attribu			485 addres	s	0X6243		
	To set PR par			1 2 2 2 2 2 2		1 - 4					
	Label	PR8 accele	eratio	n time			Valid mode	(s)	PR		
Pr9.68	Range	1 ~ 32767	l	Jnit	ms	s/Krpm	Default		100		
	Byte length	16bit		Attribute	R/		485 addres		0X6244		
	To set PR par				eed	ed for Orp					
	Label	PR8 decele					Valid mode	(s)	PR		
Pr9.69	Range	1 ~32767		Jnit		s/Krpm	Default		100		
	Byte length	16bit		Attribute	R/		485 addres		0X6245		
	To set PR par				ieed	dea for 10	•		ate to 0rpm PR		
Pr9.70	Label Range	PR8 pause time					Valid mode Default	(S)			
113.70	Byte length	0 ~ 32767 16bit	Unit Attribute			ns R/W	485 addres	e -	0 0X6246		
								J	U/\UZTU		
	Label		PR path 8 from complocial parameter				Valid mode	(s)	PR		
Pr9.71	Range	0 ~ 65535	Pui	Unit	/		Default	(-)	0		
110.11	Byte length	16bit		Attribute	F	?	485 addres	s	0X6247		
	Reserved	100.0				-	.00 444100	-	J/10=11		
	1 (COCI VEU										



		T						. / - \		
D-0.70	Label	PR9 mode			<u>, </u>		Valid mode	(S)	PR	
Pr9.72	Range	0x0~0xFFF		Unit	/_	2001	Default		0	
	Byte length	16bit		Attribute	ŀ	R/W	485 addres	S	0X6248	
Bit	14 8	8-13	6-7		5		4	0-3		
Definition		0-15:		solute	2 1:0	N	0: Can be	0-3 0: n		
Definition										
	• •	Jump to correspond		rrespond mand		erlap, licates	Interrupt 1: Can't be		ositioning elocity	
		path		rrespond		:h SJ	Interrupt,	z. v mot	•	
	1: Jump.	patri	moto			Overlap,	indicates		oming	
	Jump to SJ		mote	ונ		licated	using!		mergency	
	or CJ					:h CJ	using:	stop		
	01 63				VVIC	.11 CJ			cates using	
									/H/S	
								., ,	11,3	
							1			
	Label	PR9 position				Valid mode	e(s)	PR		
Pr9.73	Range	0~ 0xFFFF Unit Pulse 16bit Attribute R/W					Default		0	
	Byte length	16bit Attribute					485 addres	S	0X6249	
	High bit of Pa	th 9 position; (Only valid using 4				485 comr	nunication)			
	Label	PR9 position	on(L)				Valid mode	(s)	PR	
Pr9.74	Range	-21474836		Unit	Pulse		Default		0	
110114		214748364	17				405 - 11			
	Byte length	32bit		Attribute		R/W	485 addres		0X624A	
	For Path 9 po						le to R/W low	16 b	it.	
	R/W high 16 k	PR0 veloc		ilizea throug	gn F	719.73.	Valid mode	(c)	PR	
Pr9.75	Range	-10000~1		Unit		rnm	Default	(3)	60	
113.73	Byte length	16bit	0000	Attribu	rpm ute R/W		485 address		0X624B	
	To set PR pat			Attribu	110	1 1 7 7 7	465 address		0/\0Z+D	
	Label	PR9 accele	eratio	n time			Valid mode	(s)	PR	
Pr9.76	Range	1 ~ 32767		Jnit	ms	s/Krpm	Default	(-)	100	
	Byte length	16bit		Attribute	R۸		485 addres	s	0X624C	
	To set PR pat									
	Label	PR9 decele					Valid mode		PR	
Pr9.77	Range	1 ~32767	U	Jnit	ms	s/Krpm	Default	` '	100	
	Byte length	16bit	Δ	Attribute	R۸		485 addres	S	0X624D	
	To set PR pat	th 9 decelera	tion t	time, time n	need	ded for 10	000rpm to de	celer	ate to Orpm	
	Label	PR9 pause	time				Valid mode	(s)	PR	
Pr9.78	Range	0 ~ 32767	767 Unit		_	ns	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	S	0X624E	
	To set pause				oleti	on to nex				
	Label	PR9 specia	al para				Valid mode	(s)	PR	
Pr9.79	Range	0 ~ 65535		Unit	/		Default		0	
	Byte length	16bit		Attribute	R	₹	485 addres	S	0X624F	
	Reserved									_



								- 1 - 1	200	
	Label	PR10 mod				,	Valid mode	e(s)	PR	
Pr9.80	Range	0x0~0xFFI	FF	Unit	/		Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	SS	0X6250	
D''		0.43	6.7		_			0.2		
Bit		8-13	6-7		5	<u> </u>	4	0-3		
Definition		0-15:		bsolute		No	0: Can be	0: n		
	• •	Jump to		orrespond		erlap,	Interrupt		ositioning	
		correspond path		mand orrespond		dicates th SJ	1: Can't be Interrupt,	mot	elocity	
	1: Jump.	patri	mot	-		Overlap,	indicates		oming	
	Jump to SJ		IIIOt	OI .		dicated	using!		mergency	
	or CJ					th CJ	using:	stor		
	01 63				VVI	tii CJ			cates using	
									/H/S	
								', ',	, , c	
	.	1						, ,		
D-0.04	Label	PR10 posi			٠.		Valid mode	e(s)	PR	
Pr9.81	Range	0~ 0xFFFF	-	Unit	_	Pulse	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	SS	0X6251	
	High bit of Pa	itn10 position	1; (U	iniy valid us	ing	485 com	munication)			
	Label	PR10 posit		_)			Valid mode	e(s)	PR	
Pr9.82	Range	-21474836		Unit		Pulse	Default		0	
	D () ()	214748364	1 7				405 11			
	Byte length	32bit	- 405	Attribute		R/W	485 addres		0X6252	
	For Path 10 p						ble to R/VV lo	W 16	DIT.	
	Label	PR10 velo		alizeu tillou	giii	F19.01.	Valid mode	19)	PR	
Pr9.83	Range	-10000~1		Unit		rpm	Default	,(3)	60	
	Byte length	16bit		Attribu	ıte	R/W	485 addres	s	0X6253	
	To set PR par		/.	7 (64) 110 0		10,00	100 aaa. 00		0710200	
	Label	PR10 acce		ion time			Valid mode	e(s)	PR	
Pr9.84	Range	1 ~ 32767	Į	Jnit	ms	s/Krpm	Default	. ,	100	
	Byte length	16bit		Attribute	R/		485 addres	S	0X6254	
	To set PR pa	th 10 acceler	ation	time, time	nee	ded for 0	rpm to accele	erate	to 1000rpm	
	Label	PR10 dece	elerat	ion time			Valid mode	e(s)	PR	
Pr9.85	Range	1 ~32767	Į	Jnit	ms	s/Krpm	Default		100	
	Byte length	16bit	1	Attribute	R/	W	485 addres	s	0X6255	
	To set PR pa	th 10 deceler	ation	time, time	ne	eded for	1000rpm to d	ecele	erate to Orpm	
	Label	PR10 paus	se tim	ne			Valid mode	e(s)	PR	
Pr9.86	Range	0 ~ 32767		Unit	r	ns	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	s	0X6256	
	To set pause	•			nple	etion to n				
	Label	PR10 spec	cial pa	parameter Valid mode(s) PR					PR	
Pr9.87	Range	0 ~ 65535		Unit	/		Default		0	
	Byte length	16bit		Attribute	F	₹	485 addres	s	0X6257	
	Reserved	•					•			



Process Proc		Labat	DD44 ···	1.				Valid made	-/->	DD	
Bit	D 0 00	Label				Τ,			2 (S)	PR	
Bit	Pr9.88			FF		/_				<u> </u>	
Definition O: No		Byte length	16bit		Attribute	F	R/W	485 addres	S	0X6258	
Definition O: No		T									1
Jump,								•			
Indicates Correspond Command Indicates 1: Can't be Interrupt, motion Notice Interrupt, motion Notice Indicates Notice Interrupt, motion Notice Indicates Ind	Definition	0: No	0-15:	0: ab	osolute	-	-	0: Can be			
With END 1: Jump. Jump to SI Jump to		Jump,	•	1: cc	rrespond		• •			_	
1: Jump. Jump to SJ		indicates	correspond	com	mand	ind	icates	1: Can't be	2: V	elocity	
Pr9.89		with END	path	2: cc	orrespond	wit	h SJ	Interrupt,	mot	ion	
Pr9.89		1: Jump.		mot	or	1 O	verlap,	indicates	3: H	oming	
Label		Jump to SJ				ind	icated	using!	4: E	mergency	
Pr9.89		or CJ				wit	h CJ		stop)	
Pr9.89									Indi	cates using	
Pr9.89 Range Byte length 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Pr9.90 Label PR11 position; (Only valid using 485 communication) Valid mode(s) PR Pr9.90 Range -2147483648- 2147483648- 2147483647 Unit 2147483647 Attribute R/W A85 address 0X625A Default 0 Byte length 32bit Attribute R/W									P/V	/H/S	
Pr9.89 Range Byte length 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Pr9.90 Label PR11 position; (Only valid using 485 communication) Valid mode(s) PR Pr9.90 Range -2147483648- 2147483648- 2147483647 Unit 2147483647 Attribute R/W A85 address 0X625A Default 0 Byte length 32bit Attribute R/W											
Pr9.89 Range Byte length 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Default 16bit Attribute R/W 485 address 0X6259 Pr9.90 Label PR11 position; (Only valid using 485 communication) Valid mode(s) PR Pr9.90 Range -2147483648- 2147483648- 2147483647 Unit 2147483647 Attribute R/W A85 address 0X625A Default 0 Byte length 32bit Attribute R/W											-
Byte length 16bit Attribute R/W 485 address 0X6259			-						e(s)	PR	
High bit of Path 11 position: (Only valid using 485 communication) Range	Pr9.89			=		_		Default			
Label								1	S	0X6259	
Pr9.90 Range 2147483648 2147483647 Unit 2147483647 Pulse Pulse Default 0 Byte length 32bit RW in Pulse RW 485 address 32bit RW in Pulse RW 485 address 0X625A For Path 11 position, using 485 communication, only able to R/W low 16 bit. RW high 16 bit needs to be realized through Pr9.89. Valid mode(s) PR Pr9.91 Range PR11 velocity Valid mode(s) PR Byte length 16bit Attribute R/W 485 address 0X625B To set PR path 11 velocity. Valid mode(s) PR Pr9.92 Range PR1 acceleration time PR1 acceleration time RW 485 address 0X625C PR Psyte length 16bit Attribute RW 485 address 0X625C 0X625C To set PR path 11 acceleration time, time needed for 0rpm to accelerate to 1000rpm PR Pr9.93 Range PR11 deceleration time RW 485 address 0X625D PR PR Pr9.94 Range PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm PR Pr9.94 Range PR path 11 pause time PR11 pau		High bit of Pa	ath 11 position	n; (C	Only valid us	sing	485 con	nmunication)			
Price		Label	PR11 posi	tion(L	.)			Valid mode	e(s)	PR	
Byte length 32bit Attribute R/W 485 address 0X625A	D*0.00	Range	-21474836	48~	l lmi4		Dulas	Default		0	
For Path 11 position, using 485 communication, only able to R/W low 16 bit. R/W high 16 bit needs to be realized through Pr9.89. Label PR11 velocity Valid mode(s) PR Range -10000~10000 Unit rpm Default 60 Byte length 16bit Attribute R/W 485 address 0X625B To set PR path 11 velocity. Label PR11 acceleration time Valid mode(s) PR Range 1~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625C To set PR path 11 acceleration time, time needed for 0rpm to accelerate to 1000rpm Label PR11 deceleration time Valid mode(s) PR Range 1~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625C To set PR path 11 deceleration time Valid mode(s) PR To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm Label PR11 pause time Valid mode(s) PR Pr9.94 Range 0~32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Pr9.95 Range 0~65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F	F19.90		214748364	47	Onit		Puise			U	
R/W high 16 bit needs to be realized through Pr9.89.		Byte length	32bit		Attribute			485 addres	s	0X625A	
Label PR11 velocity Valid mode(s) PR Pr9.91 Range -10000~10000 Unit rpm Default 60 Byte length 16bit Attribute R/W 485 address 0X625B To set PR path 1 acceleration time Valid mode(s) PR Pr9.93 Range 1 ~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625D To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm Label PR11 pause time Valid mode(s) PR Pr9.94 Range 0 ~ 32767 Unit ms Default 0 Byte length <th< th=""><td></td><td>For Path 11</td><td>oosition, using</td><td colspan="2">l l</td><td>n, only a</td><td>ble to R/W lo</td><td>w 16</td><td>bit.</td><td></td></th<>		For Path 11	oosition, using	l l		n, only a	ble to R/W lo	w 16	bit.		
Pr9.91 Range -10000∼10000 Unit rpm Default 60 Byte length 16bit Attribute R/W 485 address 0X625B To set PR path 11 velocity. Label PR11 acceleration time Valid mode(s) PR Pr9.92 Range 1 ~ 32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625C To set PR path 11 acceleration time, time needed for 0rpm to accelerate to 1000rpm Valid mode(s) PR Pr9.93 Range 1 ~ 32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625D To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm Label PR11 pause time Valid mode(s) PR Pr9.94 Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E		R/W high 16	bit needs to b	oe rea	alized throu	gh F	Pr9.89.				
Byte length 16bit Attribute R/W 485 address 0X625B		Label	PR11 velo	city				Valid mode	(s)	PR	
Byte length	Pr9.91	Range	-10000~1	10000	Unit		rpm	Default		60	
To set PR path 11 velocity.			16bit		Attribu	ıte		485 addres	s	0X625B	
Process Proc				<i>/</i> .	1		1				
Pr9.92 Range 1 ~ 32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625C To set PR path 11 acceleration time, time needed for 0rpm to accelerate to 1000rpm PR Label PR11 deceleration time Valid mode(s) PR Range 1 ~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625D To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm To set PR path 11 pause time Valid mode(s) PR Pr9.94 Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Pr9.95 Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 a					on time			Valid mode	(s)	PR	
Byte length 16bit	Pr9.92					ms	:/Krnm		(-)		
To set PR path 11 acceleration time, time needed for 0rpm to accelerate to 1000rpm Label PR11 deceleration time Valid mode(s) PR Range 1 ~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625D To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm Label PR11 pause time Valid mode(s) PR Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F									s		
Process Proc											
Pr9.93 Range 1 ~32767 Unit ms/Krpm Default 100 Byte length 16bit Attribute R/W 485 address 0X625D To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm Label PR11 pause time Valid mode(s) PR Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F						1000	454 101 0				
Byte length 16bit Attribute R/W 485 address 0X625D Pr9.94 Eabel PR11 pause time Valid mode(s) PR Pr9.94 Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E Pr9.95 Range PR11 special parameter Valid mode(s) PR Pr9.95 Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F	Dra a3		+			me	/Krnm		,(3)		
To set PR path 11 deceleration time, time needed for 1000rpm to decelerate to 0rpm	113.33								_		
Label PR11 pause time Valid mode(s) PR Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0 X625E Pr9.95 Range PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F											
Pr9.94 Range 0 ~ 32767 Unit ms Default 0 Byte length 16bit Attribute R/W 485 address 0X625E Pr9.95 To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F						пее	eueu IOI				
Byte length 16bit Attribute R/W 485 address 0X625E To set pause time for PR path 11 from completion to next path Label PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F	D::0 04								(5)		
To set pause time for PR path 11 from completion to next path	Pr9.94					_				•	
Pr9.95 Label PR11 special parameter Valid mode(s) PR Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F									S	UX625E	
Pr9.95 Range 0 ~ 65535 Unit / Default 0 Byte length 16bit Attribute R 485 address 0X625F						nple	tion to n		,		
Byte length 16bit Attribute R 485 address 0X625F			-	cial pa					e(s)	PR	
	Pr9.95	Range	0 ~ 65535		Unit	/		Default		0	
		Byte length	16bit		Attribute	R	2	485 addres	s	0X625F	
			1	L		-1		1			



	Label	PR12 mod	le				Valid mode	e(s)	PR	
Pr9.96	Range	0x0~0xFF	FF	Unit	/		Default		0	
	Byte length	16bit		Attribute	F	R/W	485 addres	S	0X6260	
Bit	14	8-13	6-7		5		4	0-3		
Definition	0: No	0-15:	0: al	bsolute	1:0	No	0: Can be	0: n	ull	
	Jump,	Jump to	1: co	orrespond	ove	erlap,	Interrupt	1: P	ositioning	
	indicates	correspond	com	ımand	ind	licates	1: Can't be	2: V	elocity	
	with END	path	2: co	orrespond	wit	:h SJ	Interrupt,	mot	tion	
	1: Jump.		mot	or	10	verlap,	indicates	3: H	oming	
	Jump to SJ				ind	licated	using!	4: E	mergency	
	or CJ				wit	:h CJ		stop)	
								Indi	cates using	
								P/V	/H/S	
	Label	PR12 posi	tion I	1			Valid mode	e(s)	PR	
Pr9.97	Range	0~ 0xFFFF	=	Unit	_	Pulse	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	S	0X6261	
	High bit of Pa	ath 12 positio	n; (C	Only valid us	sing	485 con	nmunication)			
	Label	PR12 posi	tion(L	_)			Valid mode	e(s)	PR	
Pr9.98	Range	-21474836	48~	I Imit		Dulaa	Default		0	
Pr9.98		214748364	47	Unit		Pulse			0	
	Byte length	32bit		Attribute	е	R/W	485 addres	S	0X6262	
	For Path 12	position, using	g 485	communic	atio	n, only a	ble to R/W lo	w 16	bit.	
		bit needs to b								
	Label	PR12 velo	city				Valid mode	e(s)	PR	
Pr9.99	Range	-10000~	10000	Unit		rpm	Default		60	
	Byte length	16bit		Attribu	ıte	R/W	485 addres	s	0X6263	
		th 12 velocity	/.			1				
	Label	PR12 acce		ion time			Valid mode	e(s)	PR	
Pr9.100	Range	1 ~ 32767		Unit	ms	/Krpm	Default	1-7	100	
	Byte length	16bit		Attribute	RΛ		485 addres	s	0X6264	
	To set PR pa									
	Label	PR12 dece		· · · · · · · · · · · · · · · · · · ·			Valid mode		PR	
Pr9.101	Range	1 ~32767		Unit	ms	/Krpm	Default	(-)	100	
	Byte length	16bit		Attribute	RΛ		485 addres		0X6265	
									erate to 0rpm	
	Label	PR12 paus			1100	200 101	Valid mode		PR	
Pr9.102	Range	0 ~ 32767		Unit	m	าร	Default	(-)	0	
110.102	Byte length	16bit		Attribute		R/W	485 addres	•	0X6266	
	To set pause		nath 1					J	UNU200	
	Label				iihie	LIOIT IO III	Valid mode	(e)	PR	
D 0 400		PR12 spec	iai pa		,		Default	(2)		
Pr9.103	Range	0 ~ 65535		Unit	/				0	
	Byte length	16bit		Attribute	R	2	485 addres	S	0X6267	
	Reserved				_					_



	T	T ==						, ,		
5 6 4 6 4	Label	PR13 mod			Τ.	,	Valid mode	e(s)	PR	
Pr9.104	Range	0x0~0xFFI	-F	Unit	/		Default		0	
	Byte length	16bit		Attribute	F	R/W	485 addres	SS	0X6268	
D:4		0.42	6.7		_			0.2		
Bit		8-13	6-7	1.	5	N 1	4	0-3		
Definition		0-15:		bsolute		No	0: Can be	0: n		
	• •	Jump to		orrespond		erlap,	Interrupt		ositioning	
		correspond path		mand orrespond		dicates th SJ	1: Can't be Interrupt,	mot	elocity	
	1: Jump.	patri	mot	-		Overlap,	indicates		oming	
	Jump to SJ		11100	OI .		dicated	using!		mergency	
	or CJ					th CJ	dom's .	stop		
						00			cates using	
									/H/S	
	Lobal	DD40 nooi	امما	1			Valid made	2/2)	PR	
Pr9.105	Label Range	PR13 posi		1 Unit	1	Pulse	Valid mode Default) (5)	0	
113.103	Byte length	16bit		Attribute	_	R/W	485 addres	: e	0X6269	
	High bit of Pa		<u>۱</u>						070203	
	riigii bit oi r a	ar ro position	1, (orny vana a	Jii 19	, 400 0011	iiiiaiiioatioiij			
	Label	PR13 posit	tion(L	_)			Valid mode	e(s)	PR	
Pr9.106	Range	-21474836	48~	Unit		Pulse	Default		0	
F19.100		214748364	1 7							
	Byte length	32bit		Attribute		R/W	485 addres		0X626A	
	For Path 13 p						ble to R/W lov	w 16	bit.	
	R/W high 16 b			alized throu	gh I	Pr9.105.	Valid mode	·/o\	PR	
Pr9.107	Range	PR13 velo		Unit		rnm	Default	;(S)	60	
113.107	Byte length	16bit	0000	Attribu	ıtο	rpm R/W	485 addres	•	0X626B	
	To set PR pat		,	Attibu	110	17/77	+05 addres	3	0X020B	
	Label	PR13 acce		ion time			Valid mode	e(s)	PR	
Pr9.108	Range	1 ~ 32767		Unit	ms	s/Krpm	Default	(-)	100	
	Byte length	16bit		Attribute	R/		485 addres	s	0X626C	
	To set PR pat									
	Label	PR13 dece	elerat	ion time			Valid mode	e(s)	PR	
Pr9.109	Range	1 ~32767	Į	Jnit	ms	s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X626D	
	To set PR pat				ne	eded for				
	Label	PR13 paus	e tim				Valid mode	e(s)	PR	
Pr9.110	Range	0 ~ 32767		Unit	_	ns	Default		0	
	Byte length	16bit		Attribute		R/W	485 addres	S	0X626E	
	To set pause				nple	etion to ne		/ -\	, DB	
	Label	PR13 spec	iai pa		Τ.	,	Valid mode	e(S)	PR	
Pr9.111	Range	0 ~ 65535		Unit	/		Default		0	
	Byte length	16bit		Attribute	F	₹	485 addres	S	0X626F	
	Reserved									



	T	T ==						, ,		
5 6 4 4 6	Label	PR14 mod			Τ.	,	Valid mode	e(s)	PR	
Pr9.112	Range	0x0~0xFFI	-F	Unit	/		Default		0	
	Byte length	16bit		Attribute	ŀ	R/W	485 addres	SS	0X6270	
Dit		0.42	6.7		_			0.2		
Bit		8-13	6-7		5	N 1	4	0-3		
Definition		0-15:		osolute		No	0: Can be	0: n		
	• •	Jump to		orrespond mand		erlap, dicates	Interrupt 1: Can't be		ositioning	
		correspond path		orrespond		th SJ	Interrupt,	mot	elocity	
	1: Jump.	patri	mot	-		Overlap,	indicates		oming	
	Jump to SJ		11100	Oi		dicated	using!		mergency	
	or CJ					th CJ	dom's .	stop		
						00			cates using	
									/H/S	
	Lobal	DD44 nooi:	امما				Valid made	2/2)	PR	
Pr9.113	Label Range	PR14 posi		1 Unit	-	Pulse	Valid mode Default	2 (S)	0	
F19.113	Byte length	0~ 0xFFFF 16bit		Attribute	_	R/W	485 addres		0X6271	
	High bit of Pa		<u>۱</u>						07.027 1	
	riigii bit oi r a	ur 14 position	1, (orny vana a	Jii 19	, 400 0011	iiiiaiiioatioiij			
	Label	PR14 posit	tion(L	.)			Valid mode	e(s)	PR	
Pr9.114	Range	-21474836	48~	Unit		Pulse	Default		0	
F19.114		214748364	1 7							
	Byte length	32bit		Attribute		R/W	485 addres		0X6272	
	For Path 14 p						ble to R/W lov	w 16	bit.	
	R/W high 16 b			alized throu	gh I	Pr9.113.	Valid mode	·/o\	PR	
Pr9.115	Range	PR14 velo		Unit		rpm	Default	((5)	60	
113.113	Byte length	16bit	0000	Attribu	ıtο	R/W	485 addres	•	0X6273	
	To set PR pat		,	Attibu	110	17/77	+05 addres	3	070273	
	Label	PR14 acce		ion time			Valid mode	e(s)	PR	
Pr9.116	Range	1 ~ 32767		Jnit	ms	s/Krpm	Default	(-)	100	
	Byte length	16bit		Attribute	R/		485 addres	s	0X6274	
	To set PR pat	th 14 acceler	ation	time, time	nee	ded for 0	rpm to accele	erate	to 1000rpm	
	Label	PR14 dece					Valid mode	e(s)	PR	
Pr9.117	Range	1 ~32767		Jnit		s/Krpm	Default		100	
	Byte length	16bit		Attribute	R/		485 addres		0X6275	
	To set PR pat				ne	eded for				
	Label	PR14 paus	e tim		-		Valid mode	e(s)	PR	
Pr9.118	Range	0 ~ 32767		Unit	_	ns	Default		0	
	Byte length	16bit	- 41 - 1	Attribute		R/W	485 addres	S	0X6276	
	To set pause				nple	etion to ne		\(a\)	. DD	
D-0.440	Label Range	PR14 spec	iai pa		,	1	Valid mode Default	(5)	PR	
Pr9.119		0 ~ 65535	1	Unit	1/			_	0	
	Byte length	16bit		Attribute		₹	485 addres	S	0X6277	
	Reserved									



								. / - \	200			
	Label	PR15 mod					Valid mode	2 (S)	PR			
Pr9.120	Range	0x0~0xFFF		Unit	/		Default		0			
	Byte length	16bit		Attribute	ŀ	R/W	485 addres	S	0X6278			
D''		2.42	6.7		_			0.0				
Bit		3-13	6-7		5		4	0-3				
Definition		0-15:		solute .	1:0		0: Can be	0: n				
		lump to		rrespond		erlap,	Interrupt		ositioning			
		correspond	comr			licates	1: Can't be		elocity			
	·	oath		rrespond		:h SJ	Interrupt,	mot				
	1: Jump.		moto	or		Overlap,	indicates		oming			
	Jump to SJ or CJ					licated :h CJ	using!		mergency			
	or CJ				WIL	.n CJ		stop Indicates using				
									/H/S			
								P/ V/	/п/3			
								1				
	Label	PR15 posit	tion H				Valid mode	e(s)	PR			
Pr9.121	Range	0~ 0xFFFF	:	Unit	F	Pulse	Default		0			
	Byte length	16bit		Attribute	F	R/W	485 addres	S	0X6279			
	High bit of Pa	th 15 positior	n; (O	nly valid us	sing	485 com	nmunication)					
	Label PR15 position(L) Valid mode(s) PR											
Pr9.122	Range	-2147483648~ Unit			Pulse	Default		0				
F19.122		214748364	17	Onit					0			
	Byte length	32bit		Attribute		R/W	485 addres		0X627A			
	For Path 15 p						ble to R/W lov	w 16	bit.			
	R/W high 16 b			lized through	gh F	Pr9.121.						
D.0.400	Label	PR15 velo		1114			Valid mode	(S)	PR			
Pr9.123	Range	-10000~1	0000			rpm	Default		60			
	Byte length	16bit		Attribu	te	R/W	485 addres	S	0X627B			
	To set PR pat						Valid made	<i>(</i> -)	PR			
D=0.404	Label	PR15 acce				///	Valid mode	(S)				
Pr9.124	Range	1 ~ 32767 16bit		nit ttribute	ms R/\	s/Krpm	Default 485 addres	_	100 0X627C			
	Byte length											
	To set PR pat	PR15 dece			166	u c u 101 0	Valid mode		PR			
Pr9.125	Range	1 ~32767		nit	me	s/Krpm	Default	(3)	100			
113.123	Byte length	16bit		ttribute	R۸		485 addres	•	0X627D			
	To set PR pat											
	Label	PR15 paus			HOC	Jaca Ioi	Valid mode		PR			
Pr9.126	Range	0 ~ 32767		 Unit	n	ns	Default	(-)	0			
	Byte length	16bit		Attribute	_	R/W	485 addres	s	0X627E			
	To set pause							-				
	Label	PR15 spec			₁ 5		Valid mode	(s)	PR			
Pr9.127	Range	0 ~ 65535		Unit	/		Default	` '	0			
	Byte length	16bit		Attribute	F	{	485 addres	s	0X627F			
	Reserved	1001				-		-	J, (JL)			
	176961760											



3.2.11 [Class B] Status Parameters

	Label	Software versi	on 1 (DSP)		Valid mode(s)	P	S	T
PrB.00	Range	/	Unit	/	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	00	
	Show DSP so	ftware version in	nfo.					
	Label	Software versi	on 2 (CPLD)	Valid mode(s)	P	S	Т
PrB.01	Range	/	Unit	/	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)1	
	Show softwar	e version info.						
	Label	Software versi	on 3 (Others	3)	Valid mode(s)	P	S	Т
PrB.02	Range	/	Unit	/	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)2	
	Show softwar	e version info.						

	Label	Current alarm			Valid mode(s)	Р	S	Т
PrB.03	Range	/	Unit	/	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	03	
	Show current	alarm						

	Label	Motor not rotat	ting cause	Valid mode(s)	Р	S	T	
PrB.04	Range	/	Unit /		Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	04	
	Show cause c	of motor not rota	ting					

	Label	Driver opera	tion status		Valid mode(s)	Р	S	T
PrB.05	Range	/	Unit	/	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	05	
	Bit	Status	Description					
	0	RDY	Servo is read	dy				
	1	RUN	Servo is runr	ning				
	2	ERR	Driver error					
	3	HOME_OK	Homing com	pleted				
	4	INP	In position					
	5	AT-SPEED	Velocity reac	hed				
	6~15		Reserved					

	Label	Motor speed (I	Motor speed (Before filter)			Р	S	T
PrB.06	Range	/	Unit	rpm	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	06	
	Motor actual s	speed						

	Label	Motor torque			Valid mode(s)	Р	S	T	
PrB.07	Range	/	Unit	%	Default	/			
	Byte length	16bit	Attribute	R	485 address	0x0B0)7		
	The percentage of motor actual torque and rated torque								

	Label	Motor current			Valid mode(s)	Р	S	T
PrB.08	Range	/	Unit	0.01A	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	08	
	Motor actual of	current				•		



	Label	Label Motor speed (After filter) Va					S	T		
PrB.09	Range	/ Unit rpm			Default	/				
	Byte length	16bit	16bit Attribute R			0x0B0)9			
	Motor speed after motor actual speed filtering									

	Label	DC bus voltage	е		Valid mode(s)	Р	S	Т
PrB.10	Range	/	Unit	V	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	DΑ	
	Driver DC bus							

	Label	Driver tempera	ature	Valid mode(s)	Р	S	Т	
PrB.11	Range	/ Unit °C		Default	/			
	Byte length	16bit	Attribute	R	485 address	0x0B0)B	
Actual driver temperature								

	Label	External analo	g 1		Valid mode(s)	Р	S	T
PrB.12	Range	/	Unit	0.01V	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0	C	
	Driver analog	input 1						

	Label	External analo	g 2		Valid mode(s)	P	S	T
PrB.13	Range	/	Unit	0.01V	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)D	
	Driver analog	input 2						

	Label	External analog 3			Valid mode(s)	Р	S	T
PrB.14	Range	/	Unit	0.01V	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)E	
	Driver analog							

	Label	Motor overload rate			Valid mode(s)	Р	S	T
PrB.15	Range	/	Unit	%	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)F	
	Motor overloa	d rate						

	Label	Vent overload	rate		Valid mode(s)	P	S	T
PrB.16	Range	/	Unit	%	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B ²	10	
	Vent overload	rate						

	Label	Physical I/O in	put status		Valid mode(s)	P	S	T
PrB.17	Range	/	Unit	1	Default	/		
	Byte length	16bit	Attribute	R	485 address	0x0B0)4	
	Driver physica	al I/O input bit0 o	corresponds t	o DI1, bit1	to DI2 and so on;			
	Bitn=1, DIn+1	high level signa	al input; Bitn=	0, DIn+1 lo	w level signal inp	ut		

	Label	Cause of moto	or not rotating		Valid mode(s)	P S T
PrB.18	Range	/	Unit	1	Default	/
	Byte length	16bit Attribute R		485 address	0x0B04	
	Driver physica	al I/O output bit0	O output bit0 corresponds to DO1, bit			on;
	Bitn=1, DOn+	1 high level sign	nal output; Bit	n=0 indicate	es DOn+1 low lev	el signal output



	Label	Command posit	tion (Comma	nd unit)	Valid mode(s)	Р
PrB.20	Range	/	Unit	Р	Default	/
PrB.20	Byte length	32bit	Attribute	R	485 address	H: 0x0B14
						L: 0x0B15
					d unit: 10000 puls ılses, 10000P will	•

	Label	Motor position (Command u	nit)	Valid mode(s)	P			
PrB.21	Range	/	Unit	Р	Default	/			
110.21	Byte length	32bit	Attribute	R	485 address	H: 0x0B16			
						L: 0x0B17			
	Motor position	feedback. Drive	r command ι	nit: 10000	pulses/rev, Encod	ler unit: 8388608			
	pulses/rev. If o	driver receives 83	edback. Driver command unit: 10000 pulses/rev, Encoder unit: 8388608 er receives 8388608 pulses, 10000P will be shown.						

	Label	Position deviation (Command unit)			Valid mode(s)	P	
PrB.22	Range	/	Unit	Р	Default	/	
FID.ZZ	Byte length	32bit	Attribute	R	485 address	H: 0x0B18	
						L: 0x0B19	
Shows position deviation. Please refer to PrB.20.							

	Label	Command position (Encoder unit)			Valid mode(s)	Р			
PrB.23	Range	1	Unit	Р	Default	/			
110.25	Byte length	32bit	Attribute	R	485 address	H: 0x0B1A			
						L: 0x0B1B			
	Driver receives command pulse count. Driver command unit: 10000 pulses/rev, Encoder								
	unit: 8388608	pulses/rev. If driv	er receives	10000 puls	es, 8388608 pulse	es will be shown.			

	Label	Motor position (Encoder unit)			Valid mode(s)	Р			
PrB.24	Range	/	Unit	Р	Default	/			
110.24	Byte length	32bit	Attribute	R	485 address	H: 0x0B1C			
						L: 0x0B1D			
Driver receives motor encoder feedback pulses									

	Label	Position deviation (Encoder unit)			Valid mode(s)	Р		
PrB.25	Range	1	Unit	Р	Default	/		
115.20	Byte length	32bit	Attribute	R	485 address	H: 0x0B1E		
						L: 0x0B1F		
Shows position deviation. Please refer to PrB.23.								

	Label		Rotational encoder position feedback (Command unit)					
PrB.26	Range	/	Unit	Р	Default	/		
	Byte length	32bit Attribute R			485 address	H: 0x0B20		
						L: 0x	0B21	



Chapter 4 Control Mode

Control modes for ELD2-RS series DC servo drives can be divided into 3 categories: Position control mode, Velocity control mode and Torque control mode. RS models also come with a hybrid control mode which is a combination of any 2 modes which are above.

- Position control mode determines position through pulse count. External input pulse frequency determines rotational speed, mainly through motion controller, control card (5V pulse), PLC (24V pulse). Due to the ability of position control mode to control velocity and position tightly, it is usually use in positioning devices. It is the most widely used control mode for servo drives.
- Velocity control mode controls rotational speed through digital I/O or communication command settings. Mainly use in application where speed stability is required.

Control Mode Settings

Torque control mode is used in applications where forced applied on production material
is restricted, mainly winding or scrolling devices. For example, coil winding machines or
optical fiber cable production. Torque settings change according to the coil winding
diameter as to maintain stable force output throughout the process.

Valid mode(s)

S

To set control mode

Label

7~10

Reserved


Pr0.01*	Range	(0~10	Unit	 —	Default	0		
FIU.UI A	Byte len	gth	16bit	Attribute	R/W	485 address	0x0003		
	Valid		After rest	art					
	Value		Description						
	Value	1 st m	node	2 nd mode	♦Whe	ination hybrid			
	[0]	Pos	ition	_	· · · · · · · · ·		e can be chosen		
	1	Velo	ocity	_	accordingly with control mode switching input (C-MODE).				
	2	Tor	que	_					
	3	Pos	ition	Velocity		DE: Invalid, selec			
	4	Pos	ition	Torque		DE: Valid, select allow some time			
	5	Velo	ocity	Torque			e in between mode		
				Position Pr0.22=1	 ⇒ Switching commands. ⇒ Please set Pr0.01 = 6 to switch to other modes from PR mod, then set 2nd mode 				
	6	PR in		Velocity Pr0.22=1	using Pr0.22.				
		con	itrol	Torque	C-MODE is defaulted to Normally Ope				

Pr0.22=2




4.1 Position control

Position control determines rotational speed by frequency of external input pulse and angle of rotation through pulse count using 5V pulse from motion controller, control card or 24V pulse (Please add $2k\Omega$ resistor) for PLC. Applies where precise positioning is required.



Set Pr0.01 = 0 to activate position control mode.

Please set related servo parameters according with the following diagram.





4.1.1 Pulse input and direction settings

Position command (pulse) input method:

- 1. A and B phase pulse
- 2. Positive/Negative direction pulse
- 3. Pulse count + symbol

Set pulse mode, rotational direction and max. pulse input frequency according to actual need


CN1 Pin	Label	Definition	Description				
1/15	DI1+	Pulse command input	Low speed pulse direction command input:				
2/16	DI1-	Puise command input	PUL+ / PUL-: 5V differential input (500KHz)				
3/17	DI2+	Discretion common discret	DIR+ / DIR-: 5V differential input (500KHz)				
4/18	DI2-	Direction command input					

	Label Command pulse polarity inversion				Valid mode(s)	Р		
Pr0.06	Range	0~1 Unit —			Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x000)D	
	Valid	After restart						
Pr0.06 and Pr0.07 set command pulse input inversion and mode correspondingly.								

Pr0.07	Label	Command p	ulse input m	ode	Valid mode(s)	P		
	Range	0~3	Unit	_	Default	3		
	Byte length	16bit	Attribute	R/W	485 address	0x000)F	
	Valid	After restart						

Command pulse input Command Command pulse **Polarity Command Pulse** input mode Positive signal **Negative signal** inversion Mode settings (Pr0.06) (Pr0.07) 90°phase difference 0 2 phase pulse or (Phase A+ Phase 2 B) CW pulse [0] sequence 1 CCW pulse sequence Pulse sequence [3] Directional symbol





4.1.2 Electronic Gear Ratio

To realize correspondent motor rotational angle to arbitrarily set input command input by multiplying pulse command input from controller and coefficient of frequency divider/multiplier. Motor might not reach target velocity due to insufficient pulse output from controller. This function can be used to solve this issue by increasing pulse command frequency.

1. When Pr0.08 = 0, Pr0.09 and Pr0.10 will be valid. Other than that, Pr0.08 set value will be valid.

2. ELD2-RS series supports 2 independent sets of electronic gear ratio. The 2 sets can be switch by delivering a command frequency divider/multiplier input DIV1. Both sets of electronic gear ratio is

set up using Pr0.08, Pr0.09 and Pr0.10; Pr5.00, Pr5.01 and Pr5.02.

	Label	1st command revolution	pulse count	per	Valid mode(s)	Р	Ø	Т
Pr0.08	Range	0-67100864	Unit	PULSE	Default	10000		
	Byte length	32bit	Attribute	R/W	485 address	H: 0x00		
	Valid	After restart						

Control will affected if value set is too low. Err1b1 might occur if value < 500.

(1) Pr0.08 valid when ≠ 0: Motor revolution = input pulse count / [Pr0.08 value]

(2) Pr0.08 invalid when = 0: Pr0.09 and Pr0.10 valid.

	Label	divider/multiplier numerator				Р		
Pr0.09	Range	1~2147483647 Unit —			Default	1		
F10.09	Byte length	32bit	Attrib	R/W	485 address	H: 0x0012	2	
			ute			L: 0x0013	3	
	Valid	After restart						
Valid when Pr0.08 = 0, please refer to description in Pr0.10.								
	Label	1st command frequency divider/multiplier denominator			Valid mode(s)	Р		
D::0.40	Range	1~2147483647	Unit	_	Default	1		
Pr0.10	Byte length	32bit	Attrib	R/W	485 address	H: 0x0014	1	
			ute			L: 0x0015	;	
	Valid	After restart			_			



1. Settings:

(1)Driver command pulse input count: X

(2) Encoder pulse count after frequency divider/multiplier: Y

(3)Encoder pulse count per revolution: Z

(4)Motor revolution: W

2. Calculation:

(1) X, Y

Y = X * Pr0.09 / Pr0.10

Please keep the value of Pr0.09 and Pr0.10 to be smaller than 2²⁴ (16777216).

(2)Z

Motor with 17-bit motor: $Z = 2^{17} = 131072$

(3) Y, Z, W

W = Y / Z

Performance cannot be guaranteed if frequency divider/multiplier ratio is set to extreme values. Err1b1 might occur if W < 500.

4.1.3 Position command filter

Position command filter is to filter position command after electronic gear ratio frequency dividing/multiplying. Including position command smoothing filter and position command FIR filter.

Position command filter should be added for the following cases:


- 1. Position command pulse from controller has not yet to undergo acceleration/deceleration (with steep acceleration/deceleration).
- 2. Low command pulse frequency
- 3. Electronic gear ratio = 10 times or above

Position command filter can smoothen position command and motor rotation will be more stable

	Label	Position com	mand smooth	ning filter	Valid mode(s)	P
D-2.22	Range	0~32767	Unit	0.1ms	Default	0
Pr2.22	Byte length	16bit	Attribute	R/W	485 address	0x022D
	Valid	At stop				

To set time constant of 1 time delay filter of position command.

To set time constant of 1 time delay filter, according to target velocity Vc square wave command as show below.




Usually applied when there is rather sharp acceleration which might cause motor overshoot or undershoot. To smoothen command signal, reduces impact to machines and eliminate vibration. If Pr2.22 is set too high, overall time will be lengthened.




	Label	Position com	mand FIR filt	er	Valid mode(s)	P
D • • •	Range	0~2500	Unit	0.1ms	Default	0
Pr2.23	Byte length	16bit	Attribute	R/W	485 address	0x022F
	Valid	At stop				

As shown below, when target velocity Vc square wave command reaches Vc, it becomes trapezoidal wave after filtering.



As shown below, when target velocity Vc trapezoidal command reaches Vc, it becomes S wave after filtering.



Usually applied when there is rather sharp acceleration which might cause motor overshoot or undershoot. To smoothen command signal, reduces impact to machines and eliminate vibration. If Pr2.23 is set too high, overall time will be lengthened.

Note: Please wait for command to stop and after filter idle time to modify Pr2.23. Filter switching time = (Pr2.23 set value x 0.1ms + 0.25ms)



4.1.4 Encoder feedback output

Motor position feedback of A, B phase to master device (controller) in pulse

	Label	Encoder our revolution	tput pulse cou	nt per	Valid mode(s)	Р	S	Т
Pr0.11	Range	1~32767	Unit	P/r	Default	2500		
	Byte leng	th 16bit	Attribute	R/W	485 address	0x001	17	
Valid		After restart						
	If Pr0.11 = 1000, encoder differential output signal per revolution = 4000 pulses							
	Label	Pulse outpu	it logic inversion	on	Valid mode(s)	Р	S	T
Pr0.12	Range	0~1	Unit	_	Default	0		
P10.12	Byte leng	th 16bit	Attribute	R/W	485 address	0x0019		
	Valid	After restart	After restart					
	To set pha	ase B logic and ou	itput source fr	om encode	er pulse output. To	o invers	se B-Ph	ase
	pulse logic	c and change the	relation betwe	en Phase	A and Phase B			
	Pulse out	put logic inversi	on					
	Pr0.12	Phase B logic	CCW direc	tion	CW direction	1		
	[0]	Not inverted	A-phase		A-phase	phase		
	[0]	Not inverted	B-phase		B-phase	B-phase		
	[4]	L	A-phase		A-phase	A-phase		
	[1]	Inverted	B-phase		B-phase			



4.1.5 Positioning completed INP signal output

INP signal output will be valid when position deviation is within the range when positioning is completed. Set unit in Pr5 20


completed.	Set unit in Pr5.2	20.								
	Label	Positioning of	omplete r	ange		Valid mode(s)	P			
	Range	0~ l	Jnit	DrE	.21 set unit	Default	20			
Pr4.31		10000		FIS	.Zı set uriit		20			
	Byte length	16bit	Attribute	R/V	/	485 address	0x043F			
	Valid	Immediate	Immediate							
						pleted output sign				
						range of deviation				
	Default unit: 0. (pulse)	.00001rev. Ca	n be set oi	n Pr5	.21 as comr	mand unit (pulse)	or encoder unit			
	Label Positioning complete output setting Valid mode(s) P									
	Range	0~4	Unit	atput	Jetting	Default	1			
Pr4.32	Byte length	16bit	Attrib	ıtο	R/W	485 address	0x0441			
	,		Attible	110	17/44	+05 addic33	0,0441			
	Valid	Immediate								
		ons for INP1 ou								
	Value	Positioning				· '· · · · · · · · · · · · · · · · · ·	2.4.04			
	0					n is smaller than F				
	1	smaller than		e is r	o position c	ommand and pos	ition deviation is			
	2			ρic n	n nosition c	ommand, zero-sp	eed clamp			
						ositional deviation				
		Pr4.31	or , orginal	.00.	t and the p					
	3	Signal valid	when ther	e is r	o position c	ommand and pos	ition deviation is			
			Pr4.31. S	ignal	ON when w	vithin the time set	in Pr4.33 otherwise			
		OFF.								
	4		is no com	mano	I, position d	etection starts afte	er the delay time set			
		in Pr4.33.								
		smaller than		e is r	o position c	command and pos	itional deviation is			
	Label	INP positionii		mo		Valid mode(s)	P			
	Range	0~15000	Unit	ille	1ms	Default	0			
Pr4.33	Byte length	16bit	Attrib	ute	R/W	485 address	0x0443			
	Valid	Immediate			-					
	Valid when Pr	4.32 = 3.			1					
	Set value	Positioning	complete	d sig	ınal					
	0					xt position comma	and			
	1-15000	OFF within t	ne time se				fter receiving next			
	1-13000	position com	mand.				-			




4.2 Velocity control mode

Velocity mode precisely controls motor rotational speed/direction using analog velocity command or internal related parameters. There are 4 types of velocity control modes for ELD2-RS series DC Servo Drives: Analog control, internal velocity 4 speeds, internal velocity 8 speeds and analog + internal velocity control.

Set Pr0.01 = 1 to activate velocity control mode.




Please set related servo parameters according with the following diagram.





4.2.1 Velocity command input control

Set velocity control mode in Pr3.00



	Label	Velocity inter	nal/external s	switching	Valid mode(s)	S				
D 0 00	Range	0~3	Unit		Default	1				
Pr3.00	Byte length	16bit	Attribute	R/W	485 address	0x0301				
	Valid	Immediate								
	Connect to the	right DI to con	ight DI to control internal command velocity settings.							
	Value		Velocity settings							
	0	Analog - Vel	ocity comma	nd (SPR)						
	[1]									
	2	Internal veloc	city settings 1	st – 3 rd spe	ed (Pr3.04~P3.0	06)、Analog				
		velocity command (SPR)								
	3	Internal veloc	city settings 1	st – 8 th spe	ed (Pr3.00~Pr3.	11)				
	2	Analog - Velocity command (SPR) Internal velocity settings 1 st - 4 th speed (Pr3.04~Pr3.07) Internal velocity settings 1 st - 3 rd speed (Pr3.04~P3.06) , Analog velocity command (SPR) Internal velocity settings 1 st - 8 th speed (Pr3.00~Pr3.11)								

Velocity command direction settings

Switch velocity command direction using I/O. Assign VC-SIGN to corresponding DI terminal, velocity command direction will be in accordance to DI signal.

	Label	Velocity comma direction select		Valid mode(s)		S		
Pr3.01	Range	0~1	Unit	_	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x030	3	
	Valid	Immediate						
	To set positive	negative direction	n of velocity	comman	d			

10 set positive/negative direction of velocity command

Value	Velocity settings (Analog or internal velocity)	nalog or internal sign selection (VC-			
[0]	+	No effect	Positive		
LUI	_	No effect	Negative		
1	No effect	OFF	Positive		
	No effect	ON	Negative		



Velocity command input inversion

Set Analog-Velocity command (SPR) voltage polarity

	Label	Velocity command input inversion			Valid mode(s)	S
Pr3.03	Range	0~1	Unit	_	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0x0307
	Valid	Immediate				

To set voltage polarity of analog velocity command.

Only valid when Pr3.01 = 0. When Pr3.01 = 1, rotational direction is only related to VC-SIGN.

Value		Motor rotational direction				
[0]	Not	「Positive voltage」 → 「Positive direction」				
	inversed	「Negative voltage 」 → 「Negative direction 」				
1	Inversed	「Positive voltage 」 → 「Positive direction 」				
		\[\int Negative voltage \] → \[\int Negative direction \]				

If there is an external position sensor with different polarity from Pr3.03, motor might undergo abnormal motion.

Velocity command input gain

Set Analog-Velocity command (SPR) voltage to motor velocity command switching gain

		Label	Velocity com	mand input g	ain	Valid mode(s)	S
	Pr3.02	Range	10~2000	Unit	(r/min)/V	Default	500
		Byte length	16bit	Attribute	R/W	485 address	0x0305
		Valid	Immediate				

To set gain changes from voltage added onto analog velocity command (SPR) to motor command velocity


Pr3.02 sets command input voltage and rotational speed slope.

Factory default:

Pr3.02=500(r/min)/V.

Hence 6V input: 3000 r/min

- 1. Do not supply more than ±10V power for analog velocity command (SPR).
- 2. If Pr3.02 set value is too large, it might cause vibration.





4.2.2 Velocity command acceleration/deceleration

Acceleration/Deceleration is added onto velocity command input to control velocity. This function is valid when entering step-like velocity command or internal velocity settings is used to realize motor soft start. Use Sigmoid acceleration/deceleration to reduce vibration and impact due to changes in velocity.

	Label	Acceleration	time settings		Valid mode(s)	S
Pr3.12	Range	0~10000	Unit	ms/ (1000rpm)	Default	100
	Byte length	16bit	Attribute	R/W	485 address	0x0319
	Valid	Immediate				
	Label	Deceleration	time settings		Valid mode(s)	S
Pr3.13	Range	0~10000	Unit	ms/ (1000rpm)	Default	100
	Byte length	16bit	Attribute	R/W	485 address	0x031B
	Valid	Immediate				

Set max acceleration/deceleration for velocity command.

If target velocity = x [rpm], max acceleration = a [unit: rpm/ms], acceleration time = t [ms]

Pr3.12 = 1000/a

Pr3.13 = 1000/a


a = x/t

Velocity Initial acceleration

With added acceleration deceleration

For extemple: If motion is to achieve 1500rpm in 300s,eaetf.500/30=50rpm/ms

Pr3.12 = 1000/a = 20, Hence when Pr3.12 = 20, motor can achieve 1500rpm in 30s.




Usually used when there is rapid acceleration or trapezoidal wave velocity command due to many different internal speed segments under velocity control mode which causes instable while motor in motion.

Under velocity control mode, 6083 and 6084 is limited by Pr3.12 and Pr3.13 correspondingly.

	Label	Sigmoid acceler settings	ration/decele	Valid mode(s)		S		
Pr3.14	Range	0~1000	Unit	ms	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x031	D	
	Valid	After restart						





4.2.3 Velocity reached signal AT-SPEED output

Velocity reached signal AT-SPEED output will be valid when motor velocity reached set speed in Pr4.36. This output function can be assigned through I/O configurations, please refer to Pr4.10. When velocity matches set conditions, assigned I/O terminal will be ON, signal will be valid.

	Label	Arrival velocity			Valid mode(s)	S			
Pr4.36	Range	10~2000	Unit	r/min	Default	1000			
F14.50	Byte length	16bit	Attribute	R/W	485 address	0x0449			
	Valid	Immediate							
	When motor velocity > Pr4.36, AT-speed output signal is valid. Detection using 10RPM hysteresis.								
	Velocity [r/min] Pr4.36+10 Pr4.36-10								
	-(Pr4.36–10) -(Pr4.36+10) 	DFF ON	OFF	ON	Πι	ne			



4.2.4 Velocity coincidence V-COIN signal output

V-COIN signal output will be valid when velocity command (before acceleration/deceleration) coincides with motor velocity. Velocity is considered to be coincided if the difference between velocity command before acceleration/deceleration from servo drive and motor velocity is within the value set in Pr4.35. This output function can be assigned through I/O configurations, please refer to Pr4.10. When velocity matches set conditions, assigned I/O terminal will be ON, signal will be valid.


In Position signal in PV mode is in synchronization with V-COIN signal.

Pr4.35	Label	Velocity coincidence range			Valid mode(s)	S
	Range	10~2000	Unit	r/min	Default	50
	Byte length	16bit	Attribute	R/W	485 address	0x0447
	Valid	Immediate				

If the difference between velocity command and motor actual speed is below Pr4.35, Velocity coincidence (V-COIN) output signal valid.

Due to 10RPM hysteresis:

Velocity coincidence output OFF -> ON timing (Pr4.35 -10) r/min Velocity coincidence output ON -> OFF timing (Pr4.35 +10) r/min



4.2.5 Zero Speed Clamp

Forced set velocity command to 0 using zero speed clamp to avoid servo axis from crawling at low velocity.

This input function can be assigned through I/O configurations, please refer to Pr4.00.

Includes conditions from 1 and 2

	Label		Zero speed o	clamp function s	election	Valid mode(s)	S	
Pr3.15	Range		0~3	Unit	_	Default	0	
	Byte length		16bit	Attribute	R/W	485 address	0x031F	
	Valid		Immediate					
	Value		Zero speed clamp function					
	0	Inval	id: zero speed	clamp deactiva	ited			
	1		Velocity command is forced to 0 when the zero speed clamp (ZEROSPD) input signal is valid.					
	2	Velo	city command	is forced to 0 w	hen actual	velocity is lower th	an Pr3.16.	


	Label	Zero speed clamp	level		Valid mode(s)	S
Pr3.16	Range	10~2000	Unit	r/min	Default	30
	Byte length	16bit	Attribute	R/W	485 address	0x0321




Valid	Immediate							
Valid when Pr3.15 = 2/3, velocity command is forced to 0 when actual velocity is lower than Pr3.16 and								
after static time	set in Pr3.23.							

4.3 Torque control

Torque control mode is to the size of motor asserted torque through external analogue input or directly from set value internally. This control mode is applicable where torque is the main control and limiting factor.



Using Motion Studio, set Pr0.01 = 2 to activate torque control mode. Please set related servo parameters according with the following diagram.






4.3.1 Torque command input control

Torque control mode settings

Torque control mode includes 3 control modes as shown below. Set torque control mode in Pr3.17.



D 0 47	Label	Torque interna	l/external swit	ching	Valid mode(s)		T
	Range	0~2	Unit		Default	0	
Pr3.17	Byte length	16bit	Attribute	R/W	485 address	0x0323	
	Valid	Immediate					

Value	Torque command input	Velocity limit input
[0]	Analog input 3(Al 3)	Pr3.21 set value
1	Analog input 3(Al 3)	Analog input 1(Al 1)
2	Pr3.22 set value	Pr3.21 set value



Torque command direction settings

To switch velocity command direction through DI. Assign TC-SIGN signal to corresponding DI terminal and determine velocity command direction through digital input signal.

D-2.40	Label	Torque command of	Torque command direction selection					T
	Range	0~1	Unit	_	Default	0		
Pr3.18	Byte length	16bit	Attribute	R/W	485 address	0x0325	5	
	Valid	Immediate						

To set torque command positive/negative direction

<u></u>	out torque	command positive/negative direction
	Value	Direction settings
	[0]	TC-SIGN ON/OFF has no effect on torque direction Torque command input 「Positive」→Positive direction、 「Negative」→Negative direction
	1	Use TC-SIGN ON/OFF status for torque direction OFF: Positive direction ON: Negative direction

Torque command input inversion

To set the voltage polarity added onto analogue torque command (TRQR)

	Label	Torque command input inversion			Valid mode(s)			T
Pr3.20	Range	0~1	Unit	_	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x0329)	
	Valid	Immediate					•	

To set voltage polarity of analog torque command.

Only valid when Pr3.18 = 0.

Value	Motor torque direction					
[0]	Not inversed	$\lceil \text{Positive voltage} \rfloor \rightarrow \lceil \text{Positive direction} \rfloor$				
		$\lceil \text{Negative voltage} \rfloor \rightarrow \lceil \text{Negative direction} \rfloor$				
1	Inversed	「Positive voltage」 → 「Positive direction」				
		\[\text{Negative voltage } \] \[\text{Negative direction } \]				


Torque command input gain

To set voltage added on to switching gain of motor torque command from analog torque command(TRQR)

Pr3.19	Label	Torque comma	and input gain		Valid mode(s)	Т
	Range	10~100	Unit	0.1V/100%	Default	30
	Byte length	16bit	Attribute	R/W	485 address	0x0327
	Valid	Immediate				

To set gain changes from voltage added onto analog torque command (TRQR) to torque command (%)

- ·Unit: (0.1V/100%) 。
- •Set input voltage required for rated output torque.
- ·Default = 30, which is 3V/100%





4.3.2 Torque velocity limit

To set velocity limit in torque mode for safety reasons.

	Label	Velocity limit in to	rque mode		Valid mode(s)		T	
D-0.04	Range	0~10000	Unit	r/min	Default	0		
Pr3.21	Byte length	16bit	Attribute	R/W	485 address	0x032B		
	Valid	Immediate						
To set velocity limit in torque control mode. Only valid when Pr3.17 = 0 / 2.								
	Label	Torque comman	nd		Valid mode(s)		T	
D 0 00	Range	0~300	Unit	%	Default	0		
Pr3.22	Byte length	16bit	Attribute	R/W	485 address	0x032D		
	Valid	Immediate						
	To set torque lir	set torque limit in torque control mode. Only valid when Pr3.17 = 2.						
	Please refer to	Pr3.17.						

4.3.3 Torque limit (TL-SEL)

This input function can be assigned through I/O configurations, please refer to Pr4.00.

To set torque limiting method.

	Label	Torque limit select	ion		Valid mode(s)	P	S	T
DrE 24	Range	0~6	Unit	_	Default	0		
Pr5.21	Byte length	16bit	Attribute	R/W	485 address	0x052l	В	
	Valid	Immediate						

Value		Limit
[0]		1 st torque limit Pr0.13
1		2 nd torque limitPr5.22
0	TL-SEL OFF	Pr0.13
2	TL-SEL ON	Pr5.22
3~4		Reserved
5		Pr0.13 →Positive torque limit Pr5.22 →Negative torque limit

		Label	2 nd torque limit			Valid mode(s)	Р	S	Т
		Range	0~500	Unit	%	Default	300		
Pr5.22		Byte length	16bit	Attribute	R/W	485 address	0x052D		
		Valid	Immediate						

Pr5.22 is limited by max. torque set in motor parameter.

	Label	1 st torque limit			Valid mode(s)	Р	S	T
Pr0.13	Range	0~500	Unit	%	Default	350		
	Byte length	16bit	Attribute	R/W	485 address	0x001E	3	
	Valid	Immediate					•	

^{1&}lt;sup>st</sup> torque limit is set according to ratio percentage of motor rated current. Do not exceed max driver output current.

Please refer to Pr5.21 on how to set torque limit.



4.4 Hybrid Control Mode

Hybrid control mode is for servo drive to be able to switch between different modes during operation. Hybrid control mode consists of the 3 listed below:

- Position-velocity mode
- Position-torque mode
- Velocity-torque mode

Set Pr0.01 to select the hybrid control mode needed through Motion Studio or servo drive front panel.

	Label		Control Mo	de Settings		Valid mode(s)	P	S	T			
Pr0.01	Range	Range 0~10		Unit	_	Default	0					
PIU.UI	Byte leng	jth	16bit	Attribute	R/W	485 address 0x0003						
	Valid		After restar	rt .								
					_							
	Value	Value Desc										
	value			2 nd mode		a 3, 4, 5, 6 combination hybrid mode, 1 st and						
	[0]	P	osition	_	2 nd mod	e can be chosen acc	cordingly	with con	trol			
	1	V	elocity	_		mode switching input (C-MODE).						
	2	Т	orque	_	C-MODE: Invalid, select 1 st mode.							
	3	P	osition	Velocity		C-MODE: Valid, select 2 st mode.						
	4	P	osition	Torque		ease allow some time in between mode switching						
	5	V	elocity	Torque	commands.				doo			
				Position Pr0.22=1	 ◆Please set Pr0.01 = 6 to switch to other mode from PR mod, then set 2nd mode using Pr0.22. C-MODE is defaulted to Normally Open 							
	6		internal mmand	Velocity Pr0.22=1								
		control		Torque Pr0.22=2								
	7~10	Re	eserved									

When Pr0.01 = 3/4/5, please set assign C-MODE mode switching signal to one of the DI terminal and make sure the logic is valid.


Signal	Set value	Label	Description			
			Pr0.01	C-MODE	Control mode	
		Control mode switching	2	Invalid	Position mode	
	0x5		3	Valid	Velocity mode	
C-MODE			4	Invalid	Position mode	
			switching	4	Valid	Torque mode
			5	Invalid	Velocity mode	
			5	Valid	Torque mode	



Chapter 5 Application Case

5.1 Gain Adjustment

In order for servo driver to execute commands from master device without delay and to optimize machine performance, gain adjustment has to be done yet.




Velocity loop integral time constant: 31ms

Velocity loop integral time constant: 31ms

Position loop gain: 320 (0.1/s) Position loop gain: 900 (0.1/s) Position loop gain: 900 (0.1/s) Velocity loop gain: 180 (0.1Hz) Velocity loop gain: 500 (0.1Hz) Velocity loop gain: 500 (0.1Hz) Velocity loop integral time constant: 31ms

Servo driver gain adjustment is done in combination with a few other parameters (Inertia ratio, Position loop gain, Velocity loop gain and Filters settings). These parameters will have an effect on each other so it always advisable to tune each parameter according in order to achieve optimal machine performance. Please refer to the steps below





Gain Adjustment Flow Chart



Steps	Functions	Explanation
Inertia ratio identification	Online	Motor moves with command from controller, servo driver will automatically calculate load-inertia ratio
Auto gain adjustment	Auto gain adjustment	Real time determining of mechanical load, gain value is set accordingly. 1. One-click tuning (Can be realized using Motion Studio. Auto tuning of gain and inertia according to actual data) 2. Real time auto adjustment (Set by selecting mechanical stiffness level, related gain parameters will be automatically adjusted accordingly)
	Basic gain	On top of auto gain adjustment, manually adjust related parameters so that machine can have better responsiveness and following
	Basic steps	 Gain related parameters tuning under position mode Gain related parameters tuning under velocity mode Gain related parameters tuning under torque mode
Manual gain	Gain switching	Gain switching through internal data or external signal. Lower vibration at stop, shorten tuning time, improve command following.
adjustment	Model following control	Improve responsiveness, shorten positioning time (Only available in position mode)
	Command pulse filter	Set filter for position, velocity and torque command pulse.
	Gain feedforward	Enable feedforward function to improve following behavior
	Friction compensation	Reduce the effect of mechanical friction
	3 rd gain switching	Base on usual gain switching function. Can be set to switch gain at stopping and reduce positioning time.
Vibration	Mechanical	Using notch filtering function to suppress mechanical
suppression	resonance	resonance.
	End vibration suppression	To suppress low frequency vibration of mechanical end

5.2 Inertia ratio identification function

Inertia ratio = Total mechanical load rotational inertia / Motor rotational inertia

Inertia ratio is an important parameter. Setting a suitable value can help with the precise tuning of the servo system. Inertia ratio can be set manually and also be determined automatically through servo driver

To make sure accurate inertia ratio identification:

- 1. Max rotational velocity at 400rpm
- 2. Acceleration/deceleration time above 100ms
- 3. Stable load torque without large variation.




Online inertia determination

Enable motor using controller. Let motor run at above 400rpm, make sure there are acceleration, constant velocity and deceleration phase during the whole run. Cycle through 2-3 times to calculate load-inertia ratio. Result can be found on the front panel d16 or through Motion Studio system monitoring page. Enter the calculated value into Pr0.04 and save.

Inertia measuring using Motion Studio


- 1. Start Motion Studio and maneuver to inertia ratio identification page under performance tuning. Set trial run velocity Pr6.04 and acc-/deceleration time Pr6.25, click on 'Upload' to upload parameters to servo driver.
- 2. Tick "Prohibit external enabling" and click on "servo on".
- 3. Click and hold "CCW" to start the motor. Current position will show motor cycles of revolution. Click on POS 1 to save current position as starting point. Click and hold "CW" to start the motor again. Click on POS 2 to save current position as ending point.
- 4. Set the waiting time between each cycle in Pr6.21 and no. of cycles in Pr6.22. Click on 'Run' and motor will run according to the parameters set.



5. After the calculation is done, inertia ratio will be calculated automatically and click on 'write' to enter the calculated value into Pr0.04.



6. Click on "Parameter List" to enter parameters management to check or modify Pr0.04. Then, click on "Save" to save parameters to driver.



Please take note:

- 1. Trial run velocity and distance should be optimal to prevent any axis from bumping into objects.
- 2.It is recommended to move only in 1 direction for vertically mounted axis. Take precaution before moving the axis.
- 3. For applications with higher frictional drag, please set a minimal travel distance.

	Label	Inertia ratio			Valid mode(s)	Р	S	T
Pr0.04	Range	0~20000	Unit	%	Default	250		
P10.04	Byte length	16bit	Attribute	R/W	485 address	0x0009		
	Valid	Immediate						

Pr0.04=(load inertia/motor rotational inertia)×100%

Set inertia ratio according to actual load inertia. When both are uniform, actual motor velocity loop responsiveness and gain settings will be consistent. If inertia ratio is greater than actual value, velocity loop gain settings will be higher and vice versa. For motor with high inertia, Pr0.04 can be left unfilled but optimal setting of Pr0.04 could improve system performance

Common issues

Error	Cause	Solution
	Loose load connection	Check for mechanical failure
Inertia measuring	Measuring distance is too short	Increase measuring distance
failure	Belt load	Please pre-set an inertia ratio when using a belt to prevent jolt due to low inertia.



5.3 Auto gain adjustment

This function will measure real time mechanical properties and set gain values in accordance to mechanical stiffness. Can be used in any control mode

moonanioan caminocon camino acca in any contract						
	Conditions to implement					
Control mode	Please refer to Pr0.02 for detailed explanations. Auto gain adjustment is different for each control mode.					
Other	Servo driver needs to be enabled Set up input signals such as deviation counter clearing and command input; Torque limit and other motion control parameters to enable motor to move normally without obstacles.					

• Under certain conditions, external factors might affect automatic gain adjustment functions. If the conditions as listed exist or unfavorable, please disable the automatic gain adjustment function.

	Affecting conditions					
Load inertia	If inertia is less than 3 times or over 20 times of rotor inertia.					
Loau mertia	Changes in load inertia					
Lood	Very low mechanical stiffness					
Load	If gear backlash is a non-linear property					
	Velocity less than 100r/min or continuously in low velocity mode					
	 Acc-/deceleration to 2000r/min within 1s. 					
Motion	 Acc-/deceleration torque lower than eccentric load, frictional torque. 					
	· Velocity < 100r/min, acc-/deceleration to 2000r/min within 1s but not					
	longer than 50ms					

To enable automatic gain adjustment:

- 1. Disable the servo driver.
- 2. Set Pr0.02 = 0x01/0x11 or 0x02/0x12. Then, set Pr0.03
- 3. Servo enabled. Run motion as normal to start measuring load properties. Related parameters will be automatically set.
- 4. Increase motor responsiveness by increasing Pr0.03. Please check if there is any vibration before setting Pr0.03 to max. value.
 - 5. Save the parameters.

Please take note:

- Please stop the motor before modifying any parameter. Pr0.02 only takes effect after saving modified parameter values into EEPROM and restarting the driver.
- After enabling the servo driver for the first time or when increasing Pr0.03, mechanical noise or vibration might occur for the first run, it is normal. If it persists, please set Pr0.03 to lower value. Parameters that change in accordance to real time gain adjustment



There are 2 types of auto gain adjustment methods:

• Standard mode (Pr0.02 = 0x_1): Basic mode, prioritizing on stability, gain switching is disabled. Actual gain auto adjustment as accordance to Pr0.03.

Gain related parameters that change as shown below.

Parameter	Label	Remarks
Pr1.00	1 st position loop gain	
Pr1.01	1 st velocity loop gain	When stiffness setting is valid
Pr1.02	1 st velocity integral time	When stiffness setting is valid, parameters will be updated to
	constant	match stiffness value
Pr1.03	1 st velocity detection filter	materi stilliess value
Pr1.04	1 st torque filter	

Gain related that doesn't change

Parameter	Label	Reference value	Remarks
Pr1.10	Velocity feedforward	300 (0.1%)	Doesn't change
	gain constant		according to changes
			in stiffness

Positioning mode (Pr0.02=0x2): Prioritizing positioning. Usually applies on horizontal axis without variable load, ball screws with lower friction, gain switching enabled. Stiffness level of 2nd position loop gain is 1 level higher than 1st position.

No.	Parameters	Label	Remarks
1	Pr1.00	1 st position loop gain	
2	Pr1.01	1 st velocity loop gain	
3	Pr1.02	1 st velocity integral time	
		constant	
4	Pr1.03	1 st velocity detection filter	
5	Pr1.04	1 st torque filter	When stiffness setting is valid,
6	Pr1.05	2 nd position loop gain	parameters will be updated to
7	Pr1.06	2 nd velocity loop gain	match stiffness value
8	Pr1.07	2 nd velocity integral time	
		constant	
9	Pr1.08	2 nd velocity detection	
		filter	
10	Pr1.09	2 nd torque filter	

If auto gain adjustment is valid, the parameters listed above can't be manually modified. Only when Pr0.02 = 0x00 or 0x10, can the gain related parameters be modified manually.

Gain related parameters that don't change with the real time gain adjustment

Parameter	Label	Reference value
Pr1.10	Velocity feedforward gain constant	1000ms
Pr1.11	Velocity feedforward filter time constant	30%
Pr1.12	Torque feedforward gain	0.50ms
Pr1.13	Torque feedforward filter time constant	0
Pr1.15	Position control gain switching mode	0
Pr1.17	Position control switching level	10
Pr1.18	Position control switching hysteresis	50
Pr1.19	Position gain switching time	33



Types of mechanical load
Please select mechanical load according to load-inertia ratio and mechanical structures:

Load types	Description					
0x00_ : Rigid structure	When load is rigid with relatively low inertia . Gain adjustments prioritize system responsiveness . Structures including high precision reducer, lead screws, mechanical gears, etc.					
0x01_ : High inertia	High load inertia (10 times or above). Gain adjustments prioritize operation stability and responsiveness . Recommended mechanical stiffness level not more than 15 .					
0x02_ : Flexible structure	When load is flexible with relatively high inertia . Gain adjustments prioritize operation stability . Structures including long transportation belt or chain.					

Structures with high inertia can have better performance if inertia ratio is set accurately.

	Range Byte length		Real time Auto Gain Adjusting			Valid mode(s)	P	S	Т
Pr0.02			0x0~0xFFF	Unit	_	Default	0x1		
Pru.uz			16bit	Attribute	R/W	485 address	0x0005		
	Valid			Immediate					
Data bits	Category	:	Settings	Application					
		charac 1 with position	cteristics or se n good gener	etting requiren ality when the	nents. Ger re is no s	can be selected acc nerally, it is recomm special requiremen 2 cannot meet the	nended t t, mode	o select r 2 when	node rapid
	Motion	0:	Manual	Pr0.03 invalid. Gain value must be adjusted manually and accordingly.					
0x00_	setting mode	1:S	tandard	Pro.03 valid. Quick gain adjusting can be achieved by changing Pro.03 stiffness value. Gain switching is not used in this mode suitable for applications with requirements for stability.					
		2:Pc	ositioning	Pr0.03 stiffne requiring quic	ss value. k position	n adjusting can be This mode is sui ing. Not recommer please compensa	table fonded for	r applica load mou	itions unted



0x0_0	Load type setting	Used to select the load type, choose according to load-inertia ratio and mechanical structure.						
		0: Rigid structure	This mode prioritizes system responsiveness. Use this mode when there is a relatively rigid structure with low load inertia. Typical application including directly connected high-precision gearbox, lead screw, gears, etc.					
		1:High inertia For applications with higher load inertia (10 times or gain settings take into account both machine stabil responsiveness. Not recommended to set stiffness above high load inertia.						
		2: Flexible structure	This mode prioritizes system stability. Use this mode when there is low rigidity structure with high load inertia. Typical applications included belts and chains.					
0x_00	reserved							

The setting type combination is a hexadecimal standard, as follows:

Setting type combination	Application type
0X000	Rigid structure + Manual
0X001	Rigid structure +Standard
0X002	Rigid structure +Positioning
0X010	High inertia + Manual
0X011	High inertia + Standard
0X012	High inertia + Positioning
0X020	Flexible structure + Manual
0X021	Flexible structure +Standard
0X022	Flexible structure +Positioning

Label		Real time auto stiffness adjusting			Valid mode(s)	Р	S	Т	
Pr0.03	Range	0~31	0~31 Unit —		Default	11			
	Byte length	16bit	Attribute	R/W	485 address	0x00	07		
	Valid	Immediate	Immediate						
	Low → Mechanical stiffness → High Low → Servo gain → High 81.80 · · · · · · · · · · · · · · · · · · ·								



Gain parameters settings table


		1	st gain		2 nd gain				
SS	Pr1.00	Pr1.01	Pr1.02	Pr1.04	Pr1.05	Pr1.06	Pr1.07	Pr1.09	
Stiffness	Position loop gain (0.1/s)	Velocity loop gain (Hz)	Velocity loop integral time constant (0.1ms)	Torque filter (0.01ms)	Position loop gain (0.1/s)	Velocity loop gain (Hz)	Velocity loop integral time constant (0.1ms)	Torque filter (0.01ms)	
81	20	15	3700	1500	25	15	10000	1500	
80	25	20	2800	1100	30	20	10000	1100	
79	30	25	2200	900	40	25	10000	900	
78	40	30	1900	800	45	30	10000	800	
77	45	35	1600	600	55	35	10000	600	
76	55	45	1200	500	70	45	10000	500	
75	75	60	900	400	95	60	10000	400	
74	95	75	700	300	120	75	10000	300	
73	115	90	600	300	140	90	10000	300	
72	140	110	500	200	175	110	10000	200	
71	175	140	400	200	220	140	10000	200	
70	320	180	310	126	380	180	10000	126	
69	390	220	250	103	460	220	10000	103	
68	480	270	210	84	570	270	10000	84	
67	630	350	160	65	730	350	10000	65	
66	720	400	140	57	840	400	10000	57	
65	900	500	120	45	1050	500	10000	45	
64	1080	600	110	38	1260	600	10000	38	
63	1350	750	90	30	1570	750	10000	30	
62	1620	900	80	25	1880	900	10000	25	
61	2060	1150	70	20	2410	1150	10000	20	
60	2510	1400	60	16	2930	1400	10000	16	
59	3050	1700	50	13	3560	1700	10000	13	
58	3770	2100	40	11	4400	2100	10000	11	
57	4490	2500	40	9	5240	2500	10000	9	
56	5000	2800	35	8	5900	2800	10000	8	
55	5600	3100	30	7	6500	3100	10000	7	
54	6100	3400	30	7	7100	3400	10000	7	
53	6600	3700	25	6	7700	3700	10000	6	
52	7200	4000	25	6	8400	4000	10000	6	
51	8100	4500	20	5	9400	4500	10000	5	
50	9000	5000	20	5	10500	5000	10000	5	



5.4 Manual gain adjustment

Due to limitation of load conditions, automatic gain adjustment might not achieve expected performance. Control can be improved through manual gain adjustment

The servo system is made up of 3 control loops. From outer to inner: position loop, velocity loop, current loop as shown in the diagram below.



Inner control loop demands higher responsiveness. In order to avoid system instability, please tune in accordance to this principle. Current loop gain usually satisfies the responsiveness demand without tuning. When gain adjustment is done under position control mode, in order to keep the system stabile, position and velocity loop gain have to be increased at the same time to make sure the responsiveness of the position loop is lower than velocity loop.

Step	ning (Positi Parameter	Label	Tuning method
			Determine if velocity loop is able to follow the changes in velocity command at highest frequency. If Pr0.04 is set correctly, velocity loop highest following frequency = Pr1.01
			Increase Pr1.01 Velocity command Actual velocity
1	Pr1.01	Velocity loop gain	
			Increase Pr1.01 provided there is no noise or vibration to reduce positioning time, better velocity stability and following. Reduce Pr1.01 if there is mechanical noise.



Step	Parameter	Label	Tuning method
			To eliminate velocity loop deviation
2	Pr1.02	Velocity loop integral time constant	Reduce Pr1. 02 ———————————————————————————————————
3	Pr1.00	Position loop gain	Increase Pr1.00 ——— Position loop is able to follow the changes in position command at highest frequency. Position loop highest following frequency = Pr1.00 Increase Pr1.00 ——— Position command Actual Position Increase Pr1.01 ———————————————————————————————————
4	Pr1.04	1 st torque filter time constant	Eliminate high frequency noise, suppress mechanical resonance. ———————————————————————————————————



- 1. If vibration occurs with increasing Pr1.01, please modify Pr1.04 to suppress vibration.
- 2. If the parameters are set too high, it might cause current loop response to reduce.
- 3. To suppress vibration at stop, increase Pr1.01 and decrease Pr1.04.
- 4. Decrease Pr1.04 if motor vibrates too much at rest.
- 5. Pr1.04 cannot be set to overly high value as it might cause control system instability because the torque loop response is much higher than velocity loop.

For servo gain, if any one of the parameters is changed, please modify other gain related parameters accordingly. Make sure to the change at around 5% and follow the rules as below.

- 1) Increase responsiveness
 - a) Reduce torque command filter time
 - b) Increase velocity loop gain
 - c) Decrease velocity loop integral time
 - d) Increase position loop gain
- 2) Decrease responsiveness, prevent vibration and over shoot
 - a) Reduce position loop gain
 - b) Increase velocity loop integral time
 - c) Reduce velocity loop gain
 - d) Increase torque filter time

5.4.1 Parameters adjustment under different control modes

Under different control mode, parameters adjustment has to be adjusted in this order: "Inertia measuring" -> "Auto gain adjustment"-> "Manual gain adjustments"

Position control mode

Set load-inertia ratio Pr0.04 after inertia determination.

No.	Parameter	Label
1	Pr1.00	1 st position loop gain
2	Pr1.01	1 st velocity loop gain
3	Pr1.02	1 st velocity integral time constant
4	Pr1.03	1 st velocity detection filter
5	Pr1.04	1 st torque filter time constant
6	Pr1.05	2 nd position loop gain
7	Pr1.06	2 nd velocity loop gain
8	Pr1.07	2 nd velocity integral time constant
9	Pr1.08	2 nd velocity detection filter
10	Pr1.09	2 nd torque filter time constant
11	Pr1.10	Velocity feedforward gain constant
12	Pr1.11	Velocity feedforward filter time constant
13	Pr1.12	Torque feedforward gain
14	Pr1.13	Torque feedforward filter time constant
15	Pr1.15	Position control gain switching mode
16	Pr1.17	Position control switching level
17	Pr1.18	Position control switching hysteresis
18	Pr1.19	Position gain switching time



1st and 2nd gain initial values are obtained by automatic gain adjustment

No.	Parameter	Label
1	Pr1.00	1 st position loop gain
2	Pr1.01	1 st velocity loop gain
3	Pr1.02	1 st velocity integral time constant
4	Pr1.03	1 st velocity detection filter
5	Pr1.04	1 st torque filter time constant
6	Pr1.05	2 nd position loop gain
7	Pr1.06	2 nd velocity loop gain
8	Pr1.07	2 nd velocity integral time constant
9	Pr1.08	2 nd velocity detection filter
10	Pr1.09	2 nd torque filter time constant

Manually adjusted gain parameters

No.	Parameter	Label
1	Pr1.00	1 st position loop gain
2	Pr1.01	1 st velocity loop gain
3	Pr1.02	1 st velocity integral time constant
4	Pr1.04	1 st torque filter time constant
5	Pr1.10	Velocity feedforward gain constant
6	Pr1.11	Velocity feedforward filter time constant

Velocity control mode

Velocity control mode parameters adjustment is pretty similar to position control mode. Except for position loop gain Pr1.00 and Pr1.05, velocity feedforward gain (Pr1.10)

Torque control mode

Parameters adjustment for torque control mode has to be differentiate into 2 conditions:

- 1. When actual velocity reaches velocity limit, adjustment will be as per velocity control mode. Motor will switch from torque control to velocity limit as velocity control.
- 2. When actual velocity doesn't reach velocity limit yet, Except for position loop gain, velocity loop gain and feedforward gain, parameter adjustments as per velocity control mode.

If there is no velocity limit and control is through torque command, please deactivate torque and notch filter, set velocity limit to max. value and increase velocity loop gain to as high as possible.




5.4.2 Gain switching

Gain switching function can be triggered internally in servo driver. Only valid under position or velocity control mode. Following effects can be realized by gain switching:


- 1. Switch to lower gain when motor stops to suppress vibration
- 2. Switch to higher gain when motor is moving at a low velocity to shorten positioning time
- 3. Switch to higher gain when motor is moving at a high velocity to improve command following behavior.

Diagram below shows gain switching when motor stops.



1st gain (Pr1.00-Pr1.04) and 2nd gain (Pr1.05-Pr1.09) switching can be realized through manual and positioning mode. Switching condition is set through Pr1.15. Gain switching is invalid under standard mode.





ated parameters on gain switching							
No.	Parameter	Label	Remarks				
1	Pr1.15	Position control gain switching mode	In position control, set Pr1.15=3、5、6、9、10. In velocity control, set Pr1.15=3、5、9				
2	Pr1.17	Position control level switching	Please set Pr1.17≥Pr1.18				
3	Pr1.18	Position control hysteresis switching	If Pr1.17 <pr1.18, driver="" pr1.17<br="" set="" will="">=Pr1.18</pr1.18,>				
4	Pr1.19	Position gain time switching	As shown below				



	Label	Position control gain switching mode			Valid mode(s)	P
Pr1.15	Range	0~10	Unit	_	Default	0
P11.15	Byte length	16bit	Attribute	R/W	485 address	0x011F
	Valid	Immediate				

In position control, set the conditions for gain switching to be valid.

		ditions for gain switching to be valid.
Value	Condition	Gain switching condition
[0]	1 st gain fixed	Fixed on using 1 st gain(Pr1.00-Pr1.04)
1	2 nd gain fixed	Fixed on using 2 nd gain (Pr1.05-Pr1.09)
2	Gain switching input valid	 Gain switching input (GAIN) invalid: 1st gain. Gain switching input (GAIN) valid: 2nd gain. *Default: 1st gain
3	High command torque	Switch to 2 nd gain when set torque command absolute value larger than (level + hysteresis)[%] Switch to 1 st gain when set torque command absolute value smaller than (level + hysteresis)[%] Acceleration Constant Deceleration Speed Torque 1st 2nd 1st 2nd 1st
4-9	Reserved	Reserved
10	Pending position command +actual velocity	Valid for position control. Switch to 2 nd gain if position command ≠ 0 Switch to 1 st gain if positional command = 0 throughout the duration of delay time and absolute value of actual velocity remains smaller than (level - hysteresis) (r/min) Position Command Velocity Feedback Switch when both conditions fulfilled Hysteresis Level Level Level Level Level Level Level Tist Note The position command ≠ 0 The position command = 0 The posit

** Above 'level' and 'hysteresis' are in correspondence to Pr1.17 Position control gain switching level and Pr1.18 Hysteresis at position control switching.

	contenting teret and trine trijeter eate at peanten eath of articling.								
	Label	Position contr	ol gain switc	hing level	Valid mode(s)	P			
Pr1.17	Range	0~20000	Unit	Mode dependent	Default	50			
	Byte length	16bit	Attribute	R/W	485 address	0x0123	3		
	Valid	Immediate							



Set threshold value for gain switching to occur.

Unit is mode dependent.

Switching condition	Unit		
Position	Encoder pulse count		
Velocity	RPM		
Torque	%		

Please set level ≥ hysteresis

	Label	Hysteresis at po	sition contro	ol switching	Valid mode(s)	P
Dr1 10	Range	0~20000		Mode dependent	Default	33
Pr1.18	Byte length	16bit	Attribute	R/W	485 address	0x0125
	Valid	Immediate				


To eliminate the instability of gain switching. Used in combination with Pr1.17 using the same unit.

If level< hysteresis, drive will set internally hysteresis = level.

	Label	Position contro	l switching tin	ne	Valid mode(s)	P
	Range	0~10000	Unit	0.1ms	Default	33
Pr1.19	Byte	16bit	Attribute	R/W	485 address	0x0127
	length					
	Valid	Immediate				

During position control, if 1st and 2nd gain difference is too large, to ease torque changes and vibration due to rapid changes in position loop gain, set suitable Pr1.19 value

For example: 1st (pr1.00) <-> 2nd (Pr1.05)






5.5 3rd gain switching

Besides switching between 1st and 2nd gain, a 3rd gain switching is added to set gain at the moment of stopping to reduce positioning time.

Only available under position mode and $Pr6.05 \neq 0$, set Pr6.06 for 3^{rd} gain value. When 2^{nd} gain switches to 1^{st} gain, it has to go through 3^{rd} gain, switching time is set in Pr1.19.

Diagram below shows when Pr1.15 = 7.




Position loop gain = Pr1.00 × Pr6.06/100

Velocity loop gain = Pr1.01 × Pr6.06/100

Velocity loop integral time constant, velocity detection filter, torque filter time constant will still be applied in 1st gain

Related parameters										
	Label	Position 3 rd gai	n valid time		Valid mode(s)	P				
Pr6.05	Range	0~10000	Unit	0.1ms	Default	0				
P10.03	Byte length	16bit	Attribute	R/W	485 address	0x060B				
	Valid	Immediate								
	To set time for	3 rd gain to be va	alid							
	Only available	in position mode	e							
	When not in use, set Pr6.05=0, Pr6.06=100									
	Label	Position 3 rd gai	n scale factor		Valid mode(s)	P				
Pr6.06	Range	50~1000	Unit	100%	Default	100				
P10.00	Byte length	16bit	Attribute	R/W	485 address	0x060D				
	Valid	Immediate								






5.6 Model following control

Model following control is a type of closed loop control system. First, an ideal model is constructed and acts as a reference for actual model in a closed loop control. Model following control can be treated as a control mode with 2 flexibilities: Model reference can be used to improve command responsiveness and closed loop control used to increase responsiveness of the system towards interference. They don't affect each other.

Model following control can be used in position loop control to increase responsiveness to commands, reduce positioning time and following error. This function is only available in position control mode.



To adjust model following control

Automatic adjustment



Set model following bandwidth Pr0.00 = 1 for automatic adjustment. Now, Pr0.00 = Pr1.01, model following bandwidth is adjusted automatically according to different velocity loop gain.

- 3. Manual adjustment
 - Please used manual adjustment if
 - Automatic adjustment is not satisfactory.
 - Responsiveness needs further improvement in comparison with automatic adjustment.
 - There is a need to set servo gain or model following control parameters manually.

Step	s to ma	nually adjust						
	Step	Content						
	1	Set up vibration suppression.						
	2 Set up the right inertia ratio.							
	3	Manually adjust gain.						
	4	4 Increase Pr0.00 provided that there is no overshoot and vibration. Usually						
		Pr0.00 ≥ Pr1.01 is recommended.						

Model following bandwidth determines the responsiveness of the servo system. Increase the value set will increase responsiveness and reduce positioning time. Overshoot can be prevented if it is set at a lower value but responsiveness will be lowered. Model following bandwidth shouldn't be too large for mechanical structure with lower stiffness, excessive position deviation alarm might occur under high velocity.

5.7 Feedforward gain

In position control, velocity feedforward is calculated by comparing the velocity control command calculated internally and velocity command calculated from position feedback. Comparing to control only using feedbacks, this will reduce position deviation and increase responsiveness. Besides, by comparing the torque needed during motion from velocity control command in comparison with velocity feedback, torque feedback can be calculated to improve system responsiveness.

5.7.1 Velocity feedforward

Velocity feedforward can be used in position control mode. When the function is enabled, it can increase velocity responsiveness, reduce position deviation during constant velocity.

	Label	Velocity feed	l forward gain		Valid mode(s)	P				
Pr1.10	Range	0~1000	Unit	0.10%	Default	300				
P11.10	Byte length	16bit	Attribute	R/W	485 address	0x0115				
	Valid	Immediate								
	Used for decreasing following error caused by low responsiveness of velocity loop. Mig									
	cause overshoo	noot or increase in noise if set value is too high.								
	Label	Velocity fee	d forward fi	ilter time	Valid mode(s)	P				
	Label	constant			valia illoac(3)					
Pr1.11	Range	0~6400	Unit	0.01ms	Default	50				
	Byte length	16bit	Attribute	R/W	485 address	0x0117				
	Valid	Immediate								
	Set velocity fee	d forward low	pass filter to	eliminate	high or abnormal	frequencies in v	elocity			
	feed forward o	command. Oft	en used whe	en position	command with I	ow resolution o	or high			
	electronic gear	ration to smo	othen velocity	y feed forw	ard.					
	Position deviat	ion under con	stant velocity	can be lo	wered with higher	velocity feed f	orward			



gain. Please to refer to the equation below.

Reduce Pr1.11 value to suppress velocity overshoot during deceleration; Increase Pr1.11 value to suppress noise or vibration due to long driver control cycle or position command uneven pulse frequency.


<Application>

Set Pr1.11 = 50 (0.5ms), improve feedforward effect by gradually increase Pr1.10. The equation below can be used to determine the position deviation due to velocity feedforward gain under constant velocity.

Position deviation[Uint] =
$$\frac{Set \ velocity[\frac{Uint}{s}]}{Position \ loop \ gain[Hz]} \ x \ \frac{100 - Velocity \ feed \ foward \ gain[\%]}{100}$$

Velocity feedforward application

Set Pr1.11 to around 50 (0.5ms), then tune Pr1.10 from 0 to bigger values until the velocity feedforward achieves better performance. Under constant velocity, the position deviation in a motion will decrease as the velocity feedforward gain increase.



Steps to tuning:

- 1. Increase Pr1.10 to increase responsiveness but velocity overshoot might occur during acc-/deceleration.
- 2. By reducing Pr1.11, velocity feedforward would be more effective and vice versa. Pr1.10 and Pr1.11 need to be tuned to a balance.
- 3. If mechanical noise exists under normal working conditions, please increase Pr1.11 or use position command filter (1 time delay/ FIR smoothing filter)

5.7.2 Torque feedforward

Position control mode: Torque feedforward can increase the responsiveness of torque command, decrease position deviation during constant acc-/deceleration.

Velocity control mode: Torque feedforward can increase the responsiveness of torque command, decrease velocity deviation during constant velocity.

Pr1.12	Label	Torque feed	forward gain		Valid mode(s)	P S
	Range	0~1000	Unit	0.1%	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0x0119
	Valid	Immediate				

Before using torque feed forward, please set correct inertia ratio Pr0.04. By increasing torque feed forward gain, position deviation on constant acceleration/deceleration can be reduced to close to 0. Under ideal condition and trapezoidal speed profile, position deviation of the whole motion can be reduced to close to 0. In reality, perturbation torque will always exist, hence



position	deviation	can nev	er be 0.
----------	-----------	---------	----------

	Label	Torque feed	d forward fi	ilter time	Valid mode(s)	Р	S	
Pr1.13	Range	0~6400	Unit	0.01ms	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x011B		
	Valid	Immediate						

Low pass filter to eliminate abnormal or high frequencies in torque feed forward command. Usually used when encoder has lower resolution or precision.


Noise reduces if torque feed forward filter time constant is set higher but position deviation will increase at acceleration varied points.

<Application>

- Set Pr1.13 = 50ms, please increase torque forward gain gradually to enable torque feedforward.
- By increasing Pr1.13, noise will reduce but position deviation will become larger.

Torque feedforward application

Set Pr1.13 to around 50 (0.5ms), then tune Pr1.10 from 0 to bigger values until torque feedforward achieves better performance. Under constant acc-/deceleration, the position deviation in a motion will decrease as the velocity feedforward gain increase.




Steps to tuning:

- 3. Increase Pr1.12 to increase responsiveness but velocity overshoot might occur during acc-/deceleration.
- 4. By reducing Pr1.13, torque feedforward would be more effective and vice versa. Pr1.12 and Pr1.13 need to be tuned to a balance and reduce noise.



5.8 Friction compensation function

This function is to compensation for changes in load to reduce the effect of friction in motion. The compensation value is directional.



Vertically loaded axis: A constant eccentric load torque is applied on the motor. By adjusting Pr6.07, positioning deviation due to different motional direction can be reduced.

Belt-driven axis: Due to large radial load with dynamic frictional torque. Positioning time delay and deviation can be reduced by adjusting Pr6.08 and Pr6.09.

Pr6.07	Label	Torque comman	d additional	Valid mode(s)	P	S	T	
	Range	-100~100	Unit	%	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x060F		
	Valid	Immediate						

To set torque forward feed additional value of vertical axis.

Applicable for loaded vertical axis, compensate constant torque.

Application: When load move along vertical axis, pick any point from the whole motion and stop the load at that particular point with motor enabled but not rotating. Record output torque value from d04, use that value as torque command additional value (compensation value)

	Label	Positive direction value	n torque con	npensation	Valid mode(s)	P	S	T	
Pr6.08	Range	-100~100	Unit	%	Default	0	0		
	Byte length	16bit	Attribute	R/W	485 address	0x0611			
	Valid	Immediate							
Pr6.09	Label	Negative	direction	torque	Valid mode(s)	Р	S	T	
		compensation value							



Range	-100~100	Unit	%	Default	0
Byte length	16bit	Attribute	R/W	485 address	0x0613
Valid	Immediate				

To reduce the effect of mechanical friction in the movement(s) of the axis. Compensation values can be set according to needs for both rotational directions.

Applications:

1. When motor is at constant speed, d04 will deliver torque values.

Torque value in positive direction = T1;

Torque value in negative direction = T2

$$Pr6.08/Pr6.09 = T_f = \frac{|T1 - T2|}{2}$$

Positive/Negative compensation corresponds to actual position feedback.

Positive torque compensation value = $+(Pr6.08=+T_f)$

Negative torque compensation value = - $(Pr6.08=+T_f)$

Pr6.08 = x, Pr6.09 = y; friction compensation value = |x-y|/2

5.9 Safety Functions

5.9.1 Max. motor rotational speed limitation

Motor rotational speed limits can be set on Pr3.24. If command speed is 1500r/min, but Pr3.24 is set to 1000r/min, motor rotational speed will only go up to 1000r/min.

Motor overspeed threshold value can be set in Pr5.13, if the rotational speed is exceeded during operation, Er1A0 might occur.

Pr3.24	Label	Maximum moto	or rotational sp	Valid mode(s)	P	S	T	
	Range	0~10000	Unit	r/min	Default	0		
F13.24	Byte length	16bit	Attribute	R/W	485 address	0x033	1	
	Valid	Immediate						

To set maximum motor rotational speed but not higher than motor rated speed If Pr3.24 = 0, maximum motor rotational speed = max. speed in motor parameter.

		Label	Overspeed level settings			Valid mode(s)	P	S	T
Pr5.13	Range	0~10000	Unit	r/min	Default	0			
	Pr5.13	Byte length	16bit	Attribute	R/W	485 address	0x051B		
		Valid	Immediate						
		If motor speed exceeds Pr5.13, Er1A0 might occur.							

When Pr5.13 = 0, overspeed level = max. motor speed x 1.2



5.9.2 Max. duration for motor to stop after disabling

Set max time duration for motor to stop after disabling. If the time taken for motor to stop exceeds the duration set in Pr6.14 and motor speed is still higher than Pr4.39, holding brake will be activated. If motor doesn't have holding brake, dynamic braking will be activated to force stop the motor.

	Label	Max. time to sto	p after disabl	ing	Valid mode(s)	P S T	
D=C 14	Range	0~1000	Unit	ms	Default	500	
Pr6.14	Byte length	16bit	Attribute	R/W	485 address	0x061D	
	Valid	Immediate					

To set the max. time allowed for the axis to stop on emergency stop or normal axis disabling. After disabling axis, if motor speed is still higher than Pr4.39 but the time set in Pr6.14 is reached, BRK ON given and holding brake activated.

BRK_ON given time is determined by Pr6.14 or when motor speed goes below Pr4.39, whichever comes first.

Applications:

- 1. After disabling axis, if motor speed is still higher than Pr4.39 but the time set in Pr6.14 is reached, BRK ON given and holding brake activated.
- 2. After disabling axis, if motor speed is already lower than Pr4.39 but the time set in Pr6.14 is not yet reached, BRK_ON given and holding brake activated.

Dynamic brake will be provide the braking function if the function is activated for motors without holding brake.

5.9.3 External brake deactivation output signal BRK-OFF

Please refer to Pr4.11 to set up the I/O output function parameters. When enabled and timing conditions are fulfilled, the set I/O output will deliver ON signal.

		Label	Holding brake	deactivation de	Valid mode(s)	P	S	T	
Pr4.	27	Range	0~3000	Unit	1ms	Default	150		
Pr4	3/	Byte length	16bit	Attribute	R/W	485 address	0x044	В	
		Valid	Immediate						


To set delay time for holding brake to be activated after motor power off to prevent axis from sliding.

When Pr5.06 = 0, SRV-ON signal is off, holding brake is activated (delay time is determined by Pr4.39 or Pr6.14). Motor powered-off once delay time set in Pr4.37 is due.

	Label	Holding brake activation delay time			Valid mode(s)	P	S	T
Pr4.38	Range	0~3000	Unit	1ms	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x044	D	
	Valid	Immediate						

To set delay time for holding brake to be released after motor power on. Motor will remain at current position and input command is masked to allow holding brake to be fully released before motor is set in motion.





^{*1:} Delay time set in Pr4.38

Delay time from the moment SRV_ON is given until BRK_OFF switch to BRK_ON, is less than 500ms.

	Label	Holding brake activation speed			Valid mode(s)	P	S	T
D.4.20	Range	30~3000	Unit	r/min	Default	30		
Pr4.39	Byte length	16bit	Attribute	R/W	485 address	0x044	F	
	Valid	Immediate						

To set the activation speed for which holding brake will be activated.

When SRV-OFF signal is given, motor decelerates, after it reaches below Pr4.39 and Pr6.14 is not yet reached, BRK_OFF is given.

BRK_OFF signal is determined by Pr6.14 or if motor speed goes below Pr4.39, whichever comes first.

Application:

- 1. After disabling axis, Pr6.14 has been reached but motor speed is still above Pr4.39, BRK_OFF signal given.
- 2. After disabling axis, Pr6.14 has not been reached but motor speed is below Pr4.39, BRK_OFF signal given.

Deceleration max duration: 2s. Servo disabled after 2s.

^{*2:} Delay time from the moment BRK_OFF signal is given until actual holding brake is released or BRK_ON signal is given until actual holding brake is activated. It is dependent on the holding brake of the motor.

^{*3:} Deceleration time is determined by Pr6.14 or if motor speed goes below Pr4.39, whichever comes first. BRK_OFF given after deceleration time.

^{*4:} Pr4.37 set time value.



5.9.4 Servo stopping mode

	Label	Servo-off mode			Valid mode(s)	P	S	T	
Pr5.06	Range	0~1	Unit	_	Default	0			
P15.00	Byte length	16bit	Attribute	R/W	485 address	0x050)D		
	Valid	Immediate							
	To set servo d	Iriver disable mo	de and stati	JS.					
	Set value		Exp	lanation					
	0	Driver disables	Driver disables after velocity reaching value set in Pr4.39						
	1	Driver disables immediately, axis in free stopping mode							

5.9.5 Emergency stop function

Emergency stop is used when an alarm occurs or a servo prohibition signal is received when servo driver is enabled.

Method 1: Set up Pr4.43 to enable the function

	Label	Emergency stop	function		Valid mode(s)	P	S	T		
D 4 40	Range	0~1	Unit	_	Default	0				
Pr4.43	Byte length	16bit	Attribute	R/W	485 address	0x04	57			
	Valid	Immediate								
	Value		Description.							
	[0]	Emergency stop occurs.	mergency stop is valid, servo driver will be forced to STOP and Erroccurs.							
	1	Emergency stop be enabled once			will not be forced	to STO	P. Serv	o can		
	Label	Driver prohibitio	n input settii	ngs	Valid mode(s)	Р	S	T		
D.E. 04	Range	0/1/2	Unit	_	Default	0				
Pr5.04	Byte length	16bit	Attribute	R/W	485 address	0x0	509			
	Valid	Immediate								
	To set driver p	rohibition input (P	OT/NOT)							
	Value			Descriptio	n					
	0	POT → Positive (POT → Positive direction drive prohibited							
		NOT → Negative direction drive prohibited								
	1	POT and NOT invalid								
	2	Any single sided	input from P	OT or NOT	might cause Er260	1				

Method 2: Using RS485 address through master device to activate this function.

	Label	Servo braking torque setting			Valid mode(s)	P	S	T	
Pr5.11	Range	0~500	Unit	%	Default	0	0		
PI3.11	Byte length	16bit	Attribute	R/W	485 address	0x051	0x0517		
	Valid	Immediate							
To set torque limit for servo braking mode.									
	If Pr5.11 = 0, use torque limit as under normal situation.								



Please note that if Pr5.11 set value is too low, emergency stop will take longer.




5.10 Vibration Suppression

5.10.1 Mechanical resonance suppression


Mechanical system has certain resonance frequencies. When servo gain is increased, resonance might occur at around mechanical resonant frequencies, preventing gain value from increasing. In such situation, notch filter can be used to suppress resonance to set higher gains or lower vibration.

To suppress mechanical resonance:


- Torque command filter time constant
 Set filter time constant to reduce gain at around resonant frequencies
 Torque command filter blocked frequencies (Hz) fc=1/[2π×Pr1.04(0.01ms)×0.00001)]
- Notch filter
 Notch filter suppress mechanical resonance by reducing gain at certain frequencies. When notch filter is correctly set, resonance can be suppressed and servo gain can be increased.



- Notch filter bandwidth
 Center frequency of the notch filter, frequency bandwidth with reduction of -3dB.
 - Notch filter depth
 The ratio between input and output of center frequency.
 When depth = 0, center frequency output is totally off and when depth = 100,
 Hence when notch filter depth is set at lower value, the depth is higher and better at suppressing mechanical resonance but it might cause system instability.







If the analytic result from mechanical properties analysis tool doesn't show any obvious peak but vibration did occur, it might not be due to mechanical resonance, it may be that servo gain has reached its limit. This kind of vibration can't be suppressed by using notch filter, only by reducing gain and torque command filter time.

To use notch filter

Automatic notch filter

- 1. Set Pr2.00 = 1 for auto notch filter adjustment
- 2. If Pr0.03 stiffness increases, 3rd group of notch filter (Pr2.07/Pr2.08/Pr2.09) updates automatically when driver is enabled. Pr2.00 = 0, auto adjustments stop. If resonance is suppressed, it means self-adjusting notch filter is working. If resonance occurs when mechanical stiffness increases, please use manual notch filter, set filter frequency to actual resonant frequency.

Manual notch filter

There are 2 ways to use manual notch filter.

- 1. After enabling self-adjusting notch filter, set the values from 3^{rd} group of filters to 1^{st} group of notch filter (Pr2.01/Pr2.02/Pr2.03), see if resonance is suppressed. If there is other resonance, set Pr2.00 = 1, then set the values from 3^{rd} group of filters to 2^{nd} group of notch filter (Pr2.04/Pr2.05/Pr2.06)
- 2. Get resonant frequency, notch filter bandwidth and depth and set it into the corresponding parameters through Motion Studio.



	Label		Adaptive filte	ring mode:	settings	Valid mode(s)	P	S
	Range		0~4	Unit	_	Default	0	
Pr2.00	Byte lengt	th	16bit	Attribute	R/W	485 address	0x020	01
	Valid		Immediate					
	-		1	•	•	-	1	
	Value				Descrip	otion		
	0	Ada	aptive filter: inv	alid	unchanged	related to 3 rd		
	1		aptive filter: 1 fi once.	ilter valid	related par	filter becomes variameters updated tomatically to 0 on	accord	lingly. Pr2.00
	2	2 rem		1 filter		filter becomes va meters will keep u		
	3-4	Res	erved		-			
				i i				
	Label	•	1 st notch freq	uency		Valid mode(s)	P	S T
Dr2 01	Label Range		1 st notch freq 50~4000	uency Unit	Hz	Valid mode(s) Default	P 4000	
Pr2.01			1			-		
Pr2.01	Range Byte length Valid		50~4000 16bit Immediate	Unit Attribute	e R/W	Default 485 address	4000	
Pr2.01	Range Byte length Valid Set center for	reque	50~4000 16bit Immediate ency of 1 st torqu	Unit Attribute e comman	e R/W d notch filter	Default 485 address	4000	
Pr2.01	Range Byte length Valid Set center for Set Pr2.01 to	reque	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate	Unit Attribute e comman notch filte	e R/W d notch filter	Default 485 address	4000 0x02	
Pr2.01	Range Byte length Valid Set center for Set Pr2.01 to Label	reque	50~4000 16bit Immediate ency of 1 st torqu to deactivate 1 st notch widt	Unit Attribute e comman notch filte	e R/W d notch filter	Default 485 address Valid mode(s)	4000	
	Range Byte length Valid Set center for Set Pr2.01 to Label Range	reque o 400	50~4000 16bit Immediate ency of 1 st torqu to deactivate 1 st notch widt 0~20	Unit Attribute e comman notch filte th Unit	e R/W d notch filter	Default 485 address Valid mode(s) Default	4000 0x020 P 4	03 S T
	Range Byte length Valid Set center fr Set Pr2.01 to Label Range Byte length	reque o 400	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate 1 st notch widt 0~20 16bit	Unit Attribute e comman notch filte	e R/W d notch filter	Default 485 address Valid mode(s)	4000 0x02	03 S T
	Range Byte length Valid Set center fr Set Pr2.01 to Label Range Byte length Valid	reque o 400	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate 1 st notch widt 0~20 16bit Immediate	Unit Attribute e comman notch filte th Unit Attribute	e R/W d notch filter r R/W	Default 485 address Valid mode(s) Default	4000 0x020 P 4	03 S T
	Range Byte length Valid Set center fr Set Pr2.01 to Label Range Byte length Valid Set notch bar	reque o 400	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate 1 st notch widt 0~20 16bit Immediate Ith for 1 st reson	e comman notch filte th Unit Attribute	e R/W d notch filter r e R/W	Valid mode(s) Default 485 address	P 4000 0x02	03 S T
	Range Byte length Valid Set center from Set Pr2.01 to Label Range Byte length Valid Set notch bar Under normal	reque o 400 ndwic	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate 1 st notch widt 0~20 16bit Immediate th for 1 st reson	Unit Attribute e comman notch filte th Unit Attribute ant notch f ase use face	e R/W d notch filter r e R/W filter. ctory default	Valid mode(s) Default 485 address valid mode(s) Default 485 address	P 4 0x02	S T 05 under control
	Range Byte length Valid Set center for Set Pr2.01 to Label Range Byte length Valid Set notch bard Under normal combination	reque o 400 ndwic al circ with	50~4000 16bit Immediate oncy of 1 st torqu to to deactivate 1 st notch widt 0~20 16bit Immediate Ith for 1 st reson tumstances, ple	Unit Attribute e comman notch filte th Unit Attribute ant notch f ase use face	e R/W d notch filter r e R/W filter. ctory default	Valid mode(s) Default 485 address Valid mode(s) Default 485 address settings. If resonabe reduced to	P 4 0x02	S T 05 under control
Pr2.01 Pr2.02	Range Byte length Valid Set center for Set Pr2.01 to Label Range Byte length Valid Set notch bard Under normal combination	reque o 400 ndwic al circ with	50~4000 16bit Immediate ency of 1 st torqu 0 to deactivate 1 st notch widt 0~20 16bit Immediate th for 1 st reson	Unit Attribute e comman notch filte h Unit Attribute ant notch f ase use face Pr2.03, F er mechan	e R/W d notch filter r e R/W filter. ctory default	Valid mode(s) Default 485 address Valid mode(s) Default 485 address settings. If resonabe reduced to	P 4 0x02	S T 05 under control

Pr2.03	Label	1 st notch depth			Valid mode(s)	P	S	T
	Range	0~99	Unit	1	Default	0		
	Byte length	16bit	Attribute	R/W	485 address	0x0207		
	Valid	Immediate						

Set notch depth for 1st resonant notch filter.

Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.01 and Pr2.02, Pr2.03 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings

Pr2.04	Label	2 nd notch frequency			Valid mode(s)	Р	S	T
	Range	50~4000	Unit	Hz	Default	4000		
F12.04	Byte length	16bit	Attribute	R/W	485 address	0x0209		
	Valid	Immediate						

Set center frequency of 2nd torque command notch filter.

Set Pr2.04 to 4000 to deactivate notch filter

Pr2.05	Label	2 nd notch width			Valid mode(s)	P	S	T
	Range	0~20	Unit	_	Default	4		
P12.03	Byte length	16bit	Attribute	R/W	485 address	0x020B		
	Valid	Immediate						



Set notch bandwidth for 2nd resonant notch filter.

Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.06, Pr2.05 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.

	Pr2.06	Label	2 nd notch depth			Valid mode(s)	P	S	T
		Range	0~99	Unit	_	Default	0		
	P12.00	Byte length	16bit	Attribute	R/W	485 address	0x020D		
		Valid	Immediate						

Set notch depth for 1st resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.

	Label 3 rd notch frequency				Valid mode(s)	P	S	T
Pr2.07	Range	50~4000	Unit	Hz	Default	4000		
Pr2.07	Byte length	16bit	Attribute	R/W	485 address	0x020F		
	Valid	Immediate						

Set center frequency of 3rd torque command notch filter.

Set Pr2.07 to 4000 to deactivate notch filter

	Label	3 rd notch widt	3 rd notch width			P	S	T
Pr2.08	Range	0~20	Unit	1	Default	4		
Pr2.08	Byte length	16bit	Attribute	R/W	485 address	0x0211		
	Valid	Immediate					•	

Set notch depth for 3rd resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.


	Label 3 rd notch depth				Valid mode(s)	P	S	T
Pr2.09	Range 0~99 Unit		Unit	_	Default	0		
P12.09	Byte length	16bit	Attribute	R/W	485 address	0x0213		
	Valid	Immediate						

Set notch depth for 3rd resonant notch filter.

When Pr2.06 value is higher, notch depth becomes shallow, phase lag reduces. Under normal circumstances, please use factory default settings. If resonance is under control, in combination with Pr2.04 and Pr2.05, Pr2.06 can be reduced to improve current loop responsiveness which allows higher mechanical stiffness settings.




5.10.2 End vibration suppression




If the mechanical has an end that is long and heavy, it might cause end vibration at emergency stop and affect the positioning. Usually happens on long armed axis with loose end. The frequency is usually within 100Hz which is lower than mechanical resonant frequencies. It is called low-frequency resonance which can be prevented by applying low frequency suppression function.


To apply low frequency suppression

- 1. Trace current/ position deviation waveform when motion stops.
- 2. Measure the vibration cycle T1 of current waveform.
- 3. Convert T1 into low frequency resonance by F1 = 1/T1
- 4. Write F1 into Pr2.14
- 5. If some other low frequency resonance occurs, please repeat step 1-3 and write F2 into Pr2.16.









	Label	1 st damping frequency			Valid mode(s)	P
Pr2.14	Range	0/10~2000	Unit	0.1Hz	Default	0
P12.14	Byte length	16bit	Attribute	R/W	485 address	0x021D
	Valid	Immediate				

Set Pr2.16 to 0 to deactivate this parameter.

To suppress wobble at load end. Often used when wobble of flexible structure due to high deceleration upon stopping. Especially effective for wobble with frequencies under 100Hz. Set Pr2.15 to wobble frequency (wobble frequency can be determined using tracing function of Motion Studio)

	Label	2 ^{na} damping frequency			Valid mode(s)	P	
Pr2.16	Range	0/10~2000	Unit	0.1Hz	Default	0	l
P12.10	Byte length	16bit	Attribute	R/W	485 address	0x0221	l
	Valid	Immediate					l

Set Pr2.16 to 0 to deactivate this parameter.

To suppress wobble at load end. Often used when wobble of flexible structure due to high deceleration upon stopping. Especially effective for wobble with frequencies under 100Hz. Set Pr2.16 to wobble frequency (wobble frequency can be determined using tracing function of Motion Studio)

5.11 Multiturn absolute encoder

Multiturn absolute encoder records the position and the revolution counts of the motor. When driver is powered-off, multiturn absolute encoder will backed up the data using battery and after powering on, the data will be used to calculated absolute mechanical position and there is no need for a mechanical homing process. Use widely in robotic arms and CNC machines.

If it is the first time using the encoder, please home the mechanical axis and initialize the absolute position of the encoder to zero. Set up a homing point and only home when there is an alarm. Please stop the axis before reading any position data to prevent inaccuracy.

5.11.1 Parameters setting

	Label	Absolute encoder settings			Valid mode(s)	Р	S	T
Pr0.15	Range 0~15 Unit _		Default	0				
	Byte length	16bit	Attribute	R/W	485 address	0x00	1F	




	Valid	After restart					
Value	Mode		Desc	ription			
[0]	Incremental	Doesn't retain position d	ata on po	wer off. Unlimited	l travel distance.		
1	Multiturn absolute linear		Retrain position data on power off. For applications with fixed travel listance and no multiturn data overflow.				
2	Multiturn absolute rotary		Retrain position data on power off. Actual data feedback in between 0- Pr6.63+1). Unlimited travel distance.				
3	Single turn absolute	Used when travel distar overflow will trigger alarr		in 1 revolution o	of the encoder. Data		
5	Multi turn	Clear multiturn alarm a switch to multiturn mode please solve according t	e once ala				
9	absolute	Clear multiturn position, absolute function. Will s remains at 9 after 3s, plaxis before setting to 9 a	witch to n	nultiturn mode or e according to E	nce alarm cleared, if r153. Please disable		

5.11.2 Read absolute position

- 1、Steps:
- 1) First, select a motor with multiturn absolute encoder, install battery and confirm whether the driver version supports the specific motor;
- 2) Set Pr0.15 = 1. If it is the first time of installation, Err153 will occur because battery is newly installed and position data is invalid. Please home the axis and initialize the absolute position of the encoder to zero.
- 3) When absolute homing point is set and there is no fault with the battery, the alarm will be cleared
- 4) Finally, the user can read the absolute position. Position won't be lost even if the driver is powered off.






2. Read absolute position

When the rotor turns in clockwise direction, the revolution count will be negative; turns in counter clockwise direction, the count will be positive. No. of revolutions will be from -32767 to +32767. If the count number reaches +32767 in counter clockwise direction, the count will revert back to -32768, -32767 and vice versa for clockwise direction.

As for position data, it depends on the precision of the encoder. For 17 bit = 0-131071, 23 bit = 0-8388607



3. Clear multiturn position

Before clearing multiturn position, axis needs to be homed. After clearing multiturn position, revolution count = 0 but absolute position remains unchanged and Err153 alarm will be cleared.



Please make sure the homing point is within the range of 1 revolution of the rotor. Installation and setup of the homing point can be set with the use of auxiliary function D21 on the front panel. By setting Pr0.15 to 9, multiturn position will be cleared.

Please take notice of motor position during power on. Range of motion of a motor depends on the position of the motor during power on (23-bit absolute encoder as example).

5.11.3 Absolute Encoder Related Alarm

The alarm can determine if absolute value encoder is valid. If battery power is low, not a motor with absolute encoder, encoder error etc. occurs, user can find out about the error from alarm output or on the front panel. Controller will stop any operation until alarm is cleared.


Alarm output:

Err153 will be shown on front panel or by I/O ALM signal and from controller.

Err153 might occur,

- (1) If absolute encoder is used for the first time and due to installation of new batteries Axis needs to be homed and multiturn data needs to be cleared.
 - (2) If battery voltage is lower than 3.2v. Replace battery and restart the motor.
- (3) If battery voltage is lower than 2.5v or battery power was cut off. Replacing the battery won't clear the alarm. Axis needs to be homed and multiturn data needs to be cleared.

4. Alarm processing flow chart





5.12 Regenerative resistor settings

When motor torque is acting the opposite direction of the rotational direction (i.e. Deceleration, vertical drop axis), energy will flow back into the drive. This will caused the capacitors inside the drive to increase in voltage which might cause over capacity. Regenerative resistor is required here to prevent over capacity of the capacitors.

Regenerative energy can be reduced by reducing rotational inertia, increasing deceleration time, decrease load torque or reduce max. rotational velocity.

	Label	Regenerative	Regenerative resistance			P	S	T
Pr0.16	Range	25~500	Unit	Ohm	Default	100		
F10.16	Byte length	16bit	Attribute	R/W	485 address	0x002	1	
	Valid	Immediate						

To set resistance value of regenerative resistor

Pr0.16 and Pr0.17set value determine alarm threshold of Er120.

If set value > actual regenerative resistance, Er120 occurrence might be delayed.

	Label	Regenerative rating	Regenerative resistor power rating			Р	Ø	Т
Pr0.17	Range	20~5000	Unit	W	Default	50		
	Byte length	16bit	Attribute	R/W	485 address	0x002	23	
	Valid	Immediate						

To set power rating of regenerative resistor. Please refer to table below

Drives	Resistance (Ω)	Power rating(W)
ELD2-RS7005B	10	30
ELD2-RS7010B	10	50
ELD2-RS7015B	10	50
ELD2-RS7020B	10	100
ELD2-RS7030B	10	100/150
ELD2-RS7040B	10	150/200
ELD2-RS7060B	10	150/200

Pr0.16 and Pr0.17 determines the threshold value of Er120. Please set accordingly or it might trigger false alarm or damage to servo drive.

Note: If external regenerative resistor is used, please set according to its labeled power rating.




Chapter 6 Modbus communication

6.1 Communication connection

- RS232 tuning port Connect to PC tuning software (CN7)
- RS485 communication Connect to other drives or master device (CN5)

RS485 network of multiple servo drives

If there is a need to connect multiple ELD2-RS series servo drives together, it is recommended to connect the drivers in series and no longer than 3 meters of CABLE-TX*M*-LD2 cable between each nodes (drivers) as shown below.



- Keep the connection cable between each node as short as possible. Not longer than 3m.
- Install a terminal resistor each end. Recommended resistance: 120 Ohm.
- > Please use shielded twisted pair connection cables.
- > Connect to reference ground of the driver.
- Connect shielded foil of the cables to Protective Earth PE terminal.
- > Please separate them from power cable or any cable with strong interference.



6.2 Modbus RS485 communication parameters and ports

Communication parameters

	Label	RS485 communication mode			Valid mode(s)	P	S	T
Pr5.29	Range	0~255	Unit	_	Default	5		
F13.23	Byte length	16bit	Attribute	R/W	485 address	0x053	3B	
	Valid	After restart						

Value	Bit	Checksum	Stop
0	8	Even	2
1	8	Odd	2
2	8	Even	1
3	8	Odd	1
4	8	Null	1
[5]	8	Null	2

	Label	RS485 communication Baud rate			Valid mode(s)	P S T
D. 5 00	Range	0~15	Unit	Default 4		4
Pr5.30	Byte length	16bit	Attribute	R/W	485 address	0x053D
	Valid	After restart				

Value	Baud rate
0	2400bps
1	4800bps
2	9600bps
3	19200bps

Value	Baud rate
[4]	38400bps
5	57600bps
6	115200bps

Baud rate tolerance: 2400~38400bps±0.5%, 57600~115200bps±2%

		Label	RS485 axis ac	ldress	Valid mode(s)	Р	S	T	
	Pr5.31	Range	0~127	Unit	_	Default	1		
Pre	F13.31	Byte length	16bit	Attribute	R/W	485 address	0x053	3F	
		Valid	After restart						

When controller is connected to multiple axis and controller needs to identify the axis, Pr5.31 can be used to set the axis ID/address.

Please set to a max of 31 if the communication is between RS232 and RS485



Switch SW to modify Baud rate and terminal resistor. Please refer to the table below.

Diagram	Function		Pr6.33	SW4	Baud rate	SW1	SW2	Terminal resistor	SW3
6	Motor direction	CCW (Default)	0	OFF	Pr5.30 Default: 9600	OFF	OFF	Disconnect ed	OFF
	direction	CW		ON	19200	ON	OFF	eu	
1	Modbus	Spin dial	0	OFF	38400	OFF	ON	Connected	ON
1 🛄	high bit address	16+Spin dial	8	ON	57600	ON	ON	Connected	ON

ID spin dial

iii diai	Diagram	Bit	Modbus address	Bit	Modbus address
		0	Pr5.31 Default : 16	8	8
		1	1	9	9
	23 4 5	2	2	Α	10
RCS-1	2 8	3	3	В	11
RCS-2	P C D	4	4	С	12
		5	5	D	13
		6	6	Е	14
		7	7	F	15

Communication Port

To be connected to other drives or master device (controller) – CN5

Port	Diagram	Pin	Signal	Label
		1	RS485+	Modbus Data positive terminal
ONE	10 8 6 4 2	3	RS485-	Modbus Data negative terminal
CN5		5	GND	Power supply ground
		Others	NC	10 pins are not applicable

Note:

- Molex 55959-1030 Connector Header (Driver side)
- Molex 51353-1000 10-pin rectangle connector 1pcs for each axis (Provided)
- Molex 56134-9000 female terminal reel 10pcs for each axis (Provided)



6.3 Modbus Protocol

ELD2-RS series servo drives contain 16-bit including function code 0x03, 0x06 and 0x10.

- 0x03: Read data function code
- 0x06: Write single data function code
- 0x10: Write multiple data function code

6.3.1 Read Data 0x03

Read Data function code 0x03 can be used to read 1-100 16-bit data. For example, from servo drive to slave as 1 and reading 2 data. (H: High 8-bit, L: Low 8-bit)

No.	Request	frame data (Mastei	r->Slave)		Reply frai	me data (Slave->	lave->Master)	
1	ID	Slave	0x01		ID	Slave	0x01	
2	FC	Function code	0x03		FC	Function code	0x03	
3	ADDB	Ctantina adduces	Н		NILIM	Data count	0x00(H)	
4	ADDR	Starting address	L		NUM	(byte)	0x04(L)	
5	NILIM	Data count	0x00(H)		DATA1	Data 1	Н	
6	NUM	(word)	0x02(L)				L	
7	CRC	Checksum	L		DATA2	Data 2	Н	
8	CRC	Checksum	Н		DAIAZ	Data 2	L	
9					CRC	Chaokaum	Ĺ	
10					CKC	Checksum	Н	

Request frame and reply frame should have the same set of data as shown below.

Transmit	01 03 00 04 00 02 85 CA
Receive	01 03 04 00 00 00 02 7B F2

Send Frame: Request Frame. Master device writes a 2-Word (16 bit) data (0x0004) into slave servo drive with ID no. 1. Before frame transmission, 6 byte CRC checksum is 0xCA85

Receive Frame: Reply frame. Master device reads 4 byte (8bit) data from slave servo drive with ID no.1 successfully. Before receiving frame, 7 byte CRC checksum is 0xF27B.

6.3.2 Write single data 0x06

Function code 0x06 is to write single 16-bit data into servo drive. For example, from servo drive to slave station 1 and write 1 data. (H: High 8-bit, L: Low 8-bit).

No.	Request	frame data (Maste	er->Slave)		Reply frame data (Slave->Maste			
1	ID	Slave	0x01		ID	Slave	0x01	
2	FC	Function code	0x06		FC	Function code	0x06	
3	ADDR	Address	Н		ADDR	DR Address	Н	
4	ADDK	Address	L				L	
5	DATA	Data	Data H		DATA	Data	Н	
6	DAIA	Dala	L		DAIA		L	
7	CRC	Charles	L		CRC	Chaalsauna	L	
8	CKC	Checksum	Н		CRC	Checksum	Н	

Communication data is as shown below (Transmit and receive data should be the same):

Transmit	01 06 00 04 00 02 49 CA
Receive	01 06 00 04 00 02 49 CA



Send Frame: Request Frame. Master device writes a 1 Word (16 bit) data (0x0002) into slave servo drive with ID no. 1 (Address 0x0004). 6-byte CRC value is 0xCA49 before frame sending.

Receive Frame: Reply frame. Master device writes data into slave servo drive with ID no. 1 and get same data frame back.

6.3.3 Write multiple data 0x10

Function code 0x10 is to write multiple 16-bit data into servo drive. For example, from servo drive to slave as 1 and reading 2 data. (H: High 8-bit, L: Low 8-bit).

No.	Request	frame data (Maste	er->Slave)	Reply frame data (Slave->Master)			
1	ID	Slave	0x01	ID	Slave	0x01	
2	FC	Function code	0x03	FC	Function code	0x03	
3	ADDR	Starting address	Н	ADDR	Address	Η	
4	ADDK	Starting address	L	ADDIX	Address	L	
5	NUM1	Data count	0x00(H)	NUM	Data count	Η	
6		(word)	0x02(L)	NUW	(word)	L	
7	NUINAO	Data count	0x04	CRC	Ch a alcauma	L	
/	NUM2	(Byte)	(2*NUM1)	CRC	Checksum	Н	
8	DATA1	Data 1	Н				
9	DAIAI	Data 1	L				
10	DATA2	Data 2	Н				
11	DAIAZ	Data 2	Ĺ				
12	CRC	Checksum	Ĺ				
13	CRC	Checksum	Н				

Servo parameters are 32-bit with high 16-bit at the front and low 16-bit at the back. 2 continuous communication addresses will be distributed starting with even number (High 16-bit uses even number address, low 16-bit uses odd number address. Word byte frame word is also with high 8-bit at the front and low 8-bit at the back.

32-bit data written from starting address 0x0000 (Servo driver with axis address 01):

Send	01 10 00 00 00 02 04 01 00 00 00 F3 A0
Receive	01 10 00 04 00 02 00 09

Send Frame: Request Frame. Master device writes a 2 Word (16 bit), 4 bytes data (0x0000 0000) into slave servo drive with ID no. 1 (Address 0x0000). 11-byte CRC value is 0xAFF3 before frame sending.

Receive Frame: Reply frame. Master device writes a 2 Word value into slave servo drive with ID no. 1 (Address 0x0000). 6-byte CRC value is 0xC841 before frame sending.



6.3.4 Reply error

When driver receives request frame data format with error, driver will feedback error reply data frame to master device.

No.	Error reply frame data (Slave->Master)			
1	ID	Slave ID	0~31	
2	FC	Function code	(0x03/0x06/0x10)+0x80	
3	Error code	Address	0x01/0x02/0x03	
4	CRC	Checksum	L	
5	CKC		Н	

Error code table:

Error code	Description
0x01	Function code error
0x02	Address error
0x03	Data error, i.e. written data over limit
0x08	CRC checksum error

Communication data:

Receive frame: Slave servo drive's reply frame. Request frame data CRC from master device, servo drive will not respond to current request.

Receive frame: Slave servo drive's reply frame. Request frame data function from master device error or slave station does not support this function, unable to respond to current request.

6.3.5 Auxiliary function parameters

Auxiliary functions are activated by sending control word.

Done status can be monitored using status word. Status reset to initialization after reading status word.

Control Word:

Registry Address	Label	Operation
0x1801	Control word	Write

Control Word	Auxiliary Function	
0x1111	Reset current alarm	
0x1122	Reset history alarm	
0x2211	Save all parameter to EEPROM	
0x2222	Parameter initialization (not including motor parameters)	



0x2233	Reset all parameters to factory default
0X4001	JOG left (once every 100ms)*
0X4002	JOG right (once every 100ms)*

Note: Continuous JOG motion is only possible if signal is triggered with interval time under 100ms. Step motion if interval time >100ms.

Parameter saving status word:

Registry Address	Label	Operation
0x1901	Status word	Read

Status word	Description
0x5555	Successfully saved
0xAAAA	Failed to save

6.3.6 Alarm info parameters


Registry Address	Label	Operation
0x2203	Current Alarm	Read

Servo Alarm: Addr. 0x2203					
Effective bit[11:0]value(Hex) High 4-bit[15:12] masked	Alarm	Effective bit[11:0]value(Hex) High 4-bit[15:12] masked	Alarm		
0x000	Normal	0x190	Excessive motor vibration		
0x0E1/ 0x0E0	Overcurrent	0x150	Encoder disconnected		
0x100	Overload	0x151/0x170	Encoder data error		
0x180	Excessive position deviation	0x152	Encoder HALL signal error		
0x1A0	Overspeed	0x240	Parameter saving error		
0x1A1	Motor out of control	0x570	Emergency stop		
0x0D0	Undervoltage	0x120	Regenerative energy overload		
0x0C0	Overvoltage	0x153	Encoder battery error		
0x171/0x172	Encoder parameter error	0x210/0x211/0x212	Input configuration error (Repeated/wrong input)		
Others	Please refer to Chap. 9				



6.4 Frequently occurred issues and solutions with RS485 communication.


Terminal resistor



Terminal resistor is to be connected at the start and end of the device network. Recommended resistance of the terminal resistor: 120 Ohm. Measure the resistance within the network using a multimeter and refer to the table below.

Measured resistance (Ohm) Normal: 60 Ohm	Description
0	Short circuit
Much lower than 60	Might be other resistor within the network; incorrect terminal resistor is used
Much higher than 60	Might be due to damaged/faulty node communication port


Incorrect wiring connection




Please make sure RS485 communication connection is normal using a multimeter. Then, make sure the reference ground is corrected connected. If there is not no reference ground, please leave it unconnected. Same goes for cable shield foil.



Signal interference



External interference: Magnetic ring can be intertwined within cable 1 and 2 to prevent external interference.



Driver interference: If interference occurs within the driver, please intertwine magnetic rings on cable 1 and 2. Please loop UVW cables around the magnetic ring for at least 3 rounds. Do not loop PE wire into the magnetic ring.



Step-by-step problem solving

- 1: Verify if communication parameters setting are correct (ID not repeated, uniform Baud rate and data format);
- 2: If terminal resistor used is correct;
- 3: If wiring connection is correct;
- 4: Verify grounding and PE connection;
- 5: Communication cables should be separated from power cables.


Servo drives are devices of good anti-interference. However, during installation, interference still might occur due to wiring and grounding issues. Please refer to the table below if such problems persist.

Steps	Solutions			
1	Use shielded wire cable for I/O signals, connect shield foil to PE.			
2	Connect motor PE to PE terminals on drivers, connect driver PE to PE			
	terminals of electrical network.			
3	Ground master device and servo drives together.			
4	Loop UVW motor power cable around magnetic ring for 2-3 times.			
5	Loop signal cable around magnetic ring for 1-2 times.			
6	Use shielded cable for power cables. Connect shield foil to ground.			
7	Connect a capacitance filter onto DI input. Max capacitance: 0.1 µF			
	COM+ 0.01 µ F Driver			



Chapter 7 PR mode

PR function is a control module in servo drive that controls single axis motion using PRocedure program. Main single axis motion control functions included homing, path, position limit and emergency stop. Using PR functions can save the resources on the main controller.



Please set Pr0.01 = 6 when using PR functions. All position unit: 10000 Pulse/r



7.1 PR functions introduction

Function	Description
Homing	Driver seeks origin signal through homing to determine zero point of the mechanical motion coordination system 1. Homing mode configurable. Can be chosen between position limit signal homing, origin signal homing and manually set home; 2. Homing direction configurable; 3. Specific position can be set after homing completed; 4. Homing velocity, acceleration and deceleration configurable. 5. High homing velocity to locate origin and low homing velocity to look for Z-signal
JOG	Forward/Reverse JOG through I/O control. Used for tuning. 1. JOG direction: forward JOG, reverse JOG 2. JOG velocity and acceleration configurable
Position limit	Prevent mechanical damage by limiting the range of motion 1. Positive/Negative position limit input through I/O 2. Software position limit 3. Position limit deceleration configurable
Emergency stop	Emergency stop input signal through I/O. To stop any operating motion
Path motion	Select path ID through IO (ADD0-3), then trigger path motion through enable IO (CTRG); or directly through I/O combination mode; path motion can be controlled directly through 485 communication as well 1. Path motion includes positioning, velocity and homing modes. 2. I/O trigger includes rising edge, double edges trigger 3. Supports continuous positioning; 4. Max. 16 paths; 5. Configurable position, velocity and acceleration/deceleration; 6. Pause time/ timer configurable
485 communication	PR parameter R/W through 485 communication. Control PR functions such as homing, JOG, path motion, emergency stop, etc.



7.2 Control parameters

All PR motion related parameters including trigger, status output, limits, emergency stop, JOG, homing, etc.

Param eter	Label	Description	485 Addr.
Pr8.00	PR Control	PR control functions Bit 0: =0, CTRG rising edge trigger =1, double edges trigger; Bit 1: =1, software position limit valid, =0, software position limit not valid; Bit 2: =1, homing upon power on, =0, no homing upon power on Bit 3: =1, absolute value memory, =0, absolute value with no memory,	0X6000
Pr8.01	Path count	16 paths	0X6001
Pr8.02	Control Operation		0X6002
Pr8.06	Software positive limit H	High 16-bit of software positive limit	0X6006
Pr8.07	Software positive limit L	Software positive limit (Only able to read low 16-bit using 485 communication)	0X6007
Pr8.08	Software negative limit H	High 16-bit of software negative limit	0X6008
Pr8.09	Software negative limit L	Software negative limit (Only able to read low 16-bit using 485 communication)	0X6009
Pr8.10	Homing mode	Homing method in PR mode Bit 0: Homing direction =0: Reverse; =1: Forward Bit 1: Specific position after homing =0: No; =1: Yes Bit2~7: Homing mode =0: Position limit homing =1: Origin homing =2: Single turn Z homing =3: Torque homing =8: Immediate homing Bit 8: =1: Homing with Z-signal = 0: Homing without Z-signal Single turn Z homing is homing method within 1 revolution, has nothing to do with Bit 8 Z-signal.	0X600A
Pr8.11	Zero position H	High 16-bit of zero position	0X600B
Pr8.12	Zero position L	Zero position (Only able to read low 16-bit using 485 communication)	0X600C
Pr8.13	Home position offset H	High 16-bit of home position offset	0X600D
Pr8.14	Home position offset L	Home position offset (Only able to read low 16-bit using 485 communication)	0X600E



Pr8.15	High homing velocity	Set high homing velocity	0X600F
Pr8.16	Low homing velocity	Set low homing velocity	0X6010
Pr8.17	Homing acceleration	Set homing velocity Set homing acceleration	0X6011
Pr8.18	Homing deceleration	Set homing deceleration	0X6012
Pr8.19	Homing torque holding time	Set homing torque holding time	0X6013
Pr8.20	Homing torque	Set homing torque value	0X6014
Pr8.21	Homing overtravel alarm range	Set homing overtravel alarm threshold, set to 0 to deactivate the alarm	0X6015
Pr8.22	Emergency stop at limit deceleration	Set position limit emergency stop deceleration	0X6016
Pr8.23	STP emergency stop deceleration	Set STP emergency stop deceleration	0X6017
Pr8.26	I/O combination trigger mode	O: Disable I/O combination trigger mode. Uses I/O CTRG signal edge trigger. 1: Enable I/O combination trigger. Valid when HOME-OK signal is valid. 2: Enable I/O combination trigger. HOME-OK signal not required.	0X601A
Pr8.27	I/O combination filter	Set I/O combination filter time	0X601B
Pr8.28	S-code current output value	Display S-code output	0X601C
Pr8.29	PR warning	=0: Reset new command automatically; =0x100; Position limit error during homing =0x101; Emergency stop. Homing not completed; =0x20x; Position limit error on Path <i>N</i>	0X601D
Pr8.39	JOG velocity	Set JOG velocity	0X6027
Pr8.40	JOG acceleration	Set JOG acceleration	0X6028
Pr8.41	JOG deceleration	Set JOG deceleration	0X6029
Pr8.42	Command position H	High 16- bit of command position	0X602A
Pr8.43	Command position L	Command position (Only able to read low 16-bit using 485 communication)	0X602B
Pr8.44	Motor position H	High 16- bit of motor position	0X602C
Pr8.45	Motor position L	Motor position (Only able to read low 16-bit using 485 communication)	0X602D
Pr8.46	Input	Input status	0X602E
Pr8.47	Output	Output status	0X602F
Pr8.48 - Pr8.63	S-code setting	Path NS-code output settings	0x6030 ~ 0x603F




7.3 PR Motion

7.3.1 Homing

Homing is divided into 5 methods according to home signal: Single turn Z-phase homing, position limit homing, origin homing, torque homing, manually set home. Position limit homing, origin homing and torque homing can be with or without Z-signal. Homing can be triggered upon power on or using I/O after servo enabled.

Homing sequence diagram



- HOME: Homing trigger signal. When HOME is valid, homing will be done according to set homing method.
- 2. **CMD_OK**: Command completed signal. Invalid when command is being carried out, valid when command is done.


3. Please refer to Pr8.10 to set homing methods and other homing mode related settings. It is recommended to use Motion Studio to modify the control parameters in PR mode.

	Label	Homing mode			Valid mode(s)	PR
Pr8.10	Range	0~ 0xFFFF	Unit	/	Default	0
	Byte length	16bit	Attribute	R/W	485 address	0X600A
To set homing method in PR using Motion Studio.			node. It is red	commended	to modify PR cor	ntrol parameters
	Bit	8 (Z-signal	2-7 (Hor	ming	1 (Specific	0 (Homing
		homing) mode)			position after	direction)
					homing)	
	Description =1, homing with =0 Limit homing		noming	=1, Yes	=1, Forward	
	Z		=1 Origin	homing	=0, No	=0, Reverse
	=0, homing		=2 Single	turn Z		
		without Z-signa	al homing			
			=3 Torqu	e homing		
			=8 Immediate			
			homing			




Position limit, origin and torque homing with Z-signal


1. Negative limit homing



2. Positive limit homing




3. Origin homing – Negative direction







4. Origin homing – Positive direction



5. Torque homing – Negative direction




6. Torque homing – Positive direction






Position limit, origin, torque and manual set home (Homing with single condition)






4. Origin homing – Positive direction




5. Torque homing – Negative direction






7.3.2 Position limit and emergency stop

For safety concerns, PR mode is designed to trigger emergency stop when position limit or emergency stop signal is valid. Please refer to the sequence diagram below.



7.3.3 JOG

JOG is used to make tuning more convenient. Please refer to the sequence diagram below for motion profile during JOG





7.3.4 Path motion

Path motion: Segmented, continuous, interrupted. Path positioning: Position, velocity, homing.

PR path is to a total of 16 paths. Every path can be set with motion type, positioning mode, velocity, acceleration, deceleration and pause time independently.


Parameter	Label	Description	485 addr.
Pr9.00	PR mode	Attribute of PR path is determined by its mode. Bit 0-3: type: 0: null 1: Positioning 2: Velocity 3: Homing 4: Emergency stop Indicates using P/V/H/S Bit 4: 0: Can be Interrupted 1: Can't be Interrupted, indicates using! Bit 5: OVLP: 0: No overlap, indicates with SJ 1: Overlap, indicated with CJ Bit 6-7: 0: absolute 1: relative command 2: relative motor Corresponding to ABS/INC/REL Bit8-13: 0-15: Jump to corresponding path Indicates using SJ0x or CJ0x Bit 14: JUMP: 0: No Jump, indicates with END 1: Jump. Jump to SJ or CJ	0X6200
Pr9.01	PR position H	High 16-bit of PR path position	0X6201
Pr9.02	PR position L	PR position (Only able to read low 16-bit using 485 communication)	0X6202
Pr9.03	Velocity	Velocity, rpm	0X6203
Pr9.04	Acceleration time	Unit ms/1000rpm	0X6204
Pr9.05	Deceleration time	Unit ms/1000rpm	0X6205
Pr9.06	Pause time	Pause time after command completed	0X6206
Pr9.07	Special parameter	Mapped to Pr8.02	0X6207
Pr9.08 ~ Pr9.127		8 parameters for each path. Please refer to Class 9 parameter in Chapter 3	



Path motion


Segmented trigger

CTRG rising edge/double edges trigger (Pr8.00) a segmented motion. Please refer to the sequence diagram below with rising edge trigger of path 5.



Multi-path interrupted motion


In multi-path motion, path motion that is triggered later will interrupt path motion that has already started. Please refer to the sequence diagram below






Non-overlap continuous motion

Path motion continues by another, no trigger needed for the next one to start.



Overlapping continuous motion

Path motion starts immediate after the previous path motion is completed without deceleration or trigger in between.






7.4 PR Control

7.4.1 PR module in Motion Studio

Using Pr-Motion function in Motion Studio, PR parameters can be set including trigger settings, software position limit, JOG, homing, emergency stop, etc. Manual triggering of homing, path motion or emergency stop can also be triggered on this interface.




Most of PR control related parameters can be set on this page.






All class 9 parameters for 0-15 paths can be found here once connected to a servo drive that supports PR mode.




Manual control of servo drive in PR mode can be done in this page.



All PR mode and control parameters can be found on this list for convenience of tuning





7.4.2 Physical I/0

Path motion, feedback status, etc can be triggered through I/O in PR mode. Please refer to the table below for I/O assignments in PR mode.


Inpu	t		Output				
Label	Signal	Value		Label	Signal	Va	lue
		NO NC				NO	NC
Command trigger	CTRG	20h	A0h	Command completed	CMD_OK	20h	A0h
Homing	HOME	21h	A1h	Path completed	PR_OK	21h	A1h
Forced emergency stop	STP	22h	A2h	Homing completed	HOME_OK	22h	A2h
Positive JOG	PJOG	23h	A3h	S-code 0	SD0	23h	A3h
Negative JOG	NJOG	24h	A4h	S-code 1	SD1	24h	A4h
Positive position limit	PL	25h	A5h	S-code 2	SD2	25h	A5h
Negative position limit	NL	26h	A6h	S-code 3	SD3	26h	A6h
Origin	ORG	27h	A7h	S-code 4	SD4	27h	A7h
Path address 0	ADD0	28h	A8h	S-code 5	SD5	28h	A8h
Path address 1	ADD1	29h	A9h	S-code 6	SD6	29h	A9h
Path address 2	ADD2	2ah	Aah	PR warning	PRWAR	2Ah	AAh
Path address 3	ADD3	2bh	Abh	_			
Torque switching	TC-SEL	09h	89h				

S-code

S-code (Status code) is the S-code of currently operating PR positioning data. Every PR path has a S-code setting.

S-code	Sx.H	Sx.L			
Bit	15	8-14	7	0-6	
Description	S-code valid when completed. 0: Invalid, retain previous value 1: Valid	S-code upon completion	S-code valid upon activation 0: Invalid 1: Valid	S-code upon activation	






Valid when S1 enabled and S2 completed

S-code bit	bit0/8	bit1/9	bit2/10	bit3/11	bit4/12	bit5/13	Bit6/14
SDx	SD0	SD1	SD2	SD3	SD4	SD5	SD6

I/O trigger

Path motion trigger: Edge trigger/combination trigger(Pr8.26). Edge trigger is triggering path combination motion using I/O. I/O combination trigger uses electrical level as trigger rather than signal edge. No valid motion for path 0 and I/O combination triggers motion once after I/O filter when converted to non-zero paths.



^{**}Path combination 0 is invalid because I/O combination x>0->x can be triggered for multiple times when using incremental position.

^{*}In I/O combination trigger mode 2, path motion will be triggered upon servo drive power on if I/O combination not set to 0. Please be careful.

	Label		I/O combination	n trigger mod	е	Valid mode(s)	PR			
Pr8.26	Range		0 ~ 65535	Unit	/	Default	0			
	Byte len	gth	16bit	Attribute	R/W	485 address	0X601A			
	Value	Desc	Description							
	[0]	Disal	Disable I/O combination trigger mode. Uses I/O CTRG signal edge trigger.							
	1	Enab	Enable I/O combination trigger. Valid when HOME-OK signal is valid.							
	2	Enab	nable I/O combination trigger. HOME-OK signal not required.							
	IO comb	inatio	n trigger select p	ath using AD	D0~ADD	3. Trigger mode is s	set in Pr8.26.			



ADD3	ADD2	ADD1	ADD0	Path selection
OFF	OFF	OFF	OFF	Path 0 (Non-action)
OFF	OFF	OFF	ON	Path1
OFF	OFF	ON	OFF	Path2
OFF	OFF	ON	ON	Path3
OFF	ON	OFF	OFF	Path4
OFF	ON	OFF	ON	Path5
OFF	ON	ON	OFF	Path6
OFF	ON	ON	ON	Path7
ON	OFF	OFF	OFF	Path8
ON	OFF	OFF	ON	Path9
ON	OFF	ON	OFF	Path10
ON	OFF	ON	ON	Path11
ON	ON	OFF	OFF	Path12
ON	ON	OFF	ON	Path13
ON	ON	ON	OFF	Path14
ON	ON	ON	ON	Path15

7.4.3 485 communication

485 communication can be used to achieve the same functions as with I/O, modifying PR related parameters and trigger path motions. Through this communication protocol, controlling of multiple axes can be realized, saving wiring works with flexibility in the system. 485 communication includes 2 kinds of mode: Fixed trigger and immediate trigger.

485 communication parameters

Parameter	Label		Description						
Pr5.29	Communication	485 com	485 communication mode data						
	mode	Valu	ıe	Bit		Checksum		Stop	
		0	8	}		Ev	en	2	
		1	8	3		Oc	ld	2	
		2	8	3		Εv	en	1	
		3	3 8			Oc	ld	1	
		4	8	3		Nι	ıll	1	
		【5】	8	}	Null		ıll	2	
Pr5.30	Baud rate	To set c	ommuni	cation	spee	d o	f RS485 com	munication	
		Value	Baud ra	aud rate Valu		Value Baud rate			
		0	2400bp	00bps [4]			38400bps		
		1	4800bp	s t	5 57600b		57600bps		
		2	9600bp	s (6 115200bps		115200bps		
		3	19200b	•					
Pr5.31	ID	Modbus	slave IE) addre	ess				
Pr8.02	PR trigger	Attribute	Index	(Descr	ipti	on		
		Write	Write 0x01P		N pat	h p	ositioning		
		Write	0x020		Reset				
		Write	0x02	1	Manu	ıally	set currently p	oosition as 0 (C)rigin



Write	0x040	Emergency stop
Read	0x000P	Positioning completed. Ready to receive new data
Read	0x01P,	
	0x020,	Yet to respond to command
	0x040	
Read	0x10P	Path motion undergoing
Read	0x200	Command completed. Waiting for positioning

PR mode communication address:

Class 8 parameters: 0x6000+(Param-ID-800). For example Pr8.06: 0x6000+(806-800)=0x6006 Class 9 parameters: 0x6200+(Param-ID-900). For example Pr9.06: 0x6200+(906-900)=0x6206



7.4.4 Path trigger

Fixed trigger

Fixed triggering method is to set all 16 paths homing and other settings, then through Pr8.02 (trigger register to replace CTRG and HOME) to enable path. Recommended for simple applications with fixed motions.

Steps:

- 1. Set homing and path attributes using Motion Studio. Power on driver for parameters to be valid.
- 2. Write corresponding command into 0x6002(Pr8.02) to realize required motions.

Attribute	Index	Description
Write	0x01P	N path positioning
Write	0x020	Reset
Write	0x021	Manually set currently position as 0 (Origin)
Write	0x040	Emergency stop
Read	0x000P	Positioning completed. Ready to receive new data
Read	0x01P,	
	0x020,	Yet to respond to command
	0x040	
Read	0x10P	Path motion undergoing
Read	0x200	Command completed. Waiting for positioning

Immediate trigger

Immediate trigger is more flexible while fixed triggering is restricted by 16 paths position. Path motion is triggered immediately once path is written. Motions such as position, velocity or homing are realized through data frame.

This triggering method uses PR0 with 8 datum from which Pr9.07 mapped into Pr8.02. When 0x10 is written into Pr8.02, it will trigger PR0 motion immediately.

Steps:

- 1. Set homing and path attributes using Motion Studio. (Homing parameters must be set) Power on driver for parameters to be valid.
- 2. Control specific path using Pr8.02.
- 3. Realize path motion by writing into Pr9.00 Pr9.07 with Pr9.07 = 0x10

Master device request frame byte data

No.	Data	Description	Value
1	ID	Slave ID	1~127
2	FC	Function code	0x10
3	ADDR	Address	0x62
4	ADDR	Address	0x00
5~6	NUM1	Data count (Word)	0x0008
7	NUM2	Data count (BytE)	0x10
8-9	Pr9.00	Mode	XXXX



10-11	Pr9.01	Position high bit	XXXX
12-13	Pr9.02	Position low bit	XXXX
14-15	Pr9.03	Velocity	XXXX
16-17	Pr9.04	Acceleration	XXXX
18-19	Pr9.05	Deceleration	XXXX
20-21	Pr9.06	Delay time	XXXX
22-23	Pr9.07	Trigger control	0x0010
24	CRC	Checksum Lo	
25		Checksum Hi	

Slave response frame byte data

No.	Data	Description	Value
1	ID	Slave ID	1~127
2	FC	Function code	0x10
3	ADDR	Address	0x62
4	ADDR	Address	0x00
5	NUM	Data count (Word)	0x08
6	CRC	Checksum Lo	0xXX
7		Checksum Hi	0xXX

7.5 PR motion

7.5.1 Trigger using physical I/O

- 1. Set up servo drive parameter such as Pr0.01 = 6. Required PR I/Os are set in Pr4.00-Pr4.15
- 2. Set up PR control parameters such as trigger, homing, emergency stop, velocity, etc as shown below
- 3. Set PR path parameter such as motion type, S-code, etc as shown below. The interface is divided into 3 parts:

Function buttons: Upload, download parameters to/from drives, save parameter, backup and reset to factory default.

Parameters: Set PR path related parameters here

Descriptions: Short explanation on each PR path motion types

Remember to upload parameters to drive and save to drive after parameters setup.

- 4. Set up homing, trigger, I/O in PR mode as shown below:
- **Please select required path when using edge trigger. Make sure the corresponding path is chosen in I/O path selection
- *Please set up I/O combination filter time when using I/O combination trigger. Make sure I/O signal filter time covers the change in signal level.



7.5.2 Control using 485 communication

485 communication data frame format

Byte(x)	0	1	2	3	4	5	6	7
Definition	ID	Function	Addr.	Addr.	Data	Data	CRC	CRC
		code	High	Low	High	Low	checksum	checksum
			8-bit	8-bit	8-bit	8-bit	Low 8-bit	High 8-bit

Please refer to Modbus communication in Chapter 6 to use Word function code writing. The request and respond frame data format is similar.

1. Set PR0 to travel to absolute position = 200000 (10000 pulse/rev)

No.	485 communication data frame	frame Description			
1	01 06 62 00 00 01 57 B2	Set PR0 mode as absolute position			
2	01 06 62 01 00 03 87 B3	Set PR0 position high bit			
3	01 06 62 02 0D 40 32 D2	Set PR0 position low bit			
4	01 06 62 03 02 58 66 E8	Set PR0 velocity			
5	01 06 62 04 00 32 56 66	Set PR0 acceleration			
6	01 06 62 05 00 32 07 A6	Set PR0 deceleration			
7	01 06 60 02 00 10 37 C6	Trigger PR0 motion			
8	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required			

2. Set PR0 to travel relative distance = 10000 (10000 pulse/rev)

No.	485 communication data frame	Description
1	01 06 62 00 00 41 56 42	Set PR0 mode as relative position
2	01 06 62 01 00 00 C7 B2	Set PR0 position high bit
3	01 06 62 02 27 10 2D 8E	Set PR0 position low bit
4	01 06 62 03 02 58 66 E8	Set PR0 velocity
5	01 06 62 04 00 32 56 66	Set PR0 acceleration
6	01 06 62 05 00 32 07 A6	Set PR0 deceleration
7	01 06 60 02 00 10 37 C6	Trigger PR0 motion
8	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required

3. Set PR0 as velocity mode with velocity = 600rpm

No.	485 communication data frame Description			
1	01 06 62 00 00 02 17 B3	Set PR0 as velocity mode		
2	01 06 62 03 02 58 66 E8	Set PR0 velocity		
3	01 06 62 04 00 32 56 66	Set PR0 acceleration		
4	01 06 62 05 00 32 07 A6	Set PR0 deceleration		
5	01 06 60 02 00 10 37 C6	Trigger PR0 motion		
6	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required		



4. Set PR1 to travel to absolute position = 200000 (10000 pulse/rev)

	221 to mare to discount position 200000 (10000 pare)				
No.	485 communication data frame	Description			
1	01 06 62 08 00 01 D6 70	Set PR1 mode			
2	01 06 62 09 FF FC 07 C1	Set PR1 position high bit			
3	01 06 62 0A F2 C0 F3 40	Set PR1 position low bit			
4	01 06 62 0B 02 58 E7 2A	Set PR1 velocity			
5	01 06 62 0C 00 32 D7 A4	Set PR1 acceleration			
6	01 06 62 0D 00 32 86 64	Set PR1 deceleration			
7	01 06 60 02 00 11 F6 06	Trigger PR1 motion			
8	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required			

5. Set PR1 as velocity mode with velocity = 300rpm

No.	485 communication data frame	Description
1	01 06 62 08 00 02 96 71	Set PR1 as velocity mode
2	01 06 62 0B 01 2C E7 FD	Set PR1 velocity
3	01 06 60 02 00 11 F6 06	Set PR1 acceleration
4	01 06 62 0C 00 32 D7 A4	Set PR1 deceleration
5	01 06 62 0D 00 32 86 64	Trigger PR1 motion
6	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required

6. Homing

No.	485 communication data frame	ame Description		
1	01 06 60 0A 00 00 B7 C8	Set homing method		
2	01 06 60 0F 00 64 A6 22	Set high homing velocity		
3	01 06 60 10 00 1E 16 07	Set low homing velocity		
4	01 06 60 02 00 20 37 D2	Trigger homing		
5	01 06 60 02 00 40 37 FA	Send Emergency stop datagram when required		



Chapter 8 Warning and Alarm

8.1 Servo Drive alarm indicator


Green LED: Power ON/Motor enable

ON for once: Power ON Always ON: Motor Enable Blinking: Motor Disable OFF: Power OFF

Red LED: Alarm indicator (Motor stops when alarm indicator is ON)

Blink for 5s/cycle (Please refer to the table below)

OFF: Alarm cleared



S: Short, L: Long. 1S4L represents 1 short blink and 4 long blinks



8.2 Servo drive alarm

Table 8.1 Error Code List

Error code		Ocardon d		Attribu	te
Main	Sub	Content	Save	E.Stop	Clearable
09	0~F	FPGA communication error	•		
	0~1	Circuit current detection error	•		
	2,4	Analog input error	•		
0A	3	Motor power cable not connected			
0, 1	5	DC bus error			
	6	Temperature measuring error	•		
	0	Control circuit power supply voltage too low	•		
0b					_
0	1	Control circuit power supply voltage too high			•
0c	0	DC bus overvoltage	•		-
0d	0	DC bus undervoltage	•		•
	0	Overcurrent	•		
0E	1	Intelligent Power Module (IPM) overcurrent	•		
0_	2	Power output to motor shorted to ground	•		
	4	Phase overcurrent	•		
0F	0	Driver overheated	•	•	
	0	Motor overloaded	•		•
10	1	Driver overloaded			•
	2	Motor rotor blocked	•		•
	0	Regenerative resistor overvoltage	•	•	
12	1	Holding brake error	•		
	2	Regenerative resistor value too low	•		
	0	Encoder disconnected	•		
	1	Encoder communication error	•		
	2	Encoder initial position error	•		
15	3	Multiturn encoder error	•		
13	4	Encoder parameter settings error	•		
	5	Encoder data overflow	•		•
	6	Encoder overheated	•		•
	7	Encoder counter error	•		•
17	0	Encoder data error	•	•	
	1	Encoder parameter initialization error	•		
18	0	Excessive position deviation	•	•	•
	1	Excessive velocity deviation	•	•	•
19	0	Motor vibration too strong		•	•
	1	Excessive hybrid position deviation	•		•
1A	0	Overspeed Velocity out of control	•		•
	0	Bus input signal dithering	•		•
1b	1	Incorrect electronic gear ratio	•		•
ID	4	Excessive synchronous position command	•		•
21	0	I/O input interface assignment error	•		•
21 0 I/O input interface assignment error		•			



	I/O input interface function assignment error				
	2	I/O output interface function assignment			
	2	error	•		
24	0	CRC correction during EEPROM parameter			
27	U	saving			
26	0	Positive/Negative position limit triggered			•
20	U	under non-homing mode	•	• • •	
27	0	Analog 1 input overrun limit	•		•
	0	Control mode not match under full closed			
29		loop mode	•		
29	1	Encoder mode not match under full closed			
		loop mode	•		
57	0	0 Forced alarm input valid(E-stop)		•	•
5F	0	Motor model no. detection error			
3F	1	Driver power module detection error			
60	0	Main loop interrupted timeout			
60	1	Velocity loop interrupted timeout			
70	0	Encryption error			
88	0	Communication timeout		•	
89	0	Homing error			•

8.3 Alarm Handling

**When error occurs, please solve accordingly. Then, restart. If the solutions described don't work, please consider replacing the driver.

Error	Main	Sub	Display: "Er 090""Er 09F"		
code	09	0~F	Content: FPGA communication error		
Cause			Diagnosis	Solution	
DC-,DC+ terminal voltage		l voltage	Verify DC-,DC+ terminal Make sure DC-,DC+ terminal voltage		
too low	1 '		voltage	is within recommended range	

Error Main Sub Display: "Er 0A0""Er 0A1"				
code	0A 0~1 Content: Circuit current detection error			
Cause	Cause		Diagnosis Solution	
Motor power cable wiring error		e wiring	Verify motor power cable Make sure U,V,W terminal wirk wiring properly	
Main power supply undervoltage		ly	Verify DC-,DC+ terminal voltage	Increase main power supply voltage

Error	Main	Sub	Display: "Er 0A2" / "Er 0A4" Content: Analog input error		
code	0A	2/4			
Cause			Diagnosis	Solution	
Analog input wiring error		ng error	Verify analog input wiring Make sure of analog input wiring connection		



Error code Main Sub Display: "Er 0A3" OA 3 Content: Motor power cable not connect		Display: "Er 0A3"			
		ot connected			
Cause			Diagnosis Solution		
Motor po	ower cabl ed	le not	Verify motor power cable wiring	Measure resistance values between U, V, W terminals, make sure the values are almost equal. If not, might be due to damaged motor or motor winding open circuit.	
Motor fault			1	Replace motor	

Error	Main	Sub	Display: "Er 0A5"			
code	0A	5	Content: DC Bus error			
Cause			Diagnosis	Solution		
DC-,DC+ terminal voltage too low			Verify DC-,DC+ terminal voltage. Check if power on indicator light on servo drive is on and d27 DC bus voltage.	Make sure DC-,DC+ terminal voltage is within recommended range		

Error	Main	Sub	Display: "Er 0A6"		
code	0A	6	Content: Temperature measuring error		
Cause			Diagnosis	Solution	
DC-,DC+ terminal voltage too low			Verify DC-,DC+ terminal Make sure DC-,DC+ terminal voltage is within recommended range		

Error	Main	Sub	Display: "Er 0c0"				
code	0c	0	Content: DC bus overvoltage				
Cause			Diagnosis	Solution			
Main power supply overvoltage			Verify DC-,DC+ terminal voltage	Decrease main power supply voltage			
Acceleration/deceleration time too short			Verify if the time is actually too short	Increase the duration time or change to a regenerative resistor with higher resistance.			
Regenerative brake parameter anomaly			Verify Pr7.32/Pr7.33	Modify vent overload parameter			
Inner br	ake circ	uit damaged	/ Replace driver				

Error	Main	Sub	Display: "Er 0d0"				
code	0d	0	Content: DC bus undervoltage				
Cause			Diagnosis	Solution			
Main power supply undervoltage		ly	Verify DC-,DC+ terminal voltage	ge Increase main power su voltage		supply	



Error	Main	Sub	Display: "Er 0E0"	
code	0E	0	Content: Overcurrent	
Cause			Diagnosis	Solution
Driver power output short circuit			Verify if there is short circuit between UVW terminals, or shorted to PG.	Make sure there is no circuit. Make sure motor is not damaged
Motor w	iring erro	r	Verify motor wiring	Reconnect motor wiring
IGBT module short circuit			Disconnect motor output cable. Then, enable servo driver to check for overcurrent	Replace driver
Control parameter anomaly		r	Verify if parameter exceeds recommended range	Set parameter within recommended range.
Control	command /	t	Verify if command motion is too acute	Modify control command; use filter

Error Main Sub		Sub	Display: "Er 0E1"			
code	0E	1	Content: Intelligent Power Module	e (IPM) overcurrent		
Cause			Diagnosis	Solution		
Driver power output short circuit			Verify if there is short circuit between UVW terminals, or shorted to PG.	Make sure there is no circuit. Make sure motor is not damaged		
Motor w	iring erro	r	Verify motor wiring	Reconnect motor wiring		
IGBT module short circuit			Disconnect motor output cable. Then, enable servo driver to check for overcurrent	Replace driver		
IGBT module undervoltage			1	Replace driver		
Control parameter		er	Verify if parameter exceeds	Set parameter within		
anomaly			recommended range	recommended range.		
Control anomaly	command /	t	Verify if command motion is too acute	Modify control command; use filter		

Error	Main	Sub	Display: "Er 0F0"	
code 0F 0 Content: Driver overheated				
Cause			Diagnosis	Solution
Temperature of power module exceeded upper limit			Measure the temperature of driver radiator.	Improve cooling condition. Please check installation guide; Replace driver and motor with higher power rating; Increase duration time for acceleration and deceleration; Decrease load



Error	Main	Sub	Display: "Er 100"	
code	10	0	Content: Motor overloaded	
Cause		Diagno	osis	Solution
Load too heavy		Verify if actual load exceeds maximum value allowed		Decrease load Adjust limit values
Strong mechanical vibration		Look for mechanical vibration from machine system		Adjust gain value of control loop Increase duration time for acceleration and deceleration
Motor or encoder cable wiring error		Verify motor and encoder wiring		Reconnect wiring Replace motor and encoder cable
Holding brake engaged		Verify I	nolding brake terminal voltage	Cut off holding brake

Error	Main	Sub	Display: "Er 101"	
code 10		1	Content: Driver overloaded	
Cause		Diagnosis		Solution
Motor power cable wiring error		UVW terminals wiring error		Make sure motor power cable wiring connection is correct
Motor not		Motor	current is too high	Motor rated current is higher than driver rated current. Please change to a driver with higher rated current.

Error	Main	Sub	Display: "Er 102"		
code	10	2	Content: Motor rotor blocked		
Cause		Diagno	osis	Solution	
Motor rote	Motor rotor blocked		or mechanical blockages	Check the machinery	
Motor rotor blocking					
time threshold value		Verify value of Pr6.57		Adjust value of Pr6.57	
too low					

Error	Main	Sub	Display: "Er 120"	
code	12	0	Content: Regenerative resi	stor overvoltage
Cause			Diagnosis	Solution
Regenerative energy exceeded capacity of regenerative resistor Power supply voltage too high		y of tor	Verify if velocity is too high Verify if load is too large Verify if power supply voltage is within the rated range. Interval regenerative resistor value is too low	Decrease motor rotational velocity; Decrease load inertia; Add an external regenerative resistor; Decrease power supply voltage Increase regeneration resistance value(add external regenerative resistor)
Unstable power supply voltage		upply	Verify if power supply voltage is stable	Add a surge suppressor to main power supply.
Regenerative energy discharge circuit damaged		rgy	1	Add an external regenerative resistor; Replace driver



Error	Main	Sub	Display: "Er 121"	
code 12 1		1	Content: Holding brake error	
Cause			Diagnosis	Solution
Holding	brake	circuit	Regenerative resistor disconnected	Replace regenerative resistor
damaged			Holding brake IGBT damaged	Replace driver

Error	Main	Sub	Display: "Er 122"		
code 12 2		2	Content: Regenerative resistor value too low		
Cause	Cause		Diagnosis	Solution	
resistor va	External regenerative resistor value is less than the minimum value allowed by the drive		1	Replace the regenerative resistor with the right resistance value which meets the specification of the driver	

Error	Main	Sub	Display: "Er 150"			
code	15	0	Content: Encoder disconnected			
Cause			Diagnosis	Solution		
Encoder of disconnection			Verify encoder cable connection	Make sure encoder cable properly connected		
Encoder of	able wir	ing error	Verify if encoder wiring is correct	Reconnect encoder wiring		
Encoder d	lamaged	d	1	Replace motor		
Encoder n	neasurir	ng circuit	/ Replace driver			

Error	Main Sub		Display: "Er 151"	
code	15	1	Content: Encoder communication error	
Cause			Diagnosis	Solution
Encoder v		lding	Verify if encoder cable has shielding layer	Replace with standard encoder cable
Encoder cable wiring error			Verify if encoder wiring is correct	Reconnect encoder wiring
Encoder d	lamaged	d	1	Replace motor

Error	Main	Sub	Display: " <mark>Er 152</mark> "	
code	15	2	Content: Encoder initial position error	
Cause	Cause [Diagnosis	Solution
	Communication data abnormal		. Verify if encoder power supply oltage is DC5V±5%; . Verify if encoder cable and shielded ayer is not damaged; . Verify if encoder cable is close to igh-powered power supply cable	Make sure encoder power supply voltage is stable Make sure encoder cable is not damaged. Make sure encoder cable shielded layer is grounded to frame Make sure encoder cable is away



		from high-powered power supply cable
Encoder damaged	1	Replace motor
Encoder measuring circuit damaged	1	Replace driver

Error	Main	Sub	Display: "Er 153"		
code	15	3	Content: Multiturn encoder error		
Cause			Diagnosis	Solution	
Initial use			Origin calibration not performed	Perform origin positioning and multiturn position initialization, calibrate the origin of coordinate system.	
multituri	Encoder without multiturn absolute function used		Verify if encoder has multiturn absolute function	Replace the motor with a multiturn absolute encoder. Set Pr0.15 = 0 to deactivate multiturn absolute function.	
Low bat	Low battery power		Replace battery and restart driver to clear alarm	Replace battery	
	has no po n disman		Alarm not cleared after replacing battery and restart	Absolute position lost. Return to origin and perform multiturn initialization, calibrate the origin of coordinate system	

Error	Main	Sub	Display: "Er 154"		
code	15	4	Content: Encoder parameter settings error		
Cause			Diagnosis	Solution	
Absolute encoder mode			Verify if encoder has multi-turn	Modify absolute encoder mode	
is incorrectly set.			absolute value function.	settings	

Error	Main	Sub	Display: "Er 155"		
code 15 5		5	Content: Encoder data overflow		
Cause	Cause		Diagnosis	Solution	
Encode	Encoder data overflow		Verify if encoder is not damaged	Initialize multiturn data	
Absolute value applications, motor rotates in one direction			Verify if encoder is not damaged	Adjust absolute value application mode, set to turntable mode	

Error	Main	Sub	Display: "Er 156"	
code	15	6	Content: Encoder overheated	
Cause			Diagnosis	Solution
The encoder temperature is too high.		o high.	Verify if motor temperature is too high	Reduce encoder temperature.



Error	Main	Sub	Display: "Er 157"			
code	15	7	Content: Encoder counter error			
Cause	Cause		Diagnosis	Solution		
Encode	r data ove	erflow	Verify if encoder is not damaged	Initialize multiturn data		
Absolute value applications, motor rotates in one direction			Verify if encoder is not damaged	Adjust absolute value application mode, set to turntable mode		

LITOI		Sı	ub	Display: "Er 170"		
code	17		0	Content: Encoder data error		
Cause			Diag	nosis	Solution	
Communication data abnormal			voltag 2. Ve layer 3. Ve	rify if encoder power supply ge is DC5V±5%; rify if encoder cable and shielded is not damaged; rify if encoder cable is close to powered power supply cable	Make sure encoder power supply voltage is stable Make sure encoder cable is not damaged. Make sure encoder cable shielded layer is grounded to frame Make sure encoder cable is away from high-powered power supply cable	
Encoder damaged			1	Replace motor		
Encoder circuit da	measurin amaged	ıg		1	Replace driver	

Error	Main	Sı	np	Display: "Er 171"	
code	17	1		Content: Encoder parameter initialization error	
Cause	Cause D		Diag	nosis Solution	
	Driver and motor not matched		Verify driver and motor models.		Replace with matching driver and motor
Error while getting parameters from encoder		J	2. Ve insula	rify if encoder cable is standard. rify if encoder has no peeled ator, broken connection or oper contact.	Use standard encoder cable, verify the connection of both sides of driver and motor, change encoder cable if necessary

Error	Main	Sub Display: "Er 180"		
code 18 0 Content: Excessive position deviation				
Cause			Diagnosis	Solution
Improper position deviation settings			Verify if value of Pr_014 is too low	Increase value of Pr_014
Position gain setting too		ng too	Verify if values of Pr1.00 & Pr1.05	Increase values of Pr1.00 &
low			are too low	Pr1.05
Torque limit too low			Verify if values of Pr0.13 & Pr5.22 are too low	Increase values of Pr0.13 & Pr5.22



Excessive external load	Verify if acceleration and deceleration duration time is too low. Verify if rotational velocity is too high Verify if load is too large	Increase duration time for acceleration and deceleration Decrease rotational velocity Decrease load

Error	Main Sub Display: "Er 1			isplay: " <mark>Er 181</mark> "		
code	18	1	Content: Excessive velocity deviation			
Cause				Diagnosis	Solution	
	Deviation between set velocity and actual velocity is too great			Verify if value of Pr6.02 is too low	 Increase value of Pr6.02; Set Pr6.02 to 0, position error detection off. 	
Acceleration and deceleration duration time for set velocity is too low			or	Verify if value of Pr3.12 and Pr3.13 are too low	Increase value of Pr3.12, Pr3.13; Adjust velocity gain to reduce velocity lag error	

Error	Main	Sub	Display: "Er 190"		
code	19	0	Content: Vibration too strong		
Cause	Cause		Diagnosis	Solution	
Resonance			Mechanical stiffness is too high, resonance occurs	Reduce mechanical stiffness or use filter	
Current loop gain too large		ı too	Verify current loop gain value	Reduce current loop gain	

Error	Main	Sub	Display: " <mark>Er 191</mark> "		
code	19	1	Content: Excessive hybrid posit	tion deviation	
Cause			Diagnosis	Solution	
Driver UVW terminal output single phasing or wiring error			r Verify if UVW terminal wiring connection is right	Make sure UVW terminals are correctly connected to UVW of motor; change motor power cable.	
Motor rote	or block	ed	Look for mechanical blockages	Check the machinery	
Driver stiff	fness too	olow	Verify if position loop and velocity loop gain is too low	Increase position loop and velocity loop gain	
Full closed loop position deviation (Deviation between external encoder feedback position and motor feedback position) exceeds Pr0.33			Verify if Pr0.33 is set too low	Increase Pr0.33 set value accordingly but please aware that doing so might cause the position deviation to be higher.	



Error	Main	Sub	Display: "Er 1A0"		
code 1A		0	Content: Overspeed		
Cause		Diagno	osis	Solution	
Motor velocity exceeded first speed limit (Pr3.21) 1. Ve 2. Ve is too 3. Ve low; 4. Ve frequ		2. Veriis too i 3. Veriilow; 4. Veriifreque	fy if velocity command is too high; fy if simulated velocity command voltage nigh; fy if parameter value of Pr3.21 is too fy if input frequency and division ncy coefficient of pulse train is proper; fy if encoder is wired correctly	1. Adjust velocity input command; 2. Increase Pr3.21 value; 3. Adjust pulse train input frequency and division frequency coefficient; 4. Verify encoder wiring;	

Error	Main	Sub	Display: "Er 1A1" Content: Velocity out of control		
code	1A	1			
Cause	Cause Diagnosis		Solution		
out of con Excessive	Motor velocity out of control, Excessive velocity error Verify encoder phase sequence; Verify if UVW cable is connected to the right terminal			Reconnect UVW if wrongly connected. If still remains unsolved, please contact technical support.	

Error	Main	Sub	Display: "Er 1b0"		
code	1b	0	Content: Bus input signal dithering		
Cause			Diagnosis	Solution	
Controller synchronization dithering			/	Increase alarm threshold value	

Error	Main	Sub	Display: " <mark>Er 210</mark> "		
code	21	0	Content: I/O input interface assignment error		
Cause			Diagnosis	Solution	
Input signal assigned with two or more functions.			Verify values of Pr4.00-Pr4.09, Pr4.44-4.47	Set proper values for Pr4.00- Pr4.09, Pr4.44-4.47	

Error	Main	Sub	Display: "Er 211"		
code	21	1	Content: I/O input interface function assignment error		
Cause	Cause		Diagnosis	Solution	
Input signal assignment		ignment	Verify values of Pr4.00-Pr4.09,	Set proper values for Pr4.00-	
error			Pr4.44-4.47	Pr4.09, Pr4.44-4.47	



Error	Main	Sub	Display: "Er 212"		
code	21	2	Content: I/O output interface function assignment error		
Cause	Cause		Diagnosis	Solution	
Input sign two or mo			Verify values of Pr4.10-Pr4.15	Set proper values for Pr4.10- Pr4.15	
Input signal not assigned			Verify values of Pr4.10-Pr4.15	Set proper values for Pr4.10- Pr4.15	

Error	Main	Sub	Display: "Er 240"			
code	24	0	Content: CRC correction error during EEPROM parameter saving			
Cause			Diagnosis	Solution		
1 -	r, t terminal voltage too		Verify if r, t terminal voltage too	Make sure r, t terminal voltage is		
low			low	within recommended range		
Parameter saving			Save parameter again and	Save parameter again		
anomaly			restart			

Error	Main	Sub	Display: "Er 260"	
code	26	0	Content: Positive/Negative position limit triggered under non-homing mode	
Cause			Diagnosis	Solution
Positive/negative position limit triggered			Verify position limit signal	1

Error	Main	Sub	Display: "Er 270" "Er 272"			
code	27	0~2	Error description: Analog input 1-3 out of range			
Cause			Diagnosis	Solution		
Analog value out of range			Verify if analog input value is out of range	Adjust analog input voltage		

Error Main Sub		Sub	Display: "Er 570"			
code	57	0	Error description: Forced alarm input valid			
Cause			Diagnosis	Solution		
Forced alarm input signal occurred			Verify forced alarm input signal	Verify if the input wiring connection is correct		

Error code Main Sub Display: "Er 5F0"				
		0	Content: Motor model no. detection error	
Cause	Cause		Diagnosis	Solution
Automatically detected motor doesn't match set motor			/	Please contact our technical support



Error					
code	5F	1	Error description: Driver power module detection error		
Cause			Diagnosis	Solution	
Driver power rating not within range.			Restart driver	Please contact our technical support	

Error	Main	Sub	Display: "Er 600"		
code	60	0	Error description: Main loop interrupted timeout		
Cause			Diagnosis	Solution	
The motor control loop calculation time			Check for interference from devices releasing electromagnetic field	Ground driver and motor to reduce interference	
Overnow	overflow		Restart driver	Replace driver	

Error	Main	Sub	Display: "Er 601"			
code	60	1	Error description: Velocity loop interrupted timeout			
Cause			Diagnosis	Solution		
Motor control loop calculation time overflow			Verify if encoder connection is and that the encoder cable is too not long (more than 20 meters)	Replace encoder cable if necessary		
			Restart driver	Replace the drive with a new one		

Error	Main	Sub	Display: "Er 700"	
code	70	0	Error description: Encryption err	or
Cause			Diagnosis	Solution
Encryption error during initialization upon power-on.			Restart driver	Please contact our technical support

Error Main Sub Display: "Er 880"						
code	88	0	Error description: Modbus communication timeout			
Cause			Diagnosis	Solution		
Communication timeout			Please check if the communication cable is properly connected	Make sure the communication connection is secured		



Error	Main	Sub	Display: "Er 890"			
code	89	0	Error description: Homing error			
Cause			Diagnosis	Solution		
Excess homing velocity Homing mode is different from given signal Sensor signal edge inconsistent			Verify if homing velocity is too high Verify if homing mode is set correctly Verify if sensor signal edge is consistent	Set an optimal homing velocity Make sure sensor signal edge is consistent.		
Inconsistent origin status			Homing acceleration/ deceleration is set too low Electronic gear ratio is low which causes acceleration/ deceleration to be too low	If electronic gear ratio cannot be changed, please set a suitable 609A. Increase electronic gear ratio		

8.4 Alarm clearing

8.4.1 Servo Drive Alarm Clearing

Clearable Alarm Please clear alarm using Motion Studio after solving the error by clicking on the "Clear" button. Alarm Current History Cause(s) of motor not rotating Device Alarm Code Alarm label Clearable Error Level Axis1 Err0B2 No 2

Non-clearable Alarm

Please restart drive to clear alarm



Contact Us

Leadshine Technology Co., Ltd.

Headquarters

Address:

15-20/F, Block B, Nanshan I Valley, No.3157, Nanshan District, Shenzhen City, Guangdong Province, China

Tel:

+86 755 26411692

Fax:

+86 755 26402718

Website:

www.leadshine.com

Emails:

sales@leadshine.com

Leadshine Global Retailers Network



Get in touch with us or any of your local Leadshine certified retailers by visiting our global website.

Technical Support

Tel: 86-755-2641-8447

86-755-2641-8774 (Asia, Australia, Africa) 86-755-2665-5136 (North and South America)

86-755-8654-2465 (Europe)

Fax: 86-755-2640-2718
Email: tech@leadshine.com

Sales Hot Line

Tel: 86-755-2641-7674 (Asia, Australia, Africa) 86-755-2641-7617 (North and South America) 86-755-2640-9254 (Europe)

Email: sales@leadshine.com

Leadshine Overseas



Leadshine America, Inc.

North America Office

Address: 26050 Towne Centre Dr. Foothill Ranch California United States Tel: 1-949-608-7270 Fax: 1-949-638-7298

www.leadshineus a.com

Website:

Emails:

sales@leadshin eusa.com